

Schindler Elevator Manual (Model-9300)

Equipment manual - Schindler Model-9300 - Generated from Operio source markdown

Section 1 - Drive Motor Overtemperature

Troubleshooting Code F-01

If the elevator system encounters Fault Code F-01, it indicates that the primary drive motor has exceeded safety temperature limits.

1. **Check Ventilation Fans:** Verify that the machine room ventilation fan is running and that ambient room temperature is below 35°C.
2. **Reset Overload Relay:** Locate the main cabinet control panel and inspect the thermal overload relay. Reset the switch manually once the motor has cooled.
3. **Inspect Brake Gap:** Ensure the mechanical brake calipers are not dragging against the flywheel.