

National Transportation Safety Board Aviation Accident Final Report

Location: Venice, FL Accident Number: NYC08CA047

Date & Time: 11/26/2007, 1140 EST **Registration:** N461TC

Aircraft: Cessna 152 Aircraft Damage: Substantial

Defining Event: Injuries: 1 None

Flight Conducted Under: Part 91: General Aviation - Instructional

Analysis

During his first solo flight, the student pilot flew the Cessna 152 "fast" on final approach and flared higher than normal. The airplane bounced on the runway, and the student pilot initiated a go-around. He then lost control of the airplane, and it impacted grass off to the side of the runway. The student pilot reported no mechanical anomalies and stated that he used 10-degrees of flaps instead of 30-degrees during the approach. At the time of the accident, the student pilot had accumulated 23 hours of total flight experience, all in the make and model, and within the previous 90 days.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot's improper recovery from a bounced landing.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: GO-AROUND (VFR)

Findings

1. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Findings

2. TERRAIN CONDITION - GRASS

Factual Information

Student Pilot Information

Certificate:	Student	Age:	17, Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 With Waivers/Limitations	Last FAA Medical Exam:	08/01/2007
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	23 hours (Total, all aircraft), 23 hours (Total, this make and model), 1 hours (Pilot In Command, all aircraft), 23 hours (Last 90 days, all aircraft), 19 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N461TC
Model/Series:	152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	15283103
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	0-235
Registered Owner:	Florida Flight Training Center	Rated Power:	
Operator:	Florida Flight Training Center	Operating Certificate(s) Held:	None

Page 2 of 4 NYC08CA047

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	SRQ	Distance from Accident Site:	21 Nautical Miles
Observation Time:	EST	Direction from Accident Site:	360°
Lowest Cloud Condition:	Clear	Visibility	10 Miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	13 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	24°C / 20°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Venice, FL	Type of Flight Plan Filed:	None
Destination:	Venice, FL (VNC)	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Airport Information

Airport;	Venice Municipal Airport (VNC)	Runway Surface Type:	Asphalt
•	18 ft	, ,,	_ •
Airport Elevation:	10 11	Runway Surface Condition:	Dry
Runway Used:	13	IFR Approach:	None
Runway Length/Width:	4999 ft / 150 ft	VFR Approach/Landing:	Full Stop; Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	27.071389, -82.440278

Administrative Information

Investigator In Charge (IIC):	Jill M Andrews	Report Date:	01/31/2008
Additional Participating Persons:	Hector Diaz; FAA/FSDO; Tampa, FL		
Publish Date:			
Note:	This accident report documents the fact to the NTSB.	tual circumstances of	this accident as described
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at publing@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/ .		

Page 3 of 4 NYC08CA047

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 4 of 4 NYC08CA047