Radon Inspection Report

Measurement Information

Client Name
Steele Seei

Client Phone number
480-737-2816

Client Email Address
saseei11@gmail.com

Measurement Started
11/05/2026 15:03

Measurement Ended
11/07/2026 15:05

Inspection Duration
48 hour (Data No : 48)

Building Year
2008

Building Type
Single-family home

Room Type
Basement family room

Floor
Basement

Test Purpose
Real Estate



Measurement Location
7877 Blue Jay Way
Zionsville, Indiana
46077
County: Boone

Test Result:

EPA recommends mitigation
if the radon average is 4pci/L or more

Overall Average **6.7 pCi/L**

EPA Average*

* The EPA protocol average discards the first four hours of the deployment period. The official number to go with is the EPA protocol average.

Device Infomation

Device S/N
RP22503170017

Calibration Expiration Date
03/09/2027

MDC (Minimum Detectable Concentration)
0.2 pCi/L

Test Company information

Company
5M Inspection Services

Certification # (State-License #)
RTP01333

Company Email
info@5minspections.com

Company Phone
317-900-2651

Company Address
PO Box 43
Westfield, Indiana 46074

Test Limitations: There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations. Variations may be due to changes in the weather, operation of the dwelling, or possible interference with the necessary test conditions.

Tester Information

Measurement Professional (Certified or State-Licensed)
Pamela Markham

Certification # (State-License #)
RTP01333

Email Address
info@5MInspections.com

Phone Number
3177602311

Device Information for Measurement

Manufacturer & Model
FTLab & RadonEye Pro

Structure Type
In Basement

Test device placed simultaneously at this property

No, Test Type: Standard

Inspection Information

Delay/Discard
the first 4 hours

Inspection Duration
48 hours

Measurement Started
THU , 11/05/2026 03:03 PM

Measurement Ended
SAT , 11/07/2026 03:05 PM

Measurement Radon Concentration Max
10.7 pCi/L

Measurement Radon Concentration Min
3.5 pCi/L

Historical Radon Trend



Table of Hourly Radon Measurements

Radon Concentration Average: 6.7 pCi/ℓ

Timestamp	Radon Value	Temp(F)	RH(%)	Timestamp	Radon Value	Temp(F)	RH(%)
11/05/26 16:05	2.0	68	54	11/06/26 16:05	7.7	68	49
11/05/26 17:05	2.3	68	52	11/06/26 17:05	5.7	68	48
11/05/26 18:05	4.2	68	51	11/06/26 18:05	5.5	68	48
11/05/26 19:05	4.4	68	51	11/06/26 19:05	6.4	68	49
11/05/26 20:05	3.5	68	49	11/06/26 20:05	6.6	68	48
11/05/26 21:05	4.3	68	51	11/06/26 21:05	5.9	69	47
11/05/26 22:05	4.4	68	53	11/06/26 22:05	5.8	68	47
11/05/26 23:05	5.2	67	49	11/06/26 23:05	6.0	68	47
11/06/26 00:05	3.7	68	52	11/07/26 00:05	5.8	68	47
11/06/26 01:05	4.2	68	52	11/07/26 01:05	6.4	68	47
11/06/26 02:05	6.4	68	51	11/07/26 02:05	5.1	68	46
11/06/26 03:05	5.7	68	51	11/07/26 03:05	7.9	68	46
11/06/26 04:05	7.8	68	51	11/07/26 04:05	6.6	68	46
11/06/26 05:05	10.1	68	51	11/07/26 05:05	6.5	68	46
11/06/26 06:05	9.5	68	51	11/07/26 06:05	5.8	68	45
11/06/26 07:05	10.7	68	51	11/07/26 07:05	8.5	68	46
11/06/26 08:05	8.6	68	51	11/07/26 08:05	7.9	68	45
11/06/26 09:05	9.3	68	50	11/07/26 09:05	6.9	67	45
11/06/26 10:05	7.9	68	50	11/07/26 10:05	7.3	67	45
11/06/26 11:05	8.8	68	50	11/07/26 11:05	9.8	67	46
11/06/26 12:05	8.2	68	50	11/07/26 12:05	9.9	67	46
11/06/26 13:05	7.3	68	49	11/07/26 13:05	9.9	67	47
11/06/26 14:05	7.1	68	49	11/07/26 14:05	9.7	68	46
11/06/26 15:05	7.9	68	49	11/07/26 15:05	6.4	67	45

* Temperature and humidity can vary depending on environmental conditions.

* The test data was taken from a testing device approved by the National Radon Proficiency Program.

Conditions Observed During the Test

1. The property was vacant during the test period	No
2. Passive crawlspace vents to the outside	No
3. Window ac	No
4. ERV/HRV	No
5. Evaporating cooling system	No
6. Sub-slab ducts	No
6-1. HVAC fan setting	Auto
7. Closed-building conditions at time of placement	Yes
7-1. Closed-building conditions at time of retrieval	Yes
8. Devices placed in location as standards require	Yes
9. Indoor temperature at time of placement	68 F
9-1. Indoor temperature at time of retrieval	68 F
10. Signs of interference with test	No
11. Any anomalies in data that may indicate deviation from testing protocol	No
12. Noninterference controls used	Yes
12-1. Explain methods used Unless the client ordered a complete ANSI/AARST Soil Gas Mitigation Compliance Inspection, the radon tester offers no findings as to the proper installation and operation of the mitigation system installed	
13. Noninterference agreement given to responsible individual	No
13-1. Noninterference agreement signed by responsible individual	No
14. Mitigation system present	No
16. Unusually severe storms or high winds.	No
17. Any temporary mitigation strategies present	No

Measurement Environments

No visible mitigation systems were found, however, roughed-in piping, intended for a mitigation system was observed. We recommend consulting a certified mitigation specialist to mitigate, as radon levels exceed the EPA's safe limits.

There was a noticeable change in the home's radon levels. A variety of environmental factors can affect how much radon enters a house, including temperature, humidity, barometric pressure, wind, and rainfall. During the testing period, the area experienced strong winds and heavy rain, which likely contributed to the significant fluctuation in the readings.





Comments

RECOMMENDATIONS (as per ANSI-AARST Radon Measurement in Homes Standard)

Average test result is 4.0 pCi/L or greater: YOUR RADON IS HIGH

- FIX THE BUILDING. Test results indicate occupants may be exposed to radon concentrations that meet or exceed the EPA action level of 4 pCi/L or greater.
- Efforts to reduce radon concentrations are not complete until a retest provides evidence of mitigation effectiveness.
- Complete a short-term test between 24 hours and 30 days after installation of a mitigation system.
- Retest every 2 years to ensure the system remains effective.

Average result is between 2.0 and 4.0 pCi/L: YOUR RADON IS MODERATELY ELEVATED

- CONSIDER FIXING THE BUILDING. Test results indicate radon levels greater than half the EPA action level.
- The World Health Organization (WHO) recommends mitigation if levels are 2.7 pCi/L (100 Bq/m^3) or higher.
- Note that tests conducted when the heating system is active both day and night are more likely to provide a clear characterization of potential radon hazards.

Average test result is less than 2.0 pCi/L: YOUR RADON IS LOW

- NO FURTHER ACTION REQUIRED AT THIS TIME. The average indoor radon level is estimated to be about 1.3 pCi/L; the normal outdoor air radon level is 0.4 pCi/L.
- Radon levels in a building can fluctuate due to weather conditions and other factors, including renovations and alterations, or changes in the HVAC system. For this reason, EPA recommends **retesting your home every 5 years** and remediating if levels become elevated.

Times to Retest:

Retest in conjunction with any sale of new or existing buildings. In addition, be certain to test again or continuously monitor when any of the following circumstances occur:

- A new addition is constructed or alterations for building reconfiguration or rehabilitation occur.
- A ground contact area not previously tested is occupied, or a home is newly occupied.
- Heating or cooling systems are significantly altered, resulting in changes to air pressure relationships.
- Ventilation is significantly altered by extensive weatherization, changes to mechanical systems or comparable procedures.
- A mitigation system is altered, modified, or repaired.
- Significant openings to soil occur due to:
    - Groundwater or slab surface water control systems that are altered or added (e.g., sumps, perimeter drain tile, shower/tub retrofits, etc.).
    - Natural settlement causing major cracks to develop.
- Earthquakes, construction blasting, fracking, or formation of sink holes nearby, or
- A mitigation system is altered, modified, or repaired.

Comments

This testing was commissioned in relation to a real estate transaction, with your client assuming the role of the property buyer. Given the absence of communication with the seller, we are unable to provide them with a Non-Interference Agreement for their review and endorsement. Despite this limitation, non-interference protocols were diligently enforced throughout the testing period. A conspicuous notice was prominently displayed at the testing site, alerting any occupants to the critical nature of upholding closed-house conditions and stressing that any disruption or tampering with the testing apparatus could compromise the accuracy of the results. The device utilized for radon measurement is also equipped to identify and record any instances of interference. No unauthorized interference was detected.

State Radon Information

Indiana

- Phone: (317) 233-7563
- Website: http://www.in.gov/isdh/23279.htm
- Email: dnauth@idhs.in.gov

Report reviewed and certified by:

Company : 5M Inspection Services

Name : Pamela Markham

Certificate/License# : RTP01333