


overall HTC of the tube in the test chamber could be due to the infeasibility of installing wall temperature sensors

$$Pr_w = \frac{c_{p,w}\mu_w}{k_w}$$



(a) Grit 100



(b) Grit 1200

Fig. 5. Scanning electron microscope (SEM) images of roughened tubes.