Docusign Envelope ID: 07D426A8-D8D2-43AA-A1A2-8909B8E4A602

Whip's Chimney SERVICE, INC.

849 E. Stanley Blvd. #127
Livermore, Ca 94550
Ph: (925) 443-4991
(510) 278-4991
matt@whipschimney.com

Lic.# 549199

Level 1 Inspection -Natural Gas Fireplace Insert

Type of Fireplace: ☑ Pre-Fab ☐ Masonry ☐ Modular

No. of Stories: [1] 2 3 4 **No. of Fireplaces:** [1] 2 3 4

Woodstove: ☐ Insert ☐ Freestanding ☐ Pellet

Flue Size: ☐ 8" x 13" ☐ 13" x 13" ☐ 8" x 17" ☐ 8" x 19" ☐ 13" x 17" ☐ 6" Round" ☐ 8 " Round ☑ 3" Round

Outside Chimney Dimensions _____ " x _____ "

Fireplace Opening Size _____ " x _____ "

Date 3/19/2026
Customer Wendy Emett
Address 1731 Mountain Blvd
City Oakland, CA Zip 94611
Phone (925) 382-0653
Fax ( ) wendy@frazzanotse.com
Title Co. _____ Fax _____
Escrow # _____

CONDITION REPORT



		SATISFACTORY	UNSATISFACTORY	NOT APPLICABLE
CHIMNEY				
1.	Height	✓		
2.	Chimney Cap/Spark Arrestor /Termination	✓		
[3.]	Crown/Wash		✓	
4.	Brickwork/Mortar	✓		
5.	Flashing			
6.	Flue Liner	✓		
FIREPLACE				
7.	Smoke Chamber			
8.	Damper			
9.	Firebox/Grate			
10.	Ash Container			
11.	Spark Screen/Doors			
12.	Hearth Protection	✓		
13.	Damper stop			
14.	Miscellaneous			
WOODSTOVE OR FIREPLACE INSERT				
15.	Stovepipe Condition (woodstove)			
16.	Installation/Thimble/Clearances			
[17.]	Miscellaneous -Service/Clean/Level Appliance		✓	
18.	Pre-Fabricated Fireplace	✓		
19.	Chase Pan/Storm Collar			
20.	Refractory Panels	✓		
21.	Glass Enclosure/Screen	✓		
22.	Miscellaneous			

Approved: _____

COMMENTS: Do not leave key in gas valve.
Mortar Cap needs to be sealed-Prevent water infiltration.
Gas fireplace insert is not currently installed correctly-Not leveled with hearth -
-extension-Readjust & level unit as needed.
Appliance is due to be serviced/cleaned.
Unable to verify minimal distances to combustible materials, per Mfg. at time
-of inspection-Monitor mantel-Recommend to verify with owner's manual.
Gas burner & blower fan ignited/functioned properly at time of inspection.
Visual portion of firebox & flue are in sound condition.

Refer licensed roof co., to evaluate roof flashing.

No excessive movement was noted in chimney at time of inspection.

Service/Clean/Monitor appliance on a regular basis for any changes.

NEXT SERVICE RECOMMENDED: Repairs needed

ESTIMATE FOR REPAIRS:
#3-$390 & #17-$295

THE NATIONAL FIRE PROTECTION ASSOCIATION CODE STATES THE FIREPLACE AND CHIMNEY SHOULD BE INSPECTED YEARLY FOR ANY STRUCTURAL FAULTS.

SIGNATURE: Matt Frost
Matt Frost

RECEIPT/INVOICE

DESCRIPTION		PRICE
Inspection Fee		$250.00
☐ Billing Fee		
DATE COMPLETED: 3/19/2026	**TOTAL**	$250.00

Payment Due Within 10 Days Or Billing Fee To Apply

Note: This sheet is the result of a visual inspection done at the time of service. It is intended as a convenience to our customer, not as a certification of fire worthiness or safety. Since conditions of use and hidden construction defects are beyond our control, we make no warrantee of the safety or function of any appliance and none is to be implied.

Signed by: 7EEB7B3B666841D... 3/24/2026

Signed by: Suzanne M Peacock 7F8CFDBC33E949F... 3/25/2026