

BMW of South Austin

Vehicle Condition Report

Prepared on September 28, 2022 for:

JADEN RILEY

Vehicle: 2012 BMW 3 SERIES
VIN: WBA3A5C57CF256942

License:

Odometer: **94,390** RO: **79625**

CHARLES REEVES

Service Advisor

5501 S IH 35 Frontage Rd Austin, TX 78744 (512) 438-7908 charles.reeves2@hendrickauto.com

Service: 833-375-4011

We appreciate you choosing us for your service needs!

BMW of South Austin Vehicle Inspection

Customer Name: JADEN RILEY Vehicle Year/Model: 12 BMW 3 SERIES Printed: 09/28/2022 13:19:03 Phone: (H) (512) 713-6630 VIN: WBA3A5C57CF256942 Odometer: 94390 Service Advisor: CHARLES REEVES Technician: RO: 79625 Tag: 2936 **INSPECTION RESULT - OK** WILL REQUIRE FURTHER ATTENTION REQUIRES IMMEDIATE ATTENTION Green Yellow Red Fill windshield washer fluid Front / Rear Brake Linings LF RF Check tire pressure and adjust as needed Green Green Inspect wiper/washer operation Yellow Yellow Inspect exterior lamps/lights/bulbs (operation/damage) Red Red Inspect dash/interior lighting and horn operation Inspect windshield for chips/cracks/damage Inspect window/lock operation LR RR Green Green Inspect Interior/Exterior Condition Yellow Yellow Inspect engine air filter Red Red Inspect cabin air filter (if equipped) Inspect drive belts Inspection Not Taken Inspect engine hoses 6mm and higher Inspect starting/charging system 3.6mm to 5.9mm Check brake fluid level and condition 3.5mm and lower Check engine coolant level and condition Check Tires / Tread Depth Check power steering fluid level and condition RF Check transmission fluid level and condition (most models) Green Green Inspect Engine (leaks/wear/damage) Yellow Yellow Inspect front/rear differential and transfer case (leaks) Red Red Inspect exhaust system (leaks/damage/loose parts) Inspect brake system components (leaks/wear/damage) LR RR Inspect steering system (leaks/wear/damage) Green Green Inspect cooling system (leaks/wear/damage) Yellow Yellow Inspect heating and air conditioning operation Red Red Inspect front suspension Inspect rear suspension 7/32" or Greater Inspect axles/driveshaft(s)/U-joints/CV joints/boots 4/32" to 6/32" 3/32" or Less Inspect transmission for leaks/damage Inspect fuel tank/lines/connections Check Battery Performance Check engine light on Good Airbag light on ABS/traction control light on Recommended Maintenance **Actual Cold Cranking Amps**

Factory Cold Cranking Amps

Repair Order Estimate

Printed Date: September 28, 2022

We have performed our multi-point inspection on your vehicle and the following services were recommended.

EXISTING SERVICES

Job	Quote
COMPLIMENTARY INSP COMPLIMENTARY MULTI-POINT INSPECTION. RESULTS CAN BE EMAILED	0.00
BODY ELECTRICAL CUSTOMER REQUEST PRICE QUOTE FOR THE IDRIVE SCREEN- CRACKE	PENDING
ELECT DIAGMJR CUSTOMER STATES THE DRIVERS SIDE HEADLAMP AND FOG LIGHTS WE	262.43
INTERIOR TRIM CUSTOMER REQUEST A PRICE QUOTE FOR THE DRIVERS SEAT LEATHER	PENDING
ELECT DIAG CUSTOMER STATES THE BUTTON ON THE REAR TRUNK TO OPEN IT IS N	174.95
Existing Services Total	\$ 437.38

SUGGESTED SERVICES

Job					Qu	ote
MISC BODY ELECTRICAL replace and program cid			4,178.83			
Qty	Part Number	Part Description			Price	Ext Price
1.00	65-50-9-292-248	CENTRAL INFO BM			3374.12	3374.12
Misc Code	Misc Code Misc Description				Ext Price	
SS SERVICE CHARGE				36.00		
	Labor Hrs			487.38		
Parts			3374.12			
Misc		36.00				
Tax			281.33			
			Total			4178.83



BMW of South Austin

Job INT TRIM (CONCERN				Qu	ote
	rs seat back and bottom leather				3	,028.46
Qty	Part Number	Part Description			Price	Ext Price
1.00	52-10-7-942-318	LEATHER COVE			905.68	905.68
1.00	52-10-7-303-715	COVER, BASIC			996.10	996.10
75.00	52-10-1-945-543	CLAMP BMBIMI			1.86	139.50
Misc Code	Misc Description					Ext Price
SS	SERVICE CHARGE					36.00
			Labor	Hrs		779.80
			Parts		2	2041.28
			Misc		36.00	
			Tax			171.38
			Total		3	3028.46
Job				ļ	Qu	ote
replace rear	CONCERN trunk button					277.57
Qty	Part Number	Part Description			Price	Ext Price
1.00	51-24-7-463-161	BOOT LID/TAI BM		58.77 58.77		
Misc Code	Misc Description					Ext Price
SS	SERVICE CHARGE					17.55
			Labor	Hrs		194.95
			Parts			58.77
			Misc		17.55 6.30	
			Tax			
			Total			277.57
	CTRICAL p assemblies are aftermarket led's fog lamp assemblies				Qu	836.73
Qty	Part Number	Part Description		Price	Ext Price	
1.00	63-17-7-248-911	FOG LIGHTS, BM		238.25	238.25	
1.00	63-17-7-248-912	FOG LIGHTS, BM		238.25	238.25	
Misc Code	Misc Description					Ext Price
SS	SERVICE CHARGE					26.32
			Labor	Hrs		292.43
			Parts			476.50
			Misc			26.32
			Tax			41.48
			Total			836.73



BMW of South Austin

Job			Quote		
MISC BODY ELECTRICAL drivers headlight was not replaced but shows signs of attempted repair to headlight assembly. headlight is currently working with no warnings present				1,602.57	
replace drivers headlight assembly					
Qty	Part Number	Part Description	Price	Ext Price	
1.00	63-11-7-338-709	HEADLIGHT LE	894.30	894.30	
1.00	63-11-7-489-213	PLUG BMBIMI	9.86	9.86	
Misc Code	Misc Description				Ext Price
SS	SERVICE CHARGE				36.00
			Labor Hrs		584.85
	Parts			904.16	
Misc			36.00		
			Tax	77.56	
Total			1602.57 Quote		
a/c compressor releasing clutch materiel and showing signs of complete failure in the near future repalce compressor				2,283.76	
Qty	Part Number	Part Description	Price	Ext Price	
1.00	64-52-9-399-059	AIR COND.COM	1517.40	1517.40	
1.00	64-50-8-363-041	GASKET RING E	7.73	7.73	
1.00	64-50-8-375-741	GASKET RING E	8.30	8.30	
Misc Code	Misc Description				Ext Price
SS	SERVICE CHARGE	E CHARGE			36.00
			Labor Hrs		584.85
	Parts Misc Tax		1533.43		
			36.00		
				129.48	
	Total		2283.76 \$ 12207.92		
Suggested	Suggested Services Total			3 1	2207.92
	Total Estimate \$ 1			2645.30	

RECOMMENDED NOT DONE

These items were recommended by our certified BMW Technician but not completed during this visit.

All estimates are good for 30 days from time of estimate.