Black Forest Werkshop Service Invoice: 27477 Company Address 2 Riley, jaden 09/23/21 Created Year Address 3809 spicewood springs rd Time 11:35 AM BMW 12/17/2021 Model 328 Invoiced Austin, TX 78751 Advisor Administrato License PVZ0755 Home 512-713-6630 V Name Tech MC Division

PO#

Checked By

F256942

N20 01/12

Motor/prod

,		onprod	1420 01712			Page# 1 of 2	Miles Out	0
	ANY OF THE REAL PROPERTY.	Jo	b Desci	ription				NAME OF
minor damage to rea	ar bumper							
front damage as wel lights.	I- repair front bumper	and inst	all custo	omer			Line Total Labor Parts Sublets	0.0
oil and filer change							Line Total	7100000000
Part Number 11 42 7 953 129	Oeseription Oil filter kit 816x	QTY 1	List 23.40	Each 23,40	Total 23,40		Parts Sublets	93,49
O.E.M. spec oil Enviro Oil & Filter Recy	Full Synthetic oem spec	6.9	9.76	9.76 2.75	67.34 2.75			
Reattatch rear view	mirror						Line Total Labor Parts Sublets	26.00 0.00
Order bracket for fro	nt license plate and at	tatch pla	ate				Line Total Labor	
Part Number 51 13 7 344 551	Description front plate base	QTY	75.16	Fach 75 16	Total 75 16		Parts Sublets	75.16 0.00
Headlight bracket							Line Total	24.1 3
Part Number	Description	QTY	List	Each	Total		Parts	24.13
07 14 6 978 618 51 64 7 285 597	Torx w/ Washer Left Headlight Bracket	1	9.46 14.67	9.46 14.67	9.46 14.67		Sublets	0.00
Replace bulbs as ne	eded						Line Total Labor	109.60 65.00
Part Number	Description	QTY	List	Each	Total		Parts	44.60
63 12 8 361 289 63 21 7 160 795	Bulb H7 55w Halogen Blub 6w offset pina	;	29.87 14.73	29.87 14.73	29.87 14.73		Sublets	0.00
and install used head needed.	er and reinstall original dlight for drivers side - rket fog lights cause tl	install n	iew bulb	s as		Paid 2	Line Total Labor Parts Sublets	450.00
Part Number 63 11 7 338 705	Description Bi-Xenon Headlight	QTY	List 200.00	Each 200.00	Total 200.00	1. ch 10)		

The staff of the Black Forest Werkshop knows you have come to us by your own choice. THANK YOU! Please feet free to contact us about your experience via suggestions@blackforestwerkshop.com


2512 Buell Ave. Austin, TX 78757 512.300.BMWS (2697)

www.blackforestwerkshop.com

Work

Fax

Paid Suppliment



Body

Miles In

Graphite Sedan

91,772

Invoice Lotal			
Labor	\$756.00		
Parts	\$672.38		
Sublets	\$1,200.00		
Subtotal	\$2,628.38		
Tax	\$55.24		
Total	\$2,683.62		



Black Forest Werkshop Service Invoice: 27477 Riley, jaden Company Address 2 2012 09/23/21 Year Created 3809 spicewood springs rd Time Address 11:35 AM Make BMW Invoiced Model 328i Austin, TX 78751 Administrato License PVZ0755 Advisor Home 512-713-6630 Tech Division MC V Name Work V.I.N. F256942 PO# Body Graphite Sedan Fax Motor/prod N20 01/12 Checked By Miles In 91,772 2 of 2 Miles Out

sed bumper brake	Market No.	Job Desc	rintion	TI AT AT	The second second	
sed humner hrake			ription			
	t needed		The second second		Line Total	385.0
surance did not	pay for shipping on their	suppliment no	r did		Labor	150.0
ev nav for admini	strative fees of \$250.00	Supplimentino	did		Parts	235.0
cy pay for admini	sudive lees of \$250.00				Sublets	0.0
Part Number	Description	QTY List	Each To	n e		
51 11 7 255 393	Front bumper support	1 235 00	235 00 235	00		
ote: drivers side fo	og light trim does not fit.	60				
					1	

The staff of the Black Forest Werkshop knows you have come to us by your own choice. THANK YOU! Please feel free to contact us about your experience via suggestions@blackforestwerkshop.com

2512 Buell Ave. Austin, TX 78757 512.300.BMWS (2697)

www.blackforestwerkshop.com

Invoice Total		
Labor	\$756.00	
Parts	\$672.38	
Sublets	\$1,200.00	
Subtotal	\$2,628.38	
Tax	\$55.24	
Total	\$2,683.62	