Softing.OPCToolbox.Server.
Application.EnableTracing

Softing.OPCToolbox.Server.
Application.Initialize

Softing.OPCToolbox.Server. Creator.CreateAeAddressSpaceRoot

Softing.OPCToolbox.Server.

Creator.CreateDaAddressSpaceRoot

Softing.OPCToolbox.Server.

Creator.CreateWebTemplate

Softing.OPCToolbox.Server.
Application.Trace

Softing.OPCToolbox.Result Code.SUCCEEDED