Table-10: Stresses after Remove element no. 541 and 552

Member	Loadcase	Joi nt/Po	РТ	Phase	Norm/Equ	N/E-val ue
110	1	11	1		Si gEqu =	3. 038E+07
110	1	0. 50	13		Si gEqu =	3. 274E+07
110	1	12	13		Si gEqu =	4. 256E+07
120	1	12	13		Si gEqu =	4. 213E+07
120	1	0. 50	13		Si gEqu =	4. 124E+07
120	1	13	13		Si gEqu =	4. 035E+07
130	1	13	1		Si gEqu =	7. 180E+07
130	1	0. 50	13		Si gEqu =	3. 846E+07
130	1	14	13		Si gEqu =	9. 885E+07
140	1	14	13		Si gEqu =	1. 045E+08
140	1	0. 50	13		Si gEqu =	1. 274E+08
140	1	15	13		Si gEqu =	1. 502E+08
150	1	15	13	Phase	SigEqu =	3. 191E+08
Member	Loadcase	Joi nt/Po	PT		Norm/Equ	N/E-val ue
150 150	1	0. 50 16	5 1		Si gEqu = Si gEqu =	6. 545E+07 3. 371E+08
160	1	16	1		Si gEqu =	4. 051E+08
160	1	0. 50	1		Si gEqu =	2. 235E+08
160	1	17	13		Si gEqu =	1. 130E+08
170	1	17	13		Si gEqu =	2. 439E+08
170	1	0. 50	13		Si gEqu =	1. 912E+08
170	1	18	1		Si gEqu =	1. 603E+08
210	1	31	13		Si gEqu =	8. 262E+07
210	1	0. 50	1		Si gEqu =	8. 239E+07
210	1	32	1		Si gEqu =	9. 369E+07
220	1	32	1		Si gEqu =	9. 299E+07
220	1	0. 50	1		Si gEqu =	8. 012E+07
220	1	33	13		Si gEqu =	8. 574E+07
Member	Loadcase	Joi nt/Po	PT	Phase	Norm/Equ	N/E-val ue
230	1	33	13		Si gEqu =	1. 632E+08
230	1	0. 50	13		Si gEqu =	1. 522E+08
230	1	34	13		Si gEqu =	1. 413E+08
240	1	34	13		Si gEqu =	1. 408E+08
240	1	0. 50	13		Si gEqu =	2. 180E+08
240	1	35	13		Si gEqu =	2. 953E+08

250 250 250	1 1 1	35 0. 50 36	13 1 1		2. J-1	= = =	5. 203E+08 1. 549E+08 5. 952E+08
260 260 260	1 1 1	36 0. 50 37	1 1 13		~. J_ I	= = =	2. 960E+08 1. 754E+08 9. 781E+07
270 270 270	1 1 1	37 0. 50 38	13 13 13		Si gEqu Si gEqu Si gEqu		1. 873E+08 1. 697E+08 1. 520E+08
Member	Loadcase	Joi nt/Po	PT	Phase	Norm/Eq	ļu	N/E-val ue
311 311 311	1 1 1	11 0. 50 21	13 13 13		Si gEqu Si gEqu Si gEqu	=	1. 146E+08 1. 041E+08 9. 356E+07
312 312 312	1 1 1	21 0. 50 31	13 1 1		Si gEqu	= = =	1. 056E+08 9. 638E+07 1. 306E+08
321 321 321	1 1 1	12 0. 50 22	1 1 13		~. J_ I	= = =	6. 293E+07 4. 485E+07 5. 360E+07
322 322 322	1 1 1	22 0. 50 32	13 1 1		Si ğEqu	= = = =	4. 763E+07 2. 240E+07 4. 980E+07
331 331 331	1 1 1	13 0. 50 23	1 1 13		~. J_ '	= = =	1. 815E+08 1. 178E+08 1. 732E+08
Member	Loadcase	Joi nt/Po	PT	Phase	Norm/Ed	ļu	N/E-val ue
332 332 332	1 1 1	23 0. 50 33	13 13 1		Si gEqu	= = = =	1. 442E+08 1. 155E+08 1. 407E+08
341 341 341	1 1 1	14 0. 50 24	1 1 13		Si gEqu Si gEqu Si gEqu		1. 858E+08 6. 360E+07 1. 829E+08
342 342 342	1 1 1	24 0. 50 34	1 1 1		Si gEqu Si gEqu Si gEqu	=	2. 071E+07 2. 025E+07 1. 979E+07
351 351 351	1 1 1	15 0. 50 25	1 1 13		Si gEqu	=	4. 957E+08 2. 084E+08 4. 055E+08
352 352 352	1 1 1	25 0. 50 35	1 13 13		Si gEqu Si gEqu Si gEqu	=	2. 006E+08
Member	Loadcase	Joi nt/Po	PT	Phase	Norm/E	ļu	N/E-val ue

361 361 361	1 1 1	16 0. 50 26	13 1 1		Si gEqu Si gEqu Si gEqu	=	4. 570E+08 1. 394E+08 6. 682E+08
362 362 362	1 1 1	26 0. 50 36	13 7 1		Si gEqu Si gEqu Si gEqu	= = =	1. 007E+09 1. 247E+08 1. 154E+09
371 371 371	1 1 1	17 0. 50 27	13 13 1		Si gEqu	= = =	1. 778E+08 9. 394E+07 1. 561E+08
372 372 372	1 1 1	27 0. 50 37	1 8 13		2. 3_ 1	= = =	1. 780E+08 7. 271E+07 1. 792E+08
381 381 381	1 1 1	18 0. 50 28	1 1 13		Si gEqu Si gEqu Si gEqu	= =	1. 873E+08 1. 162E+08 1. 633E+08
Member	Loadcase	Joi nt/Po	PT	Phase	Norm/Ed	ηu	N/E-val ue
382 382 382	1 1 1	28 0. 50 38	13 13 1		Si ğEqu	= = =	1. 114E+08 9. 289E+07 1. 052E+08
511 511 511	1 1 1	11 0. 50 22	13 13 1		Si gEqu	= =	1. 875E+08 1. 797E+08 1. 764E+08
512 512 512	1 1 1	22 0. 50 31	1 13 13		Si gEqu Si gEqu Si gEqu	=	2. 162E+08 2. 012E+08 2. 199E+08
521 521 521	1 1 1	22 0. 50 13	13 13 13		Si ğEqu	= =	1. 926E+08 1. 913E+08 1. 899E+08
522 522 522	1 1 1	22 0. 50 33	13 1 1		~. J_ '	= =	1. 741E+08 1. 632E+08 1. 755E+08
Member	Loadcase	Joi nt/Po	PT	Phase	Norm/Ed	ηu	N/E-val ue
531 531 531	1 1 1	13 0. 50 24	13 1 1		Si ğ <u>E</u> qu	= =	3. 881E+08 3. 374E+08 3. 935E+08
532 532 532	1 1 1	24 0. 50 33	13 1 1		Si gEqu Si gEqu Si gEqu	= = =	7. 406E+06 8. 541E+06 1. 770E+07
542 542 542	1 1 1	24 0. 50 35	13 1 1		~. <sup>~</sup> - '	= = =	3. 091E+08 3. 307E+08 3. 747E+08

551 551 551	1 1 1	15 0. 50 26	1 13 13		Si gEqu Si gEqu Si gEqu		3. 089E+08 1. 335E+08 4. 296E+08
561 561 561	1 1 1	16 0. 50 27	13 13 1		Si gEqu Si gEqu Si gEqu	=	3. 034E+08 1. 699E+08 1. 630E+08
Member	Loadcase	Joi nt/Po	PT	Phase	Norm/Ed	qu	N/E-val ue
562 562 562	1 1 1	36 0. 50 27	1 1 13		Si gEqu Si gEqu Si gEqu	=	
571 571 571	1 1 1	17 0. 50 28	1 1 13		Si gEqu Si gEqu Si gEqu	=	5. 722E+07 2. 121E+07 3. 209E+07
572 572 572	1 1 1	28 0. 50 37	13 1 1		Si gEqu Si gEqu Si gEqu	=	2. 553E+07 1. 896E+07 4. 037E+07
911 911 911	1 1 1	21 0. 50 22	13 13 1		Si gEqu Si gEqu Si gEqu	= =	6. 312E+07 9. 555E+06 4. 800E+07
931 931 931	1 1 1	23 0. 50 24	1 1 1		Si gEqu Si gEqu Si gEqu		1. 553E+07 1. 115E+07 6. 773E+06
Member	Loadcase	Joi nt/Po	PT	Phase	Norm/Ed	qu	N/E-val ue
941 941 941	1 1 1	24 0. 50 25	13 6 1		Si gEqu Si gEqu Si gEqu	=	1. 334E+08 1. 121E+07 1. 438E+08