Table-10: Stresses after Remove element no. 561

Member	Loadcase	Joi nt/Po	РТ	Phase	Norm/Equ	u N/E-value
110 110 110	1 1 1	11 0. 50 12	1 13 13		Si gEqu : Si gEqu : Si gEqu :	= 3. 544E+07
120 120 120	1 1 1	12 0. 50 13	13 13 1		Si gEqu : Si gEqu : Si gEqu :	= 3. 611E+07
130 130 130	1 1 1	13 0. 50 14	1 1 13		Si gEqu : Si gEqu : Si gEqu :	= 6. 522E+06
140 140 140	1 1 1	14 0. 50 15	13 13 13		Si gEqu : Si gEqu : Si gEqu :	= 2. 046E+07
150 Member	1 Loadcase	15 Joi nt/Po	1 PT	Phase	SigEqu : Norm/Equ	= 1.256E+08 u N/E-val ue
150 150	1 1	0. 50 16	13 13		Si gEqu : Si gEqu :	
160 160 160	1 1 1	16 0. 50 17	13 13 1		Si gEqu : Si gEqu : Si gEqu :	= 8. 673E+07
170 170 170	1 1 1	17 0. 50 18	1 1 13		Si gEqu : Si gEqu : Si gEqu :	= 3. 023E+08
210 210 210	1 1 1	31 0. 50 32	13 1 1		Si gEqu : Si gEqu : Si gEqu :	= 7. 911E+07
220 220 220	1 1 1	32 0. 50 33	1 1 13		Si gEqu : Si gEqu : Si gEqu :	= 8. 024E+07
Member	Loadcase	Joi nt/Po	PT	Phase	Norm/Eq	ı N/E-value
230 230 230	1 1 1	33 0. 50 34	13 13 1		Si gEqu : Si gEqu : Si gEqu :	= 1. 044E+08
240 240 240	1 1 1	34 0. 50 35	1 1 1		Si gEqu : Si gEqu : Si gEqu :	= 1.168E+08
250 250 250	1 1 1	35 0. 50 36	1 13 13		Si gEqu : Si gEqu : Si gEqu :	= 1. 595E+08

260 260 260	1 1 1	36 0. 50 37	13 13 1	Si gEqu = Si gEqu = Si gEqu =	2. 842E+08 1. 343E+08 1. 759E+08
270 270 270	1 1 1	37 0. 50 38	1 1 13	Si gEqu = Si gEqu = Si gEqu =	5. 693E+08 3. 445E+08 1. 767E+08
Member	Loadcase	Joi nt/Po	PT Phase	Norm/Equ	N/E-val ue
311 311 311	1 1 1	11 0. 50 21	13 13 1	Si gEqu = Si gEqu = Si gEqu =	1. 141E+08 9. 514E+07 7. 630E+07
312 312 312	1 1 1	21 0. 50 31	13 1 1	Si gEqu = Si gEqu = Si gEqu =	8. 828E+07 8. 907E+07 1. 147E+08
321 321 321	1 1 1	12 0. 50 22	1 1 13	Si gEqu = Si gEqu = Si gEqu =	3. 910E+07 1. 814E+07 3. 175E+07
322 322 322	1 1 1	22 0. 50 32	13 1 1	Si gEqu = Si gEqu = Si gEqu =	6. 468E+07 4. 464E+07 6. 895E+07
331 331 331	1 1 1	13 0. 50 23	1 1 13	Si gEqu = Si gEqu = Si gEqu =	2. 081E+07 2. 780E+06 1. 612E+07
Member	Loadcase	Joi nt/Po	PT Phase	Norm/Equ	N/E-val ue
Member	Loadcase 1 1	Joi nt/Po 23 0. 50 33	PT Phase 1 13 13	Norm/Equ SigEqu = SigEqu = SigEqu =	N/E-val ue 2. 468E+07 3. 108E+06 2. 881E+07
332 332	1 1	23 0. 50	1 13	 Si gEqu = Si gEqu =	2. 468E+07 3. 108E+06
332 332 332 332 341 341	1 1 1 1 	23 0. 50 33 	1 13 13 13 1	Si gEqu =	2. 468E+07 3. 108E+06 2. 881E+07 7. 907E+07 5. 152E+07
332 332 332 332 341 341 341 341 342 342	1 1 1 1 1 1 1	23 0.50 33 	1 13 13 13 1 1 1 13	Si gEqu =	2. 468E+07 3. 108E+06 2. 881E+07 7. 907E+07 5. 152E+07 7. 375E+07 7. 561E+07 5. 322E+07 8. 124E+07
332 332 332 341 341 341 342 342 342 342 351 351	1 1 1 1 1 1 1 1 1 1	23 0. 50 33 	1 13 13 13 1 1 13 13 1 13	Si gEqu = Si gEq	2. 468E+07 3. 108E+06 2. 881E+07 7. 907E+07 5. 152E+07 7. 375E+07 7. 561E+07 5. 322E+07 8. 124E+07 2. 300E+07 4. 102E+07 2. 769E+07 2. 323E+07
332 332 332 332 	1 1 1 1 1 1 1 1 1 1 1 1	23 0. 50 33 14 0. 50 24 0. 50 34 15 0. 50 25 0. 50 35	1 13 13 13 1 1 13 13 1 1 13 1 13 1 13	Si gEqu =	2. 468E+07 3. 108E+06 2. 881E+07 7. 907E+07 5. 152E+07 7. 375E+07 7. 561E+07 5. 322E+07 8. 124E+07 2. 300E+07 4. 102E+07 2. 769E+07 2. 323E+07
332 332 332 332 341 341 341 341 342 342 342 342 351 351 351 351 352 352 352	1 1 1 1 1 1 1 1 1 1 1 1	23 0. 50 33 14 0. 50 24 0. 50 34 15 0. 50 25 0. 50 35	1 13 13 13 1 1 13 13 1 1 13 1 13 1 13	Si gEqu =	2. 468E+07 3. 108E+06 2. 881E+07 7. 907E+07 5. 152E+07 7. 375E+07 7. 375E+07 8. 124E+07 8. 124E+07 2. 309E+07 4. 102E+07 2. 309E+07 2. 323E+07 2. 323E+07 2. 323E+07 2. 323E+07 3. 351E+08 1. 678E+08

371	1	17	1	Si gEqu =	1. 225E+09
371	1	0. 50	6	Si gEqu =	1. 153E+08
371	1	27	13	Si gEqu =	1. 062E+09
372	1	27	1	Si gEqu =	4. 425E+08
372	1	0. 50	1	Si gEqu =	1. 324E+08
372	1	37	13	Si gEqu =	2. 307E+08
381	1	18	13	Si gEqu =	2. 378E+08
381	1	0. 50	13	Si gEqu =	1. 627E+08
381	1	28	1	Si gEqu =	1. 893E+08
Member	Loadcase	Joi nt/Po	PT Phase	Norm/Equ	N/E-val ue
382	1	28	13	Si gEqu =	1. 911E+08
382	1	0. 50	1	Si gEqu =	9. 093E+07
382	1	38	1	Si gEqu =	2. 698E+08
511	1	11	13	Si gEqu =	2. 172E+08
511	1	0. 50	13	Si gEqu =	2. 068E+08
511	1	22	1	Si gEqu =	2. 069E+08
512	1	22	1	Si gEqu =	1. 861E+08
512	1	0. 50	13	Si gEqu =	1. 748E+08
512	1	31	13	Si gEqu =	1. 905E+08
521	1	22	1	Si gEqu =	1. 685E+08
521	1	0. 50	13	Si gEqu =	1. 681E+08
521	1	13	13	Si gEqu =	1. 735E+08
522	1	22	13	Si gEqu =	1. 953E+08
522	1	0. 50	1	Si gEqu =	1. 924E+08
522	1	33	1	Si gEqu =	1. 996E+08
Member	Loadcase	Joi nt/Po	PT Phase	Norm/Equ	N/E-val ue
531	1	13	13	Si gEqu =	1. 428E+08
531	1	0. 50	13	Si gEqu =	1. 348E+08
531	1	24	1	Si gEqu =	1. 389E+08
532	1	24	1	Si gEqu =	1. 890E+08
532	1	0. 50	13	Si gEqu =	1. 806E+08
532	1	33	13	Si gEqu =	1. 923E+08
541	1	24	13	Si gEqu =	1. 462E+08
541	1	0. 50	1	Si gEqu =	1. 477E+08
541	1	15	1	Si gEqu =	1. 512E+08
542	1	24	1	Si gEqu =	1. 128E+08
542	1	0. 50	13	Si gEqu =	1. 072E+08
542	1	35	13	Si gEqu =	1. 174E+08
551	1	15	1	SI aEau =	1. 758E+08
551	1	0. 50	13		1. 472E+08
551	1	26	13	Si gEqu =	1. 976E+08
	1	26 	13		1. 976E+08 N/E-val ue

562	1	36	13	Si gEqu =	2. 787E+08
562	1	0. 50	1	Si gEqu =	7. 863E+07
562	1	27	1	Si gEqu =	3. 564E+08
571	1	17	13		2. 603E+08
571	1	0. 50	13		1. 213E+08
571	1	28	1		1. 469E+08
572	1	28	1	Si gEqu =	1. 757E+08
572	1	0. 50	13	Si gEqu =	1. 366E+08
572	1	37	13	Si gEqu =	3. 136E+08
911	1	21	13	Si gEqu =	6. 178E+07
911	1	0. 50	13	Si gEqu =	8. 040E+06
911	1	22	1	Si gEqu =	4. 682E+07
Member	Loadcase	Joi nt/Po	PT Phase	Norm/Equ	N/E-val ue
931	1	23	13		1. 969E+07
931	1	0. 50	7		1. 502E+06
931	1	24	1		1. 834E+07
941	1	24	13	Si gEqu =	1. 410E+07
941	1	0. 50	7	Si gEqu =	1. 118E+06
941	1	25	1	Si gEqu =	1. 410E+07