Table-9: Stresses after Remove element no. 542

Member	Loadcase	Joi nt/Po	PT	Phase	Norm/Equ	N/E-val ue
110	1	11	1		Si gEqu =	2. 905E+07
110	1	0. 50	13		Si gEqu =	3. 732E+07
110	1	12	13		Si gEqu =	5. 594E+07
120	1	12	13		Si gEqu =	5. 510E+07
120	1	0. 50	13		Si gEqu =	3. 639E+07
120	1	13	1		Si gEqu =	2. 899E+07
130	1	13	1		Si gEqu =	4. 158E+07
130	1	0. 50	1		Si gEqu =	4. 002E+07
130	1	14	1		Si gEqu =	3. 846E+07
140	1	14	1		Si gEqu =	3. 960E+07
140	1	0. 50	1		Si gEqu =	2. 031E+07
140	1	15	13		Si gEqu =	3. 774E+07
150	1	15	1	Phase	SigEqu =	9. 124E+07
Member	Loadcase	Joi nt/Po	PT		Norm/Equ	N/E-val ue
150	1	0. 50	1		Si gEqu =	7. 791E+07
150	1	16	1		Si gEqu =	6. 457E+07
160	1	16	1		Si gEqu =	7. 539E+07
160	1	0. 50	1		Si gEqu =	7. 765E+07
160	1	17	1		Si gEqu =	7. 992E+07
170	1	17	13		Si gEqu =	1. 503E+08
170	1	0. 50	1		Si gEqu =	1. 522E+08
170	1	18	1		Si gEqu =	1. 552E+08
210	1	31	13		Si gEqu =	8. 392E+07
210	1	0. 50	13		Si gEqu =	8. 161E+07
210	1	32	1		Si gEqu =	7. 994E+07
220	1	32	1		Si gEqu =	7. 965E+07
220	1	0. 50	1		Si gEqu =	8. 339E+07
220	1	33	1		Si gEqu =	8. 713E+07
Member	Loadcase	Joi nt/Po	PT	Phase	Norm/Equ	N/E-val ue
230	1	33	1		Si gEqu =	1. 075E+08
230	1	0. 50	13		Si gEqu =	1. 004E+08
230	1	34	13		Si gEqu =	1. 401E+08
240	1	34	13		Si gEqu =	1. 447E+08
240	1	0. 50	13		Si gEqu =	9. 202E+07
240	1	35	1		Si gEqu =	1. 298E+08
250	1	35	1		Si gEqu =	1. 730E+08
250	1	0. 50	1		Si gEqu =	1. 249E+08
250	1	36	13		Si gEqu =	1. 138E+08
260	1	36	13		Si gEqu =	9. 430E+07
260	1	0. 50	13		Si gEqu =	8. 272E+07
260	1	37	1		Si gEqu =	8. 554E+07

270 270 270	1 1 1	37 0. 50 38	1 1 13		SigEqu =	1. 763E+08 1. 602E+08 1. 554E+08
Member	Loadcase	Joi nt/Po	PT Ph	nase	Norm/Equ	N/E-val ue
311 311 311	1 1 1	11 0. 50 21	13 13 1			1. 141E+08 9. 025E+07 7. 705E+07
312 312 312	1 1 1	21 0. 50 31	13 1 1		Si aEau =	7. 851E+07 8. 508E+07 1. 060E+08
321 321 321	1 1 1	12 0. 50 22	1 1 13		Si gEqu = Si gEqu = Si gEqu =	2. 865E+07 5. 942E+06 2. 250E+07
322 322 322	1 1 1	22 0. 50 32	13 1 1		Si gEqu = Si gEqu = Si gEqu =	5. 988E+07
331 331 331	1 1 1	13 0. 50 23	1 13 13		Si gEqu = Si gEqu = Si gEqu =	7. 331E+07 6. 501E+07 7. 727E+07
Member	Loadcase	Joi nt/Po	PT Ph	nase	Norm/Equ	N/E-val ue
332 332 332	1 1 1	23 0. 50 33	13 1 1		Si gEqu = Si gEqu = Si gEqu =	1. 114E+08 6. 556E+07 1. 171E+08
341 341 341	1 1 1	14 0. 50 24	1 1 13		Si gEqu =	7. 875E+07 6. 010E+07 6. 931E+07
342 342 342	1 1 1	24 0. 50 34	13 1 1		SigEqu =	1. 649E+08 8. 588E+07 1. 735E+08
351 351 351	1 1 1	15 0. 50 25	13 13 1		Si gEqu = Si gEqu = Si gEqu =	1. 153E+08
352 352 352	1 1 1	25 0. 50 35	13 1 1		SigEqu =	2. 243E+08 1. 194E+08 2. 399E+08
Member	Loadcase	Joi nt/Po	PT Ph	nase	Norm/Equ	N/E-val ue
361 361 361	1 1 1	16 0. 50 26	1 1 13		Si gEqu =	9. 704E+07 8. 051E+07 7. 675E+07
362 362 362	1 1 1	26 0. 50 36	1 1 13		Si gEqu = Si gEqu = Si gEqu =	8. 982E+07 8. 065E+07 8. 087E+07
371 371 371	1 1 1	17 0. 50 27	1 1 13		Si gEqu = Si gEqu = Si gEqu =	9. 957E+07 5. 695E+07 9. 073E+07
<b>-</b> _ <b>-</b>	<b>_</b>	<b>_</b> _	· - <del>-</del>		<b>_</b> _	

372 372 372	1 1 1	27 0. 50 37	1 1 1		Si gEqu = Si gEqu = Si gEqu =	5. 583E+07
381 381 381	1 1 1	18 0. 50 28	1 1 13		Si gEqu = Si gEqu = Si gEqu =	
Member	Loadcase	Joi nt/Po	PT I	Phase	Norm/Equ	N/E-value
382 382 382	1 1 1	28 0. 50 38	13 1 1		Si gEqu = Si gEqu = Si gEqu =	8. 692E+07
511 511 511	1 1 1	11 0. 50 22	13 13 1		Si gEqu = Si gEqu = Si gEqu =	2. 216E+08
512 512 512	1 1 1	22 0. 50 31	1 13 13		Si gEqu = Si gEqu = Si gEqu =	1. 595E+08
521 521 521	1 1 1	22 0. 50 13	1 13 13		Si gEqu = Si gEqu = Si gEqu =	1. 513E+08
522 522 522	1 1 1	22 0. 50 33	13 1 1		Si gEqu = Si gEqu = Si gEqu =	2. 051E+08
Member	Loadcase	Joi nt/Po	PT I	Phase	Norm/Equ	N/E-val ue
531 531 531	1 1 1	13 0. 50 24	1 1 13		Si gEqu = Si gEqu = Si gEqu =	3. 967E+07
532 532 532	1 1 1	24 0. 50 33	1 1 13		Si gEqu = Si gEqu = Si gEqu =	2. 966E+08
541 541 541	1 1 1	24 0. 50 15	13 13 1		Si gEqu = Si gEqu = Si gEqu =	2. 357E+08
551 551 551	1 1 1	15 0. 50 26	13 13 13		Si gEqu = Si gEqu = Si gEqu =	1. 387E+08 1. 314E+08 1. 241E+08
552 552 552	1 1 1	35 0. 50 26	1 1 13			1. 662E+08 1. 339E+08 1. 321E+08
Member	Loadcase	Joi nt/Po	PT I	Phase	Norm/Equ	N/E-val ue
561 561 561	1 1 1	16 0. 50 27	13 13 13	_ <b></b>	SigEqu =	6. 832E+07 6. 830E+07 6. 829E+07
562 562 562	1 1 1	36 0. 50 27	13 1 1		Si gEqu = Si gEqu = Si gEqu =	7. 329E+07 6. 641E+07 7. 531E+07

571	1	17	13	Si gEqu =	2. 661E+07
571	1	0. 50	13	Si gEqu =	2. 198E+07
571	1	28	1	Si gEqu =	2. 050E+07
572	1	28	1		2. 408E+07
572	1	0. 50	13		2. 510E+07
572	1	37	13		3. 098E+07
911	1	21	1	Si gEqu =	6. 140E+07
911	1	0. 50	1	Si gEqu =	7. 781E+06
911	1	22	13	Si gEqu =	4. 633E+07
Member	Loadcase	Joi nt/Po	PT Phase	Norm/Equ	N/E-val ue
Member  931 931 931	Loadcase  1 1 1	Joi nt/Po 23 0. 50 24	PT Phase 13 13	 Si gEqu = Si gEqu =	N/E-val ue 1. 786E+07 6. 385E+06 6. 445E+06