
Hb station report

Hb data extracted for time range 2023-01-01 through 2024-05-29...

Total number of Hb sessions matching search criteria: 121

Total number of Hb observations across all sessions matching search criteria: 64718

Median station W.RMS over period: 58.05 ps Median station 'Performance' over period: 0.385



Reported issues (as extracted from analysis reports)

```
R41084: Observed in mixed mode (X, Y polarization instead of R); Removed channel from fringe fitting: S05UX, S05UY, S06UX, S06UY R11086: Removed channel from fringe fitting: S04UL/R, S05UL/R, No lisb channels present; Missed first scan.
R11087: DBBC3 failure: 2023-023-2170000 - 2023-023-210036, 2023-023-211000 - 2023-023-211707; Removed channel from fringe fitting: S04UL/R, S05UL/R R41087: Late start (1026-19-28): Observed in mixed mode (X, Y polarization instead of R); Removed channel from fringe fitting: S05UX, S05UY, S06UX, S06UY R41088: Late start: 2023-033-183738; Stopped for power outage: 2023-033-213023 - 2023-033-214240; Stopped (halted): 2023-033-220601 - 2023-033-224925; Stopped for antenna drive errors: 2023-034-053652 - 2023-034-054956, 2023-034-061826 - 2023-034-072203, 2023-034-081206 - 2023-034-084832; ; Used in AUS mixed mode; Clock break at 2023-032-25300 (-2.473 usec)
R11090: Late start 17-47; Minused out: 2023-044-170232 - 2023-044-174500; Removed channel from fringe fitting: S04UR, S05UR, S05UL, S06UR, S07UR, 
Clock break at 2023-047-183000 (0.011 usec)
R11091: Removed channel from firing fitting: S04ULX, S05ULX, S05UY
R41092: SAR tracking (061-19:15 - 061-19:20); Removed channel from fringe fitting: S04UX, S05UX, S05UY
R41092: SAR tracking (061-19:16 - 061-19:20); Removed channel from fringe fitting: S04UX, S05UX, S05UY
R11093: Wind stowed: 2023-066-023244 - 2023-066-083744; Removed channel from fringe fitting: S04UX, S05UX, S05UY
R11094: Removed channel from fringe fitting: S04UX, S05UX, S05UY
R11094: Removed channel from fringe fitting: S04UX, S05UX, S05UY
R41094: Removed channel from fringe fitting: S04UX, S05UX, S05UY
R41095: Minused out: 2023-079-170148 - 2023-079-17114; SAR: 2023-079-191543 - 2023-079-191921; Removed channel from fringe fitting: S04UXY, S05UXY
R41096: Minused out: 2023-083-063420 - 2023-083-081721 - 2023-083-182801 (end);
R11096: Removed channel from fringe fitting: S04UXY, S05UXY
R41098: Removed channel from fringe fitting: S04UXY, S05UXY
R41088: Observed in mixed mode with polarizations X, Y. Approximately half of the raw data files were corrupted (lots of junk data at end of files); Only -50% of data could be correlated; Removed channel from fringe fitting: S04UXY, S05UXY
R11099: Minused out: (late start) 2023-107-170000 - 2023-107-170502; Removed channel from fringe fitting: S04UXY, S05UXY
R11099: Minused out: (late start) 2023-107-170000 - 2023-107-170524; Removed channel from fringe fitting: S04UXY, S05UXY, S05UXY
R11099: Minused out: (late start) 2023-107-170000 - 2023-107-170524; Removed channel from fringe fitting: S04UXY, S05UXY, S05UXY
R11099: Minused out: (late start) 2023-107-170000 - 2023-115-0750002;
R11010: alted (07:02-07-45) to fix missing SY polarization (17:00-07:50); Minused out: 2023-115-0750002;
R11010: observed in mixed mode with polarizations X, Y; Schedule restarted at 17:00. May have missed first 2 scanss; Removed channel from fringe fitting: S04UXY, S05UXY
  SOAUXY, SO5UXY
R11102: Observed with dual linear polarisation X,Y; Scans incomplete because some disks went missing for a while during transfer; Missing bits are curently being transferred; Late start 18:02; Minused out: (start) 2023-128-170000 -- 2023-128-175814; Removed channel from fringe fitting: SO4UX, SO5UX; SO5UX; SO5UX; R11103: 10MHz disturbed onsight, lead to issues with clkoff reading. Affected scans 0400UT - 0830UT.; alteric 2023-136-082957 -- 2023-136-083459; Removed channel from fringe fitting: SO4UXY; No fringe after 03:53.
R11104: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: SO4UX, SO5UX; SO5UY; R11107: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: SO4UX, SO4UX, SO5UX; SO5UY; R11108: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: SO4UX, SO5UX, SO5UX; SO5UY; R11108: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: SO4UX, SO4UX, SO5UX; SO5UY; R11109: One disk was missing. Two racks on the dbbc showed 0ns delay; Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: SO4UX, SO5UX, SO5UX; S
  S04UX, S05UX, S05UX; S05UY; R11111: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R11112: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; Recording error present during the session which caused the loss of; random datastreams, e.g., there is no XX data between 199-0142 and 199-0703; R41112: Toropped channels due to low phase amplitude: S04UX, S04UY, S05UX, S05UY R11114: Antenna stuck (17:00-17:07); Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R41114: Late start 2023-215-183000 – 2023-215-185119; Missing scans due to incomplete data transfer; Missing polarization on some scans due to incomplete data transfer.
    used utalister

RT11115: Observed with dual linear polarisation X,Y and 16 MHz channel width; which required applying zoomband for correlation; Observed with eight USBs and no
LSB;, Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
RT11116: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S05UX, S05UY;
RT1117: Minused out: (late start) 2023-234-170000 - 2023-234-172430; Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX,
    SO4UY, SO5UX, SO5UY, SO5UY, SO5UY; R11118: Minused out: 2023-223-212815 -- 2023-243-215247; Removed channel from fringe fitting: S04UY, X06LR, S06UY, S06UX, X13LR, S04UX, S07UX, S05UR, S05UY; R41118: Minused out: 2023-243-212815 -- 2023-243-215247; Removed channel from fringe fitting: S04UY, X06LR, S06UY, S06UX, X13LR, S04UX, S07UX, S05UR, S05UY, S05UP, S05
       S04UR, S07UY, S05UX
SO4UX, SO5UX, SO5UX
R11119: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11120: Observed with dual linear polarisation R,L; Removed channel from fringe fitting: S04UX, S04UL, S05UR, S05UL;
R11121: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S05UX, S05UY;
R11122: Observed with dual linear polarisation X,Y; Late start due to dbbc3 reset; Minused out: (start) 2023-269-170000 - 2023-269-172328; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11123: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R41123: Minused out: 2023-278-194030 due to clock-break formatting error, 2023-279-020837 - 2023-279-032120 due to flexbuf-2hb reboot; ; Clock break at 2023-279-032300 (-0.118 usec). Station summary notes that recording bad after 02:08. Correlation results include clock break application; Dropped channel S04UR S05UI
  SUBUR
R11124: Pause: 2023-283-135544 - 2023-283-141314; Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S05UY; R11125: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S05UX, S05UY; R11126: Lost 100 MHz reference signal and late start at 00:31 after fixing; Minused out: (late start) 2023-296-170000 -- 2023-297-003100; Mk5 error messages (00:31-00:37); Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S05UX, S05UY; R11127: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R11128: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R11128: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R11128: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R11128: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R11128: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R11128: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R11128: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R11128: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; R1128: Observed with dual linear polarisation X,Y; R1128: Observed with dual linear polarisation X,Y;
       R41128: Minused out all scans
  R41128: Minused out all scans R11129: Potentially bad sampler (17:00-21:44); alted (21:44-00:36); Minused out: 2023-317-214407 – 2023-318-003245; Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S05UX, S05UY; R11130: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S05UX, S05UY; R41131: Late arrival. Not all data has arrived yet; R1132: Late start: 2023-338-170000 – 2023-339-023433; Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S05UX, S05
  S05UY;
R11133: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting; S04UX, S04UY, S05UX, S05UY;
R41133: Minused out: (start) 2023-348-183000 - 2023-348-200154. Bad sampler (18:30-20:07).;
R11134: Minused out: (Late start) 2023-352-170000 - 2023-352-181245; Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S05UY;
R41136: Minused out data corrupted
R41138: Minused out due to no fringes
R41140: Minused out did not participate
  R4114: Minused out old not participate
R11414: Observed with dual linear polarisation X,Y; Polswap in S band, could be fixed with polswapDiFX.py (comes with dtrunk); Removed channel from fringe
fitting: S04UX, S04UY, S05UX, S05UY;
R41141: Minused out: (start) 2024-039-183000 -- 2024-039-203621;; Dropped channel S04UX,S05UX
R11142: Observed with dual linear polarisation X,Y; Polswap in S band, after correlation fixed using polswapDiFX.py; Removed channel from fringe fitting: S04UX,
S05UX, S05UY; Missed first scan.
R11143: Observed with dual linear polarisation X,Y; Polarization swap in S-band, fixed in v2d file.; Removed channel from fringe fitting: S04UX, S05UX,
S05UY; SAR (19:15-19:20).
R11413: Minused out: (start) 2024-053-183000 -- 2024-053-183601:
       R41143: Minused out: (start) 2024-053-183000 -- 2024-053-183601;
  R41143: Minused out: (start) 2024-053-183000 -- 2024-053-183601;
R11145: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11146: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11147: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11148: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11150: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11151: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11151: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
  R11151: Observed with dual linear polarisation X,Y; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY; Polarisation swapped in S-band, fixed by polswapDiFX.py
R11152: Observed with dual linear polarisation X,Y; Polswap in S band; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11153: Observed with dual linear polarisation X,Y; Polswap in S-band; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11153: Observed with dual linear polarisation X,Y; Polswap in S-band; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY
R11153: Observed with dual linear polarisation X,Y; Polswap in S band; Removed channel from fringe fitting: S04UX, S04UY, S05UX;
R11154: Observed with dual linear polarisation X,Y; Polswap in S band; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
R11155: Observed with dual linear polarisation X,Y; Polarisation swap in S-band; SAR: 2024-134-191731; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S04UY, S05UX, S05UY
       S05UX, S05UY
    Susux, Susur R41155: Minused out: 2024-138-070518 -- 2024-138-182819 (end) Major DBBC issue; R11156: No scans before 2101UTC due to LBA; DBBC version reconfig required after LBA; Observed with dual linear polarisation X,Y; Minused out: (start) 2024-141-170000 -- 2024-141-210444; Removed channel from fringe fitting: S04UX, S04UY, S05UX, S05UY;
```