


Mill Speed



$$N_c = \frac{N}{N_{\text{crit}}} = \frac{N}{76.6 / \sqrt{D}}$$

① N_c = Mill speed as a fraction of its critical speed, %/1

N = Mill speed, in RPM

N_{crit} = Mill critical speed, in RPM

D = Effective diameter of the mill