

RAINFALL AT

Brasted Combe Bank

Lat. _____

Lon. _____

County of *W Kent*

Sundon Copper Rain Gauge, by *N 53*

Observer *R Mond Esq*

G. Darent.

Diameter ...									8	12	
Height									0 10	1.8	
Altitude ...									323	π	
Year ...	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ...									1.77	1.13	
February ...									1.45	.63	
March									2.68	3.59	
April									2.76	1.85	
May									2.11	1.47	
June									2.01	3.03	
July									3.85	3.51	
August									4.16	2.02	
September ..									1.56	3.24	
October ...									1.88	6.68	
November ..									1.07	1.18	
December ...									3.16	4.35	
TOTALS ...									28.46	32.68	

1908 Sundridge Church $\frac{1}{2}$ mile SE

Brasted Station $\frac{1}{2}$ W N W

rees 40 ft high 100 yards NW + N

+ Inspected by Dr. Mill

RAINFALL at Brasted ComberbankCounty of KentObserver R.I. MondragRiver Basin Thames - Darent 5Rain Gauge, by N+Z Nathwells Recordings
1912 Sundridge N+Z

Diameter ...	8										
Height	8. 10										
Altitude ...	328 ft										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	2.53	1.57	2.89	3.95	.80	4.66					
February ...	4.44	1.94	2.36	1.00	4.52	4.44					
March	1.21	2.51	4.51	2.91	5.92	.73					
April	1.92	2.46	.14	3.33	1.38	1.71					
May	2.83	1.44	1.15	1.08	1.79	3.21					
June	2.43	2.45	3.00	.68	.85	.72					
July	2.54	.61	1.44	2.58	1.47	4.46					
August	1.98	.56	6.62	1.37	2.12	2.38					
September ..	.80	1.53	3.22	1.51	1.80	2.16					
October ...	2.66	4.43	3.38	4.90		2.54					
November ..	3.59	5.88	3.07	3.52	4.23	3.36					
December ...	4.11	6.82	3.35	1.23	8.13	6.64					
TOTALS ...	31.08	32.20	35.13	28.06	33.01	37.01	NR				
	3		3	3		3					

1910 Tree 45ft high 100 yds N
200 1914

† Inspected

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
1910	51° 16' 24"	0.7. E	Brasted	1½ m	SW	Sundridge	1½ mile	SSE