

Service Depot Maintenance Log

Aldergrove Instruments Ltd. — Richmond service depot. Log reference MLOG-2025, covering January 2025 to December 2025. Entries are recorded in chronological order and are not amended after sign-off; corrections are made by a subsequent entry.

Retention

This log is retained for seven years in accordance with the Information Security Policy. Entries relating to units under warranty are additionally retained for the duration of the warranty period plus two years.

Log entries

Entry 0001 — 2025-01-02 — Unit AX7200-BC-0742

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 4.5 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Any conflict between this document and a signed customer agreement should be escalated promptly. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0002 — 2025-01-02 — Unit AX7300-BC-0793

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 2.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Records created under this section are retained in accordance with the company retention schedule. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0003 — 2025-01-02 — Unit AX7300-BC-0905

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 1.2 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Feedback on this document is welcome and should be sent to the owning department. Supporting templates are published on the internal documentation portal.

Entry 0004 — 2025-01-03 — Unit AX7300-BC-0061

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 3.6 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Photographic evidence should accompany any report of physical damage. Feedback on this document is welcome and should be sent to the owning department.

Entry 0005 — 2025-01-03 — Unit AX7200-BC-0657

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 3.3 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Calibration certificates are held by the metrology team and are available on request. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0006 — 2025-01-04 — Unit AX7200-BC-0218

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 1.6 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Consumable parts are excluded from the scope of the standard service agreement. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0007 — 2025-01-04 — Unit AX7200-BC-0085

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 3.6 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Supporting templates are published on the internal documentation portal. Nothing in this section overrides an applicable statutory obligation.

Entry 0008 — 2025-01-05 — Unit AX7300-BC-0844

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 1.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Calibration certificates are held by the metrology team and are available on request. Feedback on this document is welcome and should be sent to the owning department.

Entry 0009 — 2025-01-05 — Unit AX7300-BC-0072

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 5.1 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Managers are responsible for ensuring their teams understand the requirements set out here. Supporting templates are published on the internal documentation portal.

Entry 0010 — 2025-01-06 — Unit AX7200-BC-0435

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 1.1 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Supporting templates are published on the internal documentation portal. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0011 — 2025-01-06 — Unit AX7200-BC-0657

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 3.6 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Photographic evidence should accompany any report of physical damage. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0012 — 2025-01-07 — Unit AX7300-BC-0214

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 5.5 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0013 — 2025-01-07 — Unit AX7200-BC-0978

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 2.3 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Where a form is prescribed, the current version of that form must be used. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0014 — 2025-01-08 — Unit AX7300-BC-0554

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 4.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Feedback on this document is welcome and should be sent to the owning department.

Entry 0015 — 2025-01-08 — Unit AX7200-BC-0026

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 0.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Nothing in this section overrides an applicable statutory obligation. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0016 — 2025-01-09 — Unit AX7200-BC-0741

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 5.9 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

This section is reviewed each year by the responsible department head. Supporting templates are published on the internal documentation portal.

Entry 0017 — 2025-01-09 — Unit AX7300-BC-0918

Technician: S. Duplessis **Reported fault:** E-311 **Labour:** 3.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Managers are responsible for ensuring their teams understand the requirements set out here. Nothing in this section overrides an applicable statutory obligation.

Entry 0018 — 2025-01-10 — Unit AX7300-BC-0446

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 0.9 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Consumable parts are excluded from the scope of the standard service agreement. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0019 — 2025-01-10 — Unit AX7300-BC-0029

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 4.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The procedure assumes the operator has completed the standard competency assessment. Calibration certificates are held by the metrology team and are available on request.

Entry 0020 — 2025-01-11 — Unit AX7300-BC-0197

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 5.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Field teams should record ambient conditions at the start and end of every deployment. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0021 — 2025-01-11 — Unit AX7200-BC-0085

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 5.3 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

This section is reviewed each year by the responsible department head. Where a form is prescribed, the current version of that form must be used.

Entry 0022 — 2025-01-11 — Unit AX7300-BC-0216

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 0.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Calibration certificates are held by the metrology team and are available on request. Records created under this section are retained in accordance with the company retention schedule.

Entry 0023 — 2025-01-12 — Unit AX7300-BC-0023

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 5.4 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Deviation from the documented procedure must be noted in the deployment record. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0024 — 2025-01-12 — Unit AX7200-BC-0913

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 2.9 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Deviation from the documented procedure must be noted in the deployment record. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0025 — 2025-01-13 — Unit AX7200-BC-0579

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 4.2 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Exceptions require written approval from the relevant department head before the activity begins. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0026 — 2025-01-13 — Unit AX7200-BC-0602

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 1.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0027 — 2025-01-14 — Unit AX7300-BC-0321

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 4.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Feedback on this document is welcome and should be sent to the owning department.

Entry 0028 — 2025-01-14 — Unit AX7200-BC-0710

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 4.4 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Where a form is prescribed, the current version of that form must be used. Records created under this section are retained in accordance with the company retention schedule.

Entry 0029 — 2025-01-15 — Unit AX7200-BC-0026

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 5.5 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Deviation from the documented procedure must be noted in the deployment record. Photographic evidence should accompany any report of physical damage.

Entry 0030 — 2025-01-15 — Unit AX7200-BC-0492

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 0.9 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Calibration certificates are held by the metrology team and are available on request. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0031 — 2025-01-16 — Unit AX7300-BC-0666

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 3.5 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Where a form is prescribed, the current version of that form must be used. Nothing in this section overrides an applicable statutory obligation.

Entry 0032 — 2025-01-16 — Unit AX7200-BC-0579

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 4.8 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Training on this section forms part of the standard onboarding programme. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0033 — 2025-01-17 — Unit AX7300-BC-0535

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 2.0 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Where a form is prescribed, the current version of that form must be used. Nothing in this section overrides an applicable statutory obligation.

Entry 0034 — 2025-01-17 — Unit AX7300-BC-0161

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 5.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0035 — 2025-01-18 — Unit AX7200-BC-0961

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 4.9 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Any conflict between this document and a signed customer agreement should be escalated promptly. This section is reviewed each year by the responsible department head.

Entry 0036 — 2025-01-18 — Unit AX7300-BC-0442

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 5.2 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Field teams should record ambient conditions at the start and end of every deployment. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0037 — 2025-01-19 — Unit AX7300-BC-0807

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 1.2 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Calibration certificates are held by the metrology team and are available on request. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0038 — 2025-01-19 — Unit AX7300-BC-0993

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 5.3 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0039 — 2025-01-20 — Unit AX7300-BC-0838

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 4.1 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Managers are responsible for ensuring their teams understand the requirements set out here. Calibration certificates are held by the metrology team and are available on request.

Entry 0040 — 2025-01-20 — Unit AX7300-BC-0621

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 0.5 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Field teams should record ambient conditions at the start and end of every deployment. Where a form is prescribed, the current version of that form must be used.

Entry 0041 — 2025-01-20 — Unit AX7200-BC-0480

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 2.4 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Photographic evidence should accompany any report of physical damage.

Entry 0042 — 2025-01-21 — Unit AX7300-BC-0938

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 5.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Serial numbers must be transcribed exactly as they appear on the unit label. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0043 — 2025-01-21 — Unit AX7200-BC-0440

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 5.9 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Photographic evidence should accompany any report of physical damage. The procedure assumes the operator has completed the standard competency assessment.

Entry 0044 — 2025-01-22 — Unit AX7300-BC-0913

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 1.5 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Questions about the interpretation of this section should be directed to your manager in the first instance. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0045 — 2025-01-22 — Unit AX7200-BC-0763

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 3.3 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The depot maintains a rolling stock of common spares to reduce turnaround time. Deviation from the documented procedure must be noted in the deployment record.

Entry 0046 — 2025-01-23 — Unit AX7200-BC-0312

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 3.1 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

This section is reviewed each year by the responsible department head. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0047 — 2025-01-23 — Unit AX7300-BC-0477

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 4.7 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Supporting templates are published on the internal documentation portal. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0048 — 2025-01-24 — Unit AX7300-BC-0562

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 1.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. This section is reviewed each year by the responsible department head.

Entry 0049 — 2025-01-24 — Unit AX7300-BC-0016

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 2.9 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Any conflict between this document and a signed customer agreement should be escalated promptly. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0050 — 2025-01-25 — Unit AX7200-BC-0777

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 2.2 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Questions about the interpretation of this section should be directed to your manager in the first instance. Records created under this section are retained in accordance with the company retention schedule.

Entry 0051 — 2025-01-25 — Unit AX7200-BC-0876

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 5.0 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. This section is reviewed each year by the responsible department head.

Entry 0052 — 2025-01-26 — Unit AX7200-BC-0144

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 4.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0053 — 2025-01-26 — Unit AX7300-BC-0619

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 1.0 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Serial numbers must be transcribed exactly as they appear on the unit label. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0054 — 2025-01-27 — Unit AX7200-BC-0107

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.7 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Exceptions require written approval from the relevant department head before the activity begins. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0055 — 2025-01-27 — Unit AX7200-BC-0735

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 3.1 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Exceptions require written approval from the relevant department head before the activity begins. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0056 — 2025-01-28 — Unit AX7200-BC-0140

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 5.7 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Photographic evidence should accompany any report of physical damage.

Entry 0057 — 2025-01-28 — Unit AX7200-BC-0008

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 0.9 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0058 — 2025-01-29 — Unit AX7200-BC-0336

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 4.9 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Deviation from the documented procedure must be noted in the deployment record. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0059 — 2025-01-29 — Unit AX7300-BC-0219

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 2.9 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Photographic evidence should accompany any report of physical damage. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0060 — 2025-01-29 — Unit AX7200-BC-0373

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 5.6 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Nothing in this section overrides an applicable statutory obligation. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0061 — 2025-01-30 — Unit AX7200-BC-0704

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 3.1 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Supporting templates are published on the internal documentation portal. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0062 — 2025-01-30 — Unit AX7200-BC-0958

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 1.1 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Exceptions require written approval from the relevant department head before the activity begins. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0063 — 2025-01-31 — Unit AX7200-BC-0134

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 3.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Managers are responsible for ensuring their teams understand the requirements set out here. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0064 — 2025-01-31 — Unit AX7200-BC-0870

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 0.5 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Training on this section forms part of the standard onboarding programme. Where a form is prescribed, the current version of that form must be used.

Entry 0065 — 2025-02-01 — Unit AX7200-BC-0671

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 2.2 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Training on this section forms part of the standard onboarding programme.

Entry 0066 — 2025-02-01 — Unit AX7300-BC-0785

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 0.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Field teams should record ambient conditions at the start and end of every deployment. The procedure assumes the operator has completed the standard competency assessment.

Entry 0067 — 2025-02-02 — Unit AX7200-BC-0612

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 1.0 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Photographic evidence should accompany any report of physical damage. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0068 — 2025-02-02 — Unit AX7300-BC-0660

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 4.5 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Photographic evidence should accompany any report of physical damage. Deviation from the documented procedure must be noted in the deployment record.

Entry 0069 — 2025-02-03 — Unit AX7300-BC-0679

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 2.1 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Records created under this section are retained in accordance with the company retention schedule. Feedback on this document is welcome and should be sent to the owning department.

Entry 0070 — 2025-02-03 — Unit AX7300-BC-0323

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 3.7 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Photographic evidence should accompany any report of physical damage. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0071 — 2025-02-04 — Unit AX7300-BC-0326

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 1.2 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Calibration certificates are held by the metrology team and are available on request. Photographic evidence should accompany any report of physical damage.

Entry 0072 — 2025-02-04 — Unit AX7200-BC-0237

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 3.2 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Where a form is prescribed, the current version of that form must be used. This section is reviewed each year by the responsible department head.

Entry 0073 — 2025-02-05 — Unit AX7200-BC-0389

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 0.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Field teams should record ambient conditions at the start and end of every deployment. Photographic evidence should accompany any report of physical damage.

Entry 0074 — 2025-02-05 — Unit AX7200-BC-0048

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 2.5 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0075 — 2025-02-06 — Unit AX7300-BC-0975

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 5.6 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Deviation from the documented procedure must be noted in the deployment record. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0076 — 2025-02-06 — Unit AX7300-BC-0649

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 0.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Questions about the interpretation of this section should be directed to your manager in the first instance. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0077 — 2025-02-07 — Unit AX7200-BC-0567

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 4.0 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Photographic evidence should accompany any report of physical damage. Training on this section forms part of the standard onboarding programme.

Entry 0078 — 2025-02-07 — Unit AX7300-BC-0048

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 3.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Feedback on this document is welcome and should be sent to the owning department.

Entry 0079 — 2025-02-07 — Unit AX7200-BC-0237

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 4.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Deviation from the documented procedure must be noted in the deployment record. The procedure assumes the operator has completed the standard competency assessment.

Entry 0080 — 2025-02-08 — Unit AX7200-BC-0819

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 1.9 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Records created under this section are retained in accordance with the company retention schedule. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0081 — 2025-02-08 — Unit AX7300-BC-0602

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 2.2 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Deviation from the documented procedure must be noted in the deployment record. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0082 — 2025-02-09 — Unit AX7300-BC-0471

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 2.3 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Exceptions require written approval from the relevant department head before the activity begins. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0083 — 2025-02-09 — Unit AX7200-BC-0401

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 4.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Calibration certificates are held by the metrology team and are available on request. Nothing in this section overrides an applicable statutory obligation.

Entry 0084 — 2025-02-10 — Unit AX7200-BC-0721

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 2.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0085 — 2025-02-10 — Unit AX7200-BC-0707

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 5.8 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Nothing in this section overrides an applicable statutory obligation. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0086 — 2025-02-11 — Unit AX7200-BC-0146

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 3.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Managers are responsible for ensuring their teams understand the requirements set out here. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0087 — 2025-02-11 — Unit AX7200-BC-0127

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 4.5 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Deviation from the documented procedure must be noted in the deployment record. Where a form is prescribed, the current version of that form must be used.

Entry 0088 — 2025-02-12 — Unit AX7200-BC-0921

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 3.4 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Feedback on this document is welcome and should be sent to the owning department. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0089 — 2025-02-12 — Unit AX7200-BC-0832

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 5.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Consumable parts are excluded from the scope of the standard service agreement. Calibration certificates are held by the metrology team and are available on request.

Entry 0090 — 2025-02-13 — Unit AX7300-BC-0190

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 2.1 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0091 — 2025-02-13 — Unit AX7300-BC-0918

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 1.8 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Records created under this section are retained in accordance with the company retention schedule. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0092 — 2025-02-14 — Unit AX7300-BC-0248

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 2.7 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Supporting templates are published on the internal documentation portal. Calibration certificates are held by the metrology team and are available on request.

Entry 0093 — 2025-02-14 — Unit AX7300-BC-0910

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 4.4 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Where a form is prescribed, the current version of that form must be used. Deviation from the documented procedure must be noted in the deployment record.

Entry 0094 — 2025-02-15 — Unit AX7300-BC-0987

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 3.9 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Consumable parts are excluded from the scope of the standard service agreement. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0095 — 2025-02-15 — Unit AX7200-BC-0883

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 2.3 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The company reviews these arrangements periodically and may revise them with reasonable notice. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0096 — 2025-02-16 — Unit AX7300-BC-0879

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 3.7 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Consumable parts are excluded from the scope of the standard service agreement. Where a form is prescribed, the current version of that form must be used.

Entry 0097 — 2025-02-16 — Unit AX7300-BC-0777

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 1.3 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Deviation from the documented procedure must be noted in the deployment record. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0098 — 2025-02-16 — Unit AX7200-BC-0919

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 5.4 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Nothing in this section overrides an applicable statutory obligation. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0099 — 2025-02-17 — Unit AX7300-BC-0072

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 5.5 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Serial numbers must be transcribed exactly as they appear on the unit label. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0100 — 2025-02-17 — Unit AX7300-BC-0397

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 2.0 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Records created under this section are retained in accordance with the company retention schedule. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0101 — 2025-02-18 — Unit AX7300-BC-0867

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 4.3 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

The company reviews these arrangements periodically and may revise them with reasonable notice. Photographic evidence should accompany any report of physical damage.

Entry 0102 — 2025-02-18 — Unit AX7300-BC-0580

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 1.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Any conflict between this document and a signed customer agreement should be escalated promptly. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0103 — 2025-02-19 — Unit AX7300-BC-0668

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 0.9 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The company reviews these arrangements periodically and may revise them with reasonable notice. Where a form is prescribed, the current version of that form must be used.

Entry 0104 — 2025-02-19 — Unit AX7300-BC-0780

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 3.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Photographic evidence should accompany any report of physical damage. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0105 — 2025-02-20 — Unit AX7300-BC-0362

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 1.9 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Questions about the interpretation of this section should be directed to your manager in the first instance. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0106 — 2025-02-20 — Unit AX7300-BC-0966

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 1.2 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Feedback on this document is welcome and should be sent to the owning department. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0107 — 2025-02-21 — Unit AX7200-BC-0802

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 4.0 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Where a form is prescribed, the current version of that form must be used.

Entry 0108 — 2025-02-21 — Unit AX7300-BC-0221

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 1.6 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Exceptions require written approval from the relevant department head before the activity begins. Deviation from the documented procedure must be noted in the deployment record.

Entry 0109 — 2025-02-22 — Unit AX7200-BC-0386

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 2.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Deviation from the documented procedure must be noted in the deployment record. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0110 — 2025-02-22 — Unit AX7300-BC-0677

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 3.8 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0111 — 2025-02-23 — Unit AX7300-BC-0525

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 0.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Serial numbers must be transcribed exactly as they appear on the unit label. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0112 — 2025-02-23 — Unit AX7300-BC-0919

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 3.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

This section is reviewed each year by the responsible department head. Nothing in this section overrides an applicable statutory obligation.

Entry 0113 — 2025-02-24 — Unit AX7300-BC-0877

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 1.1 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Supporting templates are published on the internal documentation portal. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0114 — 2025-02-24 — Unit AX7300-BC-0594

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 3.0 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Records created under this section are retained in accordance with the company retention schedule. Photographic evidence should accompany any report of physical damage.

Entry 0115 — 2025-02-25 — Unit AX7300-BC-0635

Technician: R. Fairweather **Reported fault:** E-311 **Labour:** 2.9 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Managers are responsible for ensuring their teams understand the requirements set out here. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0116 — 2025-02-25 — Unit AX7300-BC-0371

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 1.8 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0117 — 2025-02-25 — Unit AX7200-BC-0437

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 3.2 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Calibration certificates are held by the metrology team and are available on request. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0118 — 2025-02-26 — Unit AX7300-BC-0558

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 4.7 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Serial numbers must be transcribed exactly as they appear on the unit label. Nothing in this section overrides an applicable statutory obligation.

Entry 0119 — 2025-02-26 — Unit AX7300-BC-0620

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 4.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Training on this section forms part of the standard onboarding programme.

Entry 0120 — 2025-02-27 — Unit AX7300-BC-0915

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 5.1 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

This section is reviewed each year by the responsible department head. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0121 — 2025-02-27 — Unit AX7200-BC-0977

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 0.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The procedure assumes the operator has completed the standard competency assessment. Supporting templates are published on the internal documentation portal.

Entry 0122 — 2025-02-28 — Unit AX7300-BC-0925

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 2.8 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Serial numbers must be transcribed exactly as they appear on the unit label. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0123 — 2025-02-28 — Unit AX7300-BC-0539

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 1.6 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Deviation from the documented procedure must be noted in the deployment record. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0124 — 2025-03-01 — Unit AX7200-BC-0849

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 1.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Exceptions require written approval from the relevant department head before the activity begins. The procedure assumes the operator has completed the standard competency assessment.

Entry 0125 — 2025-03-01 — Unit AX7200-BC-0889

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 4.0 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0126 — 2025-03-02 — Unit AX7200-BC-0487

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 4.7 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

This section is reviewed each year by the responsible department head. Training on this section forms part of the standard onboarding programme.

Entry 0127 — 2025-03-02 — Unit AX7300-BC-0305

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 2.9 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Where a form is prescribed, the current version of that form must be used. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0128 — 2025-03-03 — Unit AX7200-BC-0621

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 3.3 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Consumable parts are excluded from the scope of the standard service agreement. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0129 — 2025-03-03 — Unit AX7300-BC-0008

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 4.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Serial numbers must be transcribed exactly as they appear on the unit label. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0130 — 2025-03-04 — Unit AX7300-BC-0834

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 2.4 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Questions about the interpretation of this section should be directed to your manager in the first instance. Nothing in this section overrides an applicable statutory obligation.

Entry 0131 — 2025-03-04 — Unit AX7300-BC-0519

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 2.4 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Training on this section forms part of the standard onboarding programme. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0132 — 2025-03-05 — Unit AX7300-BC-0789

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 5.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0133 — 2025-03-05 — Unit AX7300-BC-0127

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 2.2 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Field teams should record ambient conditions at the start and end of every deployment. Calibration certificates are held by the metrology team and are available on request.

Entry 0134 — 2025-03-05 — Unit AX7300-BC-0931

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 0.9 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Where a form is prescribed, the current version of that form must be used. Feedback on this document is welcome and should be sent to the owning department.

Entry 0135 — 2025-03-06 — Unit AX7200-BC-0351

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 0.9 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0136 — 2025-03-06 — Unit AX7200-BC-0068

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 5.9 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Nothing in this section overrides an applicable statutory obligation. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0137 — 2025-03-07 — Unit AX7300-BC-0283

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 2.3 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. The procedure assumes the operator has completed the standard competency assessment.

Entry 0138 — 2025-03-07 — Unit AX7300-BC-0284

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 4.8 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Where a form is prescribed, the current version of that form must be used.

Entry 0139 — 2025-03-08 — Unit AX7300-BC-0126

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 1.4 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Feedback on this document is welcome and should be sent to the owning department. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0140 — 2025-03-08 — Unit AX7300-BC-0583

Technician: S. Duplessis **Reported fault:** E-311 **Labour:** 3.8 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Photographic evidence should accompany any report of physical damage. Supporting templates are published on the internal documentation portal.

Entry 0141 — 2025-03-09 — Unit AX7200-BC-0351

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 2.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0142 — 2025-03-09 — Unit AX7200-BC-0763

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 5.5 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Questions about the interpretation of this section should be directed to your manager in the first instance. Supporting templates are published on the internal documentation portal.

Entry 0143 — 2025-03-10 — Unit AX7200-BC-0873

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 5.6 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Nothing in this section overrides an applicable statutory obligation. This section is reviewed each year by the responsible department head.

Entry 0144 — 2025-03-10 — Unit AX7300-BC-0460

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 5.7 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Supporting templates are published on the internal documentation portal. Nothing in this section overrides an applicable statutory obligation.

Entry 0145 — 2025-03-11 — Unit AX7200-BC-0236

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 1.3 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Shipping arrangements are confirmed in writing before any unit leaves the depot. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0146 — 2025-03-11 — Unit AX7200-BC-0197

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 5.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The depot maintains a rolling stock of common spares to reduce turnaround time. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0147 — 2025-03-12 — Unit AX7200-BC-0467

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 2.4 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Questions about the interpretation of this section should be directed to your manager in the first instance. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0148 — 2025-03-12 — Unit AX7300-BC-0852

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 5.6 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Feedback on this document is welcome and should be sent to the owning department. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0149 — 2025-03-13 — Unit AX7300-BC-0360

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 0.7 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0150 — 2025-03-13 — Unit AX7300-BC-0887

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 4.6 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Serial numbers must be transcribed exactly as they appear on the unit label. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0151 — 2025-03-14 — Unit AX7300-BC-0437

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 1.0 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Deviation from the documented procedure must be noted in the deployment record. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0152 — 2025-03-14 — Unit AX7200-BC-0186

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 4.5 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The depot maintains a rolling stock of common spares to reduce turnaround time. Supporting templates are published on the internal documentation portal.

Entry 0153 — 2025-03-15 — Unit AX7200-BC-0266

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 5.6 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Consumable parts are excluded from the scope of the standard service agreement. This section is reviewed each year by the responsible department head.

Entry 0154 — 2025-03-15 — Unit AX7200-BC-0753

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 1.6 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0155 — 2025-03-15 — Unit AX7200-BC-0136

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 5.2 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Records created under this section are retained in accordance with the company retention schedule. This section is reviewed each year by the responsible department head.

Entry 0156 — 2025-03-16 — Unit AX7200-BC-0820

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 1.7 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The depot maintains a rolling stock of common spares to reduce turnaround time. This section is reviewed each year by the responsible department head.

Entry 0157 — 2025-03-16 — Unit AX7300-BC-0680

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 3.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Consumable parts are excluded from the scope of the standard service agreement. Training on this section forms part of the standard onboarding programme.

Entry 0158 — 2025-03-17 — Unit AX7300-BC-0350

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 4.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Exceptions require written approval from the relevant department head before the activity begins. Calibration certificates are held by the metrology team and are available on request.

Entry 0159 — 2025-03-17 — Unit AX7200-BC-0276

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 3.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Where a form is prescribed, the current version of that form must be used. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0160 — 2025-03-18 — Unit AX7300-BC-0978

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 1.2 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Training on this section forms part of the standard onboarding programme. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0161 — 2025-03-18 — Unit AX7300-BC-0141

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 2.3 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Nothing in this section overrides an applicable statutory obligation. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0162 — 2025-03-19 — Unit AX7300-BC-0184

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 1.3 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

This section is reviewed each year by the responsible department head. Records created under this section are retained in accordance with the company retention schedule.

Entry 0163 — 2025-03-19 — Unit AX7200-BC-0639

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 1.4 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Training on this section forms part of the standard onboarding programme. Nothing in this section overrides an applicable statutory obligation.

Entry 0164 — 2025-03-20 — Unit AX7300-BC-0844

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 1.3 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Where a form is prescribed, the current version of that form must be used. This section is reviewed each year by the responsible department head.

Entry 0165 — 2025-03-20 — Unit AX7200-BC-0920

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 1.2 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Nothing in this section overrides an applicable statutory obligation. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0166 — 2025-03-21 — Unit AX7200-BC-0966

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 1.2 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Supporting templates are published on the internal documentation portal. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0167 — 2025-03-21 — Unit AX7300-BC-0845

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 3.8 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Exceptions require written approval from the relevant department head before the activity begins. Photographic evidence should accompany any report of physical damage.

Entry 0168 — 2025-03-22 — Unit AX7200-BC-0065

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 3.2 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0169 — 2025-03-22 — Unit AX7300-BC-0201

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 3.9 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

The company reviews these arrangements periodically and may revise them with reasonable notice. The procedure assumes the operator has completed the standard competency assessment.

Entry 0170 — 2025-03-23 — Unit AX7300-BC-0883

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 1.8 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Records created under this section are retained in accordance with the company retention schedule. Deviation from the documented procedure must be noted in the deployment record.

Entry 0171 — 2025-03-23 — Unit AX7300-BC-0624

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 4.1 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Photographic evidence should accompany any report of physical damage. Feedback on this document is welcome and should be sent to the owning department.

Entry 0172 — 2025-03-24 — Unit AX7200-BC-0121

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 4.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

The depot maintains a rolling stock of common spares to reduce turnaround time. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0173 — 2025-03-24 — Unit AX7200-BC-0663

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 3.2 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

The company reviews these arrangements periodically and may revise them with reasonable notice. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0174 — 2025-03-24 — Unit AX7300-BC-0981

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 3.0 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The procedure assumes the operator has completed the standard competency assessment. Photographic evidence should accompany any report of physical damage.

Entry 0175 — 2025-03-25 — Unit AX7300-BC-0410

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 5.5 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Field teams should record ambient conditions at the start and end of every deployment. Training on this section forms part of the standard onboarding programme.

Entry 0176 — 2025-03-25 — Unit AX7200-BC-0139

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 4.6 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Shipping arrangements are confirmed in writing before any unit leaves the depot. This section is reviewed each year by the responsible department head.

Entry 0177 — 2025-03-26 — Unit AX7200-BC-0441

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 3.4 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Feedback on this document is welcome and should be sent to the owning department. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0178 — 2025-03-26 — Unit AX7200-BC-0018

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 1.5 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Serial numbers must be transcribed exactly as they appear on the unit label. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0179 — 2025-03-27 — Unit AX7200-BC-0898

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 4.3 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Serial numbers must be transcribed exactly as they appear on the unit label. Feedback on this document is welcome and should be sent to the owning department.

Entry 0180 — 2025-03-27 — Unit AX7300-BC-0611

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 2.7 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Feedback on this document is welcome and should be sent to the owning department.

Entry 0181 — 2025-03-28 — Unit AX7200-BC-0374

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 4.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Supporting templates are published on the internal documentation portal. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0182 — 2025-03-28 — Unit AX7300-BC-0993

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 2.9 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Where a form is prescribed, the current version of that form must be used. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0183 — 2025-03-29 — Unit AX7300-BC-0626

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 4.1 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Managers are responsible for ensuring their teams understand the requirements set out here. Feedback on this document is welcome and should be sent to the owning department.

Entry 0184 — 2025-03-29 — Unit AX7300-BC-0822

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 5.9 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Records created under this section are retained in accordance with the company retention schedule. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0185 — 2025-03-30 — Unit AX7200-BC-0666

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 1.6 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Serial numbers must be transcribed exactly as they appear on the unit label. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0186 — 2025-03-30 — Unit AX7200-BC-0750

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 5.7 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Photographic evidence should accompany any report of physical damage.

Entry 0187 — 2025-03-31 — Unit AX7200-BC-0804

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 3.8 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

The depot maintains a rolling stock of common spares to reduce turnaround time. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0188 — 2025-03-31 — Unit AX7200-BC-0752

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 4.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Deviation from the documented procedure must be noted in the deployment record. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0189 — 2025-04-01 — Unit AX7200-BC-0208

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 2.0 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

This section is reviewed each year by the responsible department head. Calibration certificates are held by the metrology team and are available on request.

Entry 0190 — 2025-04-01 — Unit AX7200-BC-0182

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 3.8 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Training on this section forms part of the standard onboarding programme. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0191 — 2025-04-02 — Unit AX7300-BC-0426

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 2.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Serial numbers must be transcribed exactly as they appear on the unit label. Photographic evidence should accompany any report of physical damage.

Entry 0192 — 2025-04-02 — Unit AX7300-BC-0052

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 1.5 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

The procedure assumes the operator has completed the standard competency assessment. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0193 — 2025-04-02 — Unit AX7200-BC-0957

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 3.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Any conflict between this document and a signed customer agreement should be escalated promptly. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0194 — 2025-04-03 — Unit AX7300-BC-0524

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 4.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Supporting templates are published on the internal documentation portal.

Entry 0195 — 2025-04-03 — Unit AX7300-BC-0811

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 3.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The depot maintains a rolling stock of common spares to reduce turnaround time. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0196 — 2025-04-04 — Unit AX7200-BC-0146

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 0.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

The procedure assumes the operator has completed the standard competency assessment. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0197 — 2025-04-04 — Unit AX7300-BC-0459

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 0.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Records created under this section are retained in accordance with the company retention schedule. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0198 — 2025-04-05 — Unit AX7300-BC-0669

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 5.5 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Field teams should record ambient conditions at the start and end of every deployment. Deviation from the documented procedure must be noted in the deployment record.

Entry 0199 — 2025-04-05 — Unit AX7200-BC-0343

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 3.0 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Questions about the interpretation of this section should be directed to your manager in the first instance. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0200 — 2025-04-06 — Unit AX7200-BC-0299

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 3.1 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Where a form is prescribed, the current version of that form must be used. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0201 — 2025-04-06 — Unit AX7200-BC-0942

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 4.3 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Feedback on this document is welcome and should be sent to the owning department. Supporting templates are published on the internal documentation portal.

Entry 0202 — 2025-04-07 — Unit AX7300-BC-0638

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

This section is reviewed each year by the responsible department head. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0203 — 2025-04-07 — Unit AX7200-BC-0846

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 3.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Questions about the interpretation of this section should be directed to your manager in the first instance. Calibration certificates are held by the metrology team and are available on request.

Entry 0204 — 2025-04-08 — Unit AX7300-BC-0876

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 3.8 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Serial numbers must be transcribed exactly as they appear on the unit label. Records created under this section are retained in accordance with the company retention schedule.

Entry 0205 — 2025-04-08 — Unit AX7300-BC-0416

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 0.9 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Records created under this section are retained in accordance with the company retention schedule. Training on this section forms part of the standard onboarding programme.

Entry 0206 — 2025-04-09 — Unit AX7200-BC-0052

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 2.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Deviation from the documented procedure must be noted in the deployment record. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0207 — 2025-04-09 — Unit AX7300-BC-0200

Technician: R. Fairweather **Reported fault:** E-311 **Labour:** 5.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Training on this section forms part of the standard onboarding programme. This section is reviewed each year by the responsible department head.

Entry 0208 — 2025-04-10 — Unit AX7300-BC-0873

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 2.0 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Exceptions require written approval from the relevant department head before the activity begins. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0209 — 2025-04-10 — Unit AX7300-BC-0010

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 2.0 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Consumable parts are excluded from the scope of the standard service agreement. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0210 — 2025-04-11 — Unit AX7200-BC-0766

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 4.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Deviation from the documented procedure must be noted in the deployment record. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0211 — 2025-04-11 — Unit AX7200-BC-0924

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 3.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0212 — 2025-04-11 — Unit AX7200-BC-0340

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 4.2 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Deviation from the documented procedure must be noted in the deployment record.

Entry 0213 — 2025-04-12 — Unit AX7300-BC-0204

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 4.7 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Field teams should record ambient conditions at the start and end of every deployment. Nothing in this section overrides an applicable statutory obligation.

Entry 0214 — 2025-04-12 — Unit AX7300-BC-0843

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 2.0 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Supporting templates are published on the internal documentation portal. Nothing in this section overrides an applicable statutory obligation.

Entry 0215 — 2025-04-13 — Unit AX7300-BC-0857

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 6.0 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Where a form is prescribed, the current version of that form must be used.

Entry 0216 — 2025-04-13 — Unit AX7200-BC-0637

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 0.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Photographic evidence should accompany any report of physical damage. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0217 — 2025-04-14 — Unit AX7200-BC-0549

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 5.5 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Deviation from the documented procedure must be noted in the deployment record. Supporting templates are published on the internal documentation portal.

Entry 0218 — 2025-04-14 — Unit AX7200-BC-0337

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 2.5 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Serial numbers must be transcribed exactly as they appear on the unit label. This section is reviewed each year by the responsible department head.

Entry 0219 — 2025-04-15 — Unit AX7300-BC-0143

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 3.9 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Records created under this section are retained in accordance with the company retention schedule. Calibration certificates are held by the metrology team and are available on request.

Entry 0220 — 2025-04-15 — Unit AX7200-BC-0694

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 2.5 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The procedure assumes the operator has completed the standard competency assessment. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0221 — 2025-04-16 — Unit AX7200-BC-0229

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 5.2 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Deviation from the documented procedure must be noted in the deployment record. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0222 — 2025-04-16 — Unit AX7300-BC-0324

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 5.7 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

This section is reviewed each year by the responsible department head. Deviation from the documented procedure must be noted in the deployment record.

Entry 0223 — 2025-04-17 — Unit AX7200-BC-0371

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 2.5 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Serial numbers must be transcribed exactly as they appear on the unit label. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0224 — 2025-04-17 — Unit AX7300-BC-0529

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 3.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0225 — 2025-04-18 — Unit AX7200-BC-0547

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 4.8 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Managers are responsible for ensuring their teams understand the requirements set out here. Training on this section forms part of the standard onboarding programme.

Entry 0226 — 2025-04-18 — Unit AX7200-BC-0311

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 5.3 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The depot maintains a rolling stock of common spares to reduce turnaround time. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0227 — 2025-04-19 — Unit AX7200-BC-0969

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 3.6 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Nothing in this section overrides an applicable statutory obligation. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0228 — 2025-04-19 — Unit AX7200-BC-0308

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 1.0 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Training on this section forms part of the standard onboarding programme.

Entry 0229 — 2025-04-20 — Unit AX7300-BC-0736

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 2.4 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Questions about the interpretation of this section should be directed to your manager in the first instance. Feedback on this document is welcome and should be sent to the owning department.

Entry 0230 — 2025-04-20 — Unit AX7200-BC-0355

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 0.9 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Photographic evidence should accompany any report of physical damage. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0231 — 2025-04-20 — Unit AX7300-BC-0397

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 1.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Where a form is prescribed, the current version of that form must be used. Supporting templates are published on the internal documentation portal.

Entry 0232 — 2025-04-21 — Unit AX7200-BC-0941

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 5.1 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

The depot maintains a rolling stock of common spares to reduce turnaround time. Photographic evidence should accompany any report of physical damage.

Entry 0233 — 2025-04-21 — Unit AX7200-BC-0700

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 1.5 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Feedback on this document is welcome and should be sent to the owning department. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0234 — 2025-04-22 — Unit AX7300-BC-0874

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 1.9 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Nothing in this section overrides an applicable statutory obligation. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0235 — 2025-04-22 — Unit AX7300-BC-0628

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 5.1 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Supporting templates are published on the internal documentation portal. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0236 — 2025-04-23 — Unit AX7300-BC-0148

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 0.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Consumable parts are excluded from the scope of the standard service agreement. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0237 — 2025-04-23 — Unit AX7300-BC-0828

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 0.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The procedure assumes the operator has completed the standard competency assessment. Nothing in this section overrides an applicable statutory obligation.

Entry 0238 — 2025-04-24 — Unit AX7200-BC-0467

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 4.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Consumable parts are excluded from the scope of the standard service agreement. The procedure assumes the operator has completed the standard competency assessment.

Entry 0239 — 2025-04-24 — Unit AX7300-BC-0607

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 3.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Any conflict between this document and a signed customer agreement should be escalated promptly. Training on this section forms part of the standard onboarding programme.

Entry 0240 — 2025-04-25 — Unit AX7200-BC-0434

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 1.6 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Training on this section forms part of the standard onboarding programme. Photographic evidence should accompany any report of physical damage.

Entry 0241 — 2025-04-25 — Unit AX7200-BC-0752

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 4.9 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Questions about the interpretation of this section should be directed to your manager in the first instance. Photographic evidence should accompany any report of physical damage.

Entry 0242 — 2025-04-26 — Unit AX7300-BC-0936

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 3.0 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Nothing in this section overrides an applicable statutory obligation. The procedure assumes the operator has completed the standard competency assessment.

Entry 0243 — 2025-04-26 — Unit AX7200-BC-0870

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 6.0 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

This section is reviewed each year by the responsible department head. Feedback on this document is welcome and should be sent to the owning department.

Entry 0244 — 2025-04-27 — Unit AX7200-BC-0536

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 5.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Where a form is prescribed, the current version of that form must be used. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0245 — 2025-04-27 — Unit AX7300-BC-0234

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 4.5 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Managers are responsible for ensuring their teams understand the requirements set out here. The procedure assumes the operator has completed the standard competency assessment.

Entry 0246 — 2025-04-28 — Unit AX7200-BC-0721

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 5.2 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Calibration certificates are held by the metrology team and are available on request. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0247 — 2025-04-28 — Unit AX7200-BC-0773

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 1.2 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Exceptions require written approval from the relevant department head before the activity begins. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0248 — 2025-04-29 — Unit AX7300-BC-0723

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 4.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The procedure assumes the operator has completed the standard competency assessment. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0249 — 2025-04-29 — Unit AX7200-BC-0320

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 5.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Shipping arrangements are confirmed in writing before any unit leaves the depot. The procedure assumes the operator has completed the standard competency assessment.

Entry 0250 — 2025-04-29 — Unit AX7200-BC-0213

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 2.3 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Calibration certificates are held by the metrology team and are available on request.

Entry 0251 — 2025-04-30 — Unit AX7300-BC-0642

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 2.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Any conflict between this document and a signed customer agreement should be escalated promptly. Photographic evidence should accompany any report of physical damage.

Entry 0252 — 2025-04-30 — Unit AX7200-BC-0294

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 4.9 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0253 — 2025-05-01 — Unit AX7300-BC-0875

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 1.8 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The procedure assumes the operator has completed the standard competency assessment. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0254 — 2025-05-01 — Unit AX7200-BC-0091

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 2.4 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The procedure assumes the operator has completed the standard competency assessment. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0255 — 2025-05-02 — Unit AX7300-BC-0776

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 5.1 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Where a form is prescribed, the current version of that form must be used. Records created under this section are retained in accordance with the company retention schedule.

Entry 0256 — 2025-05-02 — Unit AX7300-BC-0641

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 2.1 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Records created under this section are retained in accordance with the company retention schedule. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0257 — 2025-05-03 — Unit AX7200-BC-0549

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 4.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Photographic evidence should accompany any report of physical damage.

Entry 0258 — 2025-05-03 — Unit AX7200-BC-0297

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 0.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Any conflict between this document and a signed customer agreement should be escalated promptly. This section is reviewed each year by the responsible department head.

Entry 0259 — 2025-05-04 — Unit AX7300-BC-0012

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 2.5 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Field teams should record ambient conditions at the start and end of every deployment. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0260 — 2025-05-04 — Unit AX7300-BC-0896

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 1.9 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The procedure assumes the operator has completed the standard competency assessment. Feedback on this document is welcome and should be sent to the owning department.

Entry 0261 — 2025-05-05 — Unit AX7300-BC-0531

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 1.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0262 — 2025-05-05 — Unit AX7300-BC-0616

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 4.7 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Serial numbers must be transcribed exactly as they appear on the unit label. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0263 — 2025-05-06 — Unit AX7300-BC-0830

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 2.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Records created under this section are retained in accordance with the company retention schedule. Supporting templates are published on the internal documentation portal.

Entry 0264 — 2025-05-06 — Unit AX7300-BC-0157

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 2.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0265 — 2025-05-07 — Unit AX7300-BC-0657

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 5.1 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. This section is reviewed each year by the responsible department head.

Entry 0266 — 2025-05-07 — Unit AX7300-BC-0674

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 2.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Photographic evidence should accompany any report of physical damage. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0267 — 2025-05-07 — Unit AX7300-BC-0563

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 3.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Serial numbers must be transcribed exactly as they appear on the unit label. Training on this section forms part of the standard onboarding programme.

Entry 0268 — 2025-05-08 — Unit AX7300-BC-0421

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 4.9 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

The company reviews these arrangements periodically and may revise them with reasonable notice. Calibration certificates are held by the metrology team and are available on request.

Entry 0269 — 2025-05-08 — Unit AX7200-BC-0088

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 5.9 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Managers are responsible for ensuring their teams understand the requirements set out here. Deviation from the documented procedure must be noted in the deployment record.

Entry 0270 — 2025-05-09 — Unit AX7200-BC-0694

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 5.5 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Field teams should record ambient conditions at the start and end of every deployment. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0271 — 2025-05-09 — Unit AX7200-BC-0510

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 4.2 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

This section is reviewed each year by the responsible department head. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0272 — 2025-05-10 — Unit AX7200-BC-0237

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 3.1 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

This section is reviewed each year by the responsible department head. Calibration certificates are held by the metrology team and are available on request.

Entry 0273 — 2025-05-10 — Unit AX7200-BC-0873

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 5.1 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The depot maintains a rolling stock of common spares to reduce turnaround time. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0274 — 2025-05-11 — Unit AX7300-BC-0203

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 2.0 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Deviation from the documented procedure must be noted in the deployment record. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0275 — 2025-05-11 — Unit AX7200-BC-0870

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 3.4 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Questions about the interpretation of this section should be directed to your manager in the first instance. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0276 — 2025-05-12 — Unit AX7200-BC-0202

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 0.5 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Deviation from the documented procedure must be noted in the deployment record. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0277 — 2025-05-12 — Unit AX7300-BC-0195

Technician: S. Duplessis **Reported fault:** E-311 **Labour:** 4.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Records created under this section are retained in accordance with the company retention schedule. Nothing in this section overrides an applicable statutory obligation.

Entry 0278 — 2025-05-13 — Unit AX7200-BC-0543

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 5.9 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Feedback on this document is welcome and should be sent to the owning department. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0279 — 2025-05-13 — Unit AX7200-BC-0034

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 3.9 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Field teams should record ambient conditions at the start and end of every deployment. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0280 — 2025-05-14 — Unit AX7200-BC-0239

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 5.2 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Feedback on this document is welcome and should be sent to the owning department. Supporting templates are published on the internal documentation portal.

Entry 0281 — 2025-05-14 — Unit AX7300-BC-0921

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 4.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Photographic evidence should accompany any report of physical damage. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0282 — 2025-05-15 — Unit AX7200-BC-0951

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 4.3 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Feedback on this document is welcome and should be sent to the owning department. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0283 — 2025-05-15 — Unit AX7200-BC-0893

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 4.3 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Any conflict between this document and a signed customer agreement should be escalated promptly. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0284 — 2025-05-16 — Unit AX7300-BC-0305

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 3.3 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Photographic evidence should accompany any report of physical damage. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0285 — 2025-05-16 — Unit AX7200-BC-0768

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 1.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Supporting templates are published on the internal documentation portal. Photographic evidence should accompany any report of physical damage.

Entry 0286 — 2025-05-17 — Unit AX7200-BC-0279

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 3.0 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The procedure assumes the operator has completed the standard competency assessment. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0287 — 2025-05-17 — Unit AX7200-BC-0412

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 3.5 h

Action taken: Battery pack replaced under warranty. Thermal paste reapplied to the cell bridge. Unit soak-tested for six hours at 40 °C before release.

Questions about the interpretation of this section should be directed to your manager in the first instance. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0288 — 2025-05-17 — Unit AX7200-BC-0735

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 5.9 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Exceptions require written approval from the relevant department head before the activity begins. Records created under this section are retained in accordance with the company retention schedule.

Entry 0289 — 2025-05-18 — Unit AX7300-BC-0841

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 5.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Photographic evidence should accompany any report of physical damage. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0290 — 2025-05-18 — Unit AX7300-BC-0835

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 1.4 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Supporting templates are published on the internal documentation portal. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0291 — 2025-05-19 — Unit AX7200-BC-0997

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 1.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Training on this section forms part of the standard onboarding programme. Records created under this section are retained in accordance with the company retention schedule.

Entry 0292 — 2025-05-19 — Unit AX7300-BC-0620

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 3.8 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Exceptions require written approval from the relevant department head before the activity begins. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0293 — 2025-05-20 — Unit AX7200-BC-0213

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 5.4 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Exceptions require written approval from the relevant department head before the activity begins. Supporting templates are published on the internal documentation portal.

Entry 0294 — 2025-05-20 — Unit AX7200-BC-0718

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 0.8 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Managers are responsible for ensuring their teams understand the requirements set out here. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0295 — 2025-05-21 — Unit AX7300-BC-0460

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 2.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

This section is reviewed each year by the responsible department head. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0296 — 2025-05-21 — Unit AX7300-BC-0423

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 5.4 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Questions about the interpretation of this section should be directed to your manager in the first instance. Deviation from the documented procedure must be noted in the deployment record.

Entry 0297 — 2025-05-22 — Unit AX7200-BC-0360

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 4.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Photographic evidence should accompany any report of physical damage. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0298 — 2025-05-22 — Unit AX7200-BC-0240

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 0.8 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Photographic evidence should accompany any report of physical damage. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0299 — 2025-05-23 — Unit AX7200-BC-0008

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 5.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0300 — 2025-05-23 — Unit AX7200-BC-0118

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 4.4 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0301 — 2025-05-24 — Unit AX7300-BC-0968

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 1.1 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Records created under this section are retained in accordance with the company retention schedule. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0302 — 2025-05-24 — Unit AX7200-BC-0441

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 3.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Field teams should record ambient conditions at the start and end of every deployment. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0303 — 2025-05-25 — Unit AX7200-BC-0223

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 1.9 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Where local regulation imposes a stricter requirement, the stricter requirement applies. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0304 — 2025-05-25 — Unit AX7300-BC-0043

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 2.7 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0305 — 2025-05-26 — Unit AX7300-BC-0535

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 5.0 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Consumable parts are excluded from the scope of the standard service agreement. Where a form is prescribed, the current version of that form must be used.

Entry 0306 — 2025-05-26 — Unit AX7300-BC-0222

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 0.7 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Nothing in this section overrides an applicable statutory obligation. The procedure assumes the operator has completed the standard competency assessment.

Entry 0307 — 2025-05-26 — Unit AX7200-BC-0878

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 5.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

This section is reviewed each year by the responsible department head. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0308 — 2025-05-27 — Unit AX7200-BC-0753

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 3.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Nothing in this section overrides an applicable statutory obligation. Deviation from the documented procedure must be noted in the deployment record.

Entry 0309 — 2025-05-27 — Unit AX7200-BC-0519

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 3.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Photographic evidence should accompany any report of physical damage. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0310 — 2025-05-28 — Unit AX7300-BC-0615

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 3.0 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Supporting templates are published on the internal documentation portal. Nothing in this section overrides an applicable statutory obligation.

Entry 0311 — 2025-05-28 — Unit AX7200-BC-0258

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 4.1 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Records created under this section are retained in accordance with the company retention schedule. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0312 — 2025-05-29 — Unit AX7200-BC-0352

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 1.2 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0313 — 2025-05-29 — Unit AX7300-BC-0495

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 2.5 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Managers are responsible for ensuring their teams understand the requirements set out here. This section is reviewed each year by the responsible department head.

Entry 0314 — 2025-05-30 — Unit AX7300-BC-0940

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 4.3 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Feedback on this document is welcome and should be sent to the owning department. Where a form is prescribed, the current version of that form must be used.

Entry 0315 — 2025-05-30 — Unit AX7200-BC-0343

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 3.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Training on this section forms part of the standard onboarding programme. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0316 — 2025-05-31 — Unit AX7200-BC-0821

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 4.1 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Serial numbers must be transcribed exactly as they appear on the unit label. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0317 — 2025-05-31 — Unit AX7200-BC-0120

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 3.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Consumable parts are excluded from the scope of the standard service agreement. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0318 — 2025-06-01 — Unit AX7200-BC-0157

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 1.4 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Where local regulation imposes a stricter requirement, the stricter requirement applies. This section is reviewed each year by the responsible department head.

Entry 0319 — 2025-06-01 — Unit AX7200-BC-0706

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 5.8 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Feedback on this document is welcome and should be sent to the owning department. Deviation from the documented procedure must be noted in the deployment record.

Entry 0320 — 2025-06-02 — Unit AX7300-BC-0812

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 2.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Any conflict between this document and a signed customer agreement should be escalated promptly. Photographic evidence should accompany any report of physical damage.

Entry 0321 — 2025-06-02 — Unit AX7300-BC-0104

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 3.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Nothing in this section overrides an applicable statutory obligation. This section is reviewed each year by the responsible department head.

Entry 0322 — 2025-06-03 — Unit AX7300-BC-0077

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 0.9 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Records created under this section are retained in accordance with the company retention schedule. Photographic evidence should accompany any report of physical damage.

Entry 0323 — 2025-06-03 — Unit AX7300-BC-0044

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 5.4 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Nothing in this section overrides an applicable statutory obligation. The procedure assumes the operator has completed the standard competency assessment.

Entry 0324 — 2025-06-04 — Unit AX7300-BC-0736

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 2.9 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

This section is reviewed each year by the responsible department head. The procedure assumes the operator has completed the standard competency assessment.

Entry 0325 — 2025-06-04 — Unit AX7300-BC-0362

Technician: R. Fairweather **Reported fault:** E-311 **Labour:** 2.2 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The procedure assumes the operator has completed the standard competency assessment. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0326 — 2025-06-04 — Unit AX7300-BC-0081

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 2.8 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Feedback on this document is welcome and should be sent to the owning department.

Entry 0327 — 2025-06-05 — Unit AX7200-BC-0927

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 1.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The depot maintains a rolling stock of common spares to reduce turnaround time. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0328 — 2025-06-05 — Unit AX7300-BC-0478

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 1.9 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Calibration certificates are held by the metrology team and are available on request. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0329 — 2025-06-06 — Unit AX7200-BC-0209

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.7 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0330 — 2025-06-06 — Unit AX7300-BC-0309

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 3.3 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Exceptions require written approval from the relevant department head before the activity begins. Calibration certificates are held by the metrology team and are available on request.

Entry 0331 — 2025-06-07 — Unit AX7300-BC-0306

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 3.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

The company reviews these arrangements periodically and may revise them with reasonable notice. Calibration certificates are held by the metrology team and are available on request.

Entry 0332 — 2025-06-07 — Unit AX7300-BC-0765

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 4.1 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Questions about the interpretation of this section should be directed to your manager in the first instance. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0333 — 2025-06-08 — Unit AX7200-BC-0172

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 3.0 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Consumable parts are excluded from the scope of the standard service agreement. Photographic evidence should accompany any report of physical damage.

Entry 0334 — 2025-06-08 — Unit AX7300-BC-0518

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 3.9 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Consumable parts are excluded from the scope of the standard service agreement. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0335 — 2025-06-09 — Unit AX7300-BC-0232

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 4.8 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Photographic evidence should accompany any report of physical damage. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0336 — 2025-06-09 — Unit AX7200-BC-0014

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 3.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

The company reviews these arrangements periodically and may revise them with reasonable notice. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0337 — 2025-06-10 — Unit AX7200-BC-0552

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 5.4 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Records created under this section are retained in accordance with the company retention schedule.

Entry 0338 — 2025-06-10 — Unit AX7200-BC-0819

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Training on this section forms part of the standard onboarding programme. This section is reviewed each year by the responsible department head.

Entry 0339 — 2025-06-11 — Unit AX7300-BC-0799

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 3.7 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Serial numbers must be transcribed exactly as they appear on the unit label. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0340 — 2025-06-11 — Unit AX7300-BC-0903

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 3.3 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Records created under this section are retained in accordance with the company retention schedule. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0341 — 2025-06-12 — Unit AX7300-BC-0340

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 4.4 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Questions about the interpretation of this section should be directed to your manager in the first instance. Calibration certificates are held by the metrology team and are available on request.

Entry 0342 — 2025-06-12 — Unit AX7200-BC-0640

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 0.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The depot maintains a rolling stock of common spares to reduce turnaround time. Photographic evidence should accompany any report of physical damage.

Entry 0343 — 2025-06-13 — Unit AX7300-BC-0556

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 2.8 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Serial numbers must be transcribed exactly as they appear on the unit label. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0344 — 2025-06-13 — Unit AX7300-BC-0980

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 5.3 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Field teams should record ambient conditions at the start and end of every deployment. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0345 — 2025-06-13 — Unit AX7200-BC-0702

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 4.0 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Shipping arrangements are confirmed in writing before any unit leaves the depot. This section is reviewed each year by the responsible department head.

Entry 0346 — 2025-06-14 — Unit AX7300-BC-0244

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 0.8 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Measurements should be recorded in SI units unless a customer specification requires otherwise. This section is reviewed each year by the responsible department head.

Entry 0347 — 2025-06-14 — Unit AX7200-BC-0403

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 4.8 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The procedure assumes the operator has completed the standard competency assessment. Calibration certificates are held by the metrology team and are available on request.

Entry 0348 — 2025-06-15 — Unit AX7300-BC-0724

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 0.9 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Training on this section forms part of the standard onboarding programme. Feedback on this document is welcome and should be sent to the owning department.

Entry 0349 — 2025-06-15 — Unit AX7300-BC-0694

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 2.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Training on this section forms part of the standard onboarding programme. Supporting templates are published on the internal documentation portal.

Entry 0350 — 2025-06-16 — Unit AX7200-BC-0507

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 2.9 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Training on this section forms part of the standard onboarding programme. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0351 — 2025-06-16 — Unit AX7200-BC-0262

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 4.4 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Questions about the interpretation of this section should be directed to your manager in the first instance. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0352 — 2025-06-17 — Unit AX7300-BC-0551

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 2.5 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0353 — 2025-06-17 — Unit AX7300-BC-0057

Technician: S. Duplessis **Reported fault:** E-311 **Labour:** 5.2 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Calibration certificates are held by the metrology team and are available on request. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0354 — 2025-06-18 — Unit AX7300-BC-0498

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.8 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Calibration certificates are held by the metrology team and are available on request. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0355 — 2025-06-18 — Unit AX7200-BC-0662

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 5.9 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

The procedure assumes the operator has completed the standard competency assessment. Where a form is prescribed, the current version of that form must be used.

Entry 0356 — 2025-06-19 — Unit AX7200-BC-0052

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 0.7 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Training on this section forms part of the standard onboarding programme. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0357 — 2025-06-19 — Unit AX7200-BC-0445

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 5.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Records created under this section are retained in accordance with the company retention schedule. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0358 — 2025-06-20 — Unit AX7300-BC-0402

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 1.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0359 — 2025-06-20 — Unit AX7200-BC-0191

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 5.6 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Exceptions require written approval from the relevant department head before the activity begins. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0360 — 2025-06-21 — Unit AX7200-BC-0488

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 0.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Questions about the interpretation of this section should be directed to your manager in the first instance. Where a form is prescribed, the current version of that form must be used.

Entry 0361 — 2025-06-21 — Unit AX7300-BC-0762

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 2.4 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The procedure assumes the operator has completed the standard competency assessment. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0362 — 2025-06-22 — Unit AX7300-BC-0697

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 3.1 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Exceptions require written approval from the relevant department head before the activity begins. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0363 — 2025-06-22 — Unit AX7300-BC-0354

Technician: R. Fairweather **Reported fault:** E-311 **Labour:** 0.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The company reviews these arrangements periodically and may revise them with reasonable notice. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0364 — 2025-06-22 — Unit AX7200-BC-0244

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 2.3 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

The depot maintains a rolling stock of common spares to reduce turnaround time. Training on this section forms part of the standard onboarding programme.

Entry 0365 — 2025-06-23 — Unit AX7200-BC-0719

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 2.3 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Shipping arrangements are confirmed in writing before any unit leaves the depot. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0366 — 2025-06-23 — Unit AX7200-BC-0447

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 4.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Feedback on this document is welcome and should be sent to the owning department. Training on this section forms part of the standard onboarding programme.

Entry 0367 — 2025-06-24 — Unit AX7200-BC-0974

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 2.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The depot maintains a rolling stock of common spares to reduce turnaround time. Calibration certificates are held by the metrology team and are available on request.

Entry 0368 — 2025-06-24 — Unit AX7200-BC-0493

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 5.1 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

This section is reviewed each year by the responsible department head. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0369 — 2025-06-25 — Unit AX7200-BC-0517

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 5.2 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The company reviews these arrangements periodically and may revise them with reasonable notice. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0370 — 2025-06-25 — Unit AX7200-BC-0312

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 0.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Managers are responsible for ensuring their teams understand the requirements set out here. This section is reviewed each year by the responsible department head.

Entry 0371 — 2025-06-26 — Unit AX7300-BC-0704

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 5.3 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Training on this section forms part of the standard onboarding programme.

Entry 0372 — 2025-06-26 — Unit AX7300-BC-0536

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 3.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The depot maintains a rolling stock of common spares to reduce turnaround time. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0373 — 2025-06-27 — Unit AX7200-BC-0581

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 4.8 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Deviation from the documented procedure must be noted in the deployment record. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0374 — 2025-06-27 — Unit AX7200-BC-0352

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 1.4 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Serial numbers must be transcribed exactly as they appear on the unit label. The procedure assumes the operator has completed the standard competency assessment.

Entry 0375 — 2025-06-28 — Unit AX7300-BC-0135

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 0.6 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0376 — 2025-06-28 — Unit AX7200-BC-0843

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 4.9 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Any conflict between this document and a signed customer agreement should be escalated promptly. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0377 — 2025-06-29 — Unit AX7300-BC-0869

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 1.0 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0378 — 2025-06-29 — Unit AX7300-BC-0788

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 2.4 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

This section is reviewed each year by the responsible department head. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0379 — 2025-06-30 — Unit AX7200-BC-0894

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 5.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

The company reviews these arrangements periodically and may revise them with reasonable notice. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0380 — 2025-06-30 — Unit AX7200-BC-0751

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 3.2 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Records created under this section are retained in accordance with the company retention schedule. The procedure assumes the operator has completed the standard competency assessment.

Entry 0381 — 2025-07-01 — Unit AX7200-BC-0430

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 3.2 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Photographic evidence should accompany any report of physical damage. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0382 — 2025-07-01 — Unit AX7200-BC-0436

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 0.8 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0383 — 2025-07-01 — Unit AX7300-BC-0104

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 5.0 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The procedure assumes the operator has completed the standard competency assessment. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0384 — 2025-07-02 — Unit AX7200-BC-0832

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 1.7 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Consumable parts are excluded from the scope of the standard service agreement. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0385 — 2025-07-02 — Unit AX7300-BC-0932

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 4.6 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Questions about the interpretation of this section should be directed to your manager in the first instance. Deviation from the documented procedure must be noted in the deployment record.

Entry 0386 — 2025-07-03 — Unit AX7300-BC-0449

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 2.9 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Feedback on this document is welcome and should be sent to the owning department. Training on this section forms part of the standard onboarding programme.

Entry 0387 — 2025-07-03 — Unit AX7300-BC-0504

Technician: S. Duplessis **Reported fault:** E-311 **Labour:** 6.0 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Where a form is prescribed, the current version of that form must be used. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0388 — 2025-07-04 — Unit AX7300-BC-0331

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 4.4 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The procedure assumes the operator has completed the standard competency assessment.

Entry 0389 — 2025-07-04 — Unit AX7300-BC-0572

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 3.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The depot maintains a rolling stock of common spares to reduce turnaround time. Supporting templates are published on the internal documentation portal.

Entry 0390 — 2025-07-05 — Unit AX7300-BC-0457

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 5.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Any conflict between this document and a signed customer agreement should be escalated promptly. This section is reviewed each year by the responsible department head.

Entry 0391 — 2025-07-05 — Unit AX7200-BC-0079

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 1.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Shipping arrangements are confirmed in writing before any unit leaves the depot. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0392 — 2025-07-06 — Unit AX7300-BC-0021

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 3.1 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Calibration certificates are held by the metrology team and are available on request. Photographic evidence should accompany any report of physical damage.

Entry 0393 — 2025-07-06 — Unit AX7300-BC-0199

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 5.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Where a form is prescribed, the current version of that form must be used. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0394 — 2025-07-07 — Unit AX7200-BC-0243

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 5.6 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Where a form is prescribed, the current version of that form must be used. Deviation from the documented procedure must be noted in the deployment record.

Entry 0395 — 2025-07-07 — Unit AX7200-BC-0523

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 1.1 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

This section is reviewed each year by the responsible department head. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0396 — 2025-07-08 — Unit AX7300-BC-0575

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 5.8 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Consumable parts are excluded from the scope of the standard service agreement. Photographic evidence should accompany any report of physical damage.

Entry 0397 — 2025-07-08 — Unit AX7300-BC-0114

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 4.4 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0398 — 2025-07-09 — Unit AX7300-BC-0288

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 4.1 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Supporting templates are published on the internal documentation portal. Nothing in this section overrides an applicable statutory obligation.

Entry 0399 — 2025-07-09 — Unit AX7300-BC-0662

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 1.9 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The procedure assumes the operator has completed the standard competency assessment. Photographic evidence should accompany any report of physical damage.

Entry 0400 — 2025-07-10 — Unit AX7200-BC-0557

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 4.2 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Calibration certificates are held by the metrology team and are available on request. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0401 — 2025-07-10 — Unit AX7200-BC-0313

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 2.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Records created under this section are retained in accordance with the company retention schedule. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0402 — 2025-07-10 — Unit AX7200-BC-0639

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 2.4 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Nothing in this section overrides an applicable statutory obligation. Feedback on this document is welcome and should be sent to the owning department.

Entry 0403 — 2025-07-11 — Unit AX7200-BC-0535

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.1 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Where a form is prescribed, the current version of that form must be used. This section is reviewed each year by the responsible department head.

Entry 0404 — 2025-07-11 — Unit AX7200-BC-0856

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 1.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Nothing in this section overrides an applicable statutory obligation. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0405 — 2025-07-12 — Unit AX7200-BC-0164

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 1.2 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0406 — 2025-07-12 — Unit AX7300-BC-0833

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 2.1 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Serial numbers must be transcribed exactly as they appear on the unit label. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0407 — 2025-07-13 — Unit AX7200-BC-0733

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 5.2 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

The procedure assumes the operator has completed the standard competency assessment. Feedback on this document is welcome and should be sent to the owning department.

Entry 0408 — 2025-07-13 — Unit AX7200-BC-0068

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 3.5 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Feedback on this document is welcome and should be sent to the owning department. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0409 — 2025-07-14 — Unit AX7200-BC-0431

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 2.8 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

The procedure assumes the operator has completed the standard competency assessment. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0410 — 2025-07-14 — Unit AX7300-BC-0333

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 4.9 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Nothing in this section overrides an applicable statutory obligation. Training on this section forms part of the standard onboarding programme.

Entry 0411 — 2025-07-15 — Unit AX7300-BC-0329

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 1.7 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Nothing in this section overrides an applicable statutory obligation. Photographic evidence should accompany any report of physical damage.

Entry 0412 — 2025-07-15 — Unit AX7200-BC-0872

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 2.6 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Feedback on this document is welcome and should be sent to the owning department. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0413 — 2025-07-16 — Unit AX7300-BC-0444

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 3.3 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Field teams should record ambient conditions at the start and end of every deployment. Feedback on this document is welcome and should be sent to the owning department.

Entry 0414 — 2025-07-16 — Unit AX7300-BC-0536

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 3.4 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Managers are responsible for ensuring their teams understand the requirements set out here. Where a form is prescribed, the current version of that form must be used.

Entry 0415 — 2025-07-17 — Unit AX7300-BC-0142

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 4.2 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Records created under this section are retained in accordance with the company retention schedule. Calibration certificates are held by the metrology team and are available on request.

Entry 0416 — 2025-07-17 — Unit AX7300-BC-0878

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 1.4 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Any conflict between this document and a signed customer agreement should be escalated promptly. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0417 — 2025-07-18 — Unit AX7300-BC-0487

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 5.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Feedback on this document is welcome and should be sent to the owning department. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0418 — 2025-07-18 — Unit AX7200-BC-0685

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 5.3 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Where a form is prescribed, the current version of that form must be used. Feedback on this document is welcome and should be sent to the owning department.

Entry 0419 — 2025-07-19 — Unit AX7300-BC-0023

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 5.8 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Consumable parts are excluded from the scope of the standard service agreement. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0420 — 2025-07-19 — Unit AX7200-BC-0127

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 3.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Feedback on this document is welcome and should be sent to the owning department. Photographic evidence should accompany any report of physical damage.

Entry 0421 — 2025-07-19 — Unit AX7200-BC-0830

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 5.4 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Training on this section forms part of the standard onboarding programme. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0422 — 2025-07-20 — Unit AX7300-BC-0183

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 4.0 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Exceptions require written approval from the relevant department head before the activity begins. Where a form is prescribed, the current version of that form must be used.

Entry 0423 — 2025-07-20 — Unit AX7300-BC-0003

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 3.4 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Managers are responsible for ensuring their teams understand the requirements set out here. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0424 — 2025-07-21 — Unit AX7300-BC-0530

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 5.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Deviation from the documented procedure must be noted in the deployment record. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0425 — 2025-07-21 — Unit AX7300-BC-0987

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 5.4 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The procedure assumes the operator has completed the standard competency assessment. Calibration certificates are held by the metrology team and are available on request.

Entry 0426 — 2025-07-22 — Unit AX7300-BC-0076

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 2.9 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The company reviews these arrangements periodically and may revise them with reasonable notice. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0427 — 2025-07-22 — Unit AX7200-BC-0033

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.9 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Feedback on this document is welcome and should be sent to the owning department. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0428 — 2025-07-23 — Unit AX7300-BC-0516

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 3.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Serial numbers must be transcribed exactly as they appear on the unit label. Where a form is prescribed, the current version of that form must be used.

Entry 0429 — 2025-07-23 — Unit AX7300-BC-0838

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 2.6 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Photographic evidence should accompany any report of physical damage.

Entry 0430 — 2025-07-24 — Unit AX7200-BC-0998

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 2.8 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Records created under this section are retained in accordance with the company retention schedule. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0431 — 2025-07-24 — Unit AX7200-BC-0012

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 1.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0432 — 2025-07-25 — Unit AX7300-BC-0521

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 4.0 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Field teams should record ambient conditions at the start and end of every deployment. Nothing in this section overrides an applicable statutory obligation.

Entry 0433 — 2025-07-25 — Unit AX7300-BC-0617

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 1.1 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Nothing in this section overrides an applicable statutory obligation. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0434 — 2025-07-26 — Unit AX7200-BC-0202

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 5.3 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Consumable parts are excluded from the scope of the standard service agreement. This section is reviewed each year by the responsible department head.

Entry 0435 — 2025-07-26 — Unit AX7300-BC-0969

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 4.7 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Records created under this section are retained in accordance with the company retention schedule. Feedback on this document is welcome and should be sent to the owning department.

Entry 0436 — 2025-07-27 — Unit AX7300-BC-0140

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 5.2 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Photographic evidence should accompany any report of physical damage.

Entry 0437 — 2025-07-27 — Unit AX7300-BC-0850

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 4.6 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0438 — 2025-07-27 — Unit AX7200-BC-0419

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 5.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0439 — 2025-07-28 — Unit AX7300-BC-0801

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 3.4 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Feedback on this document is welcome and should be sent to the owning department. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0440 — 2025-07-28 — Unit AX7200-BC-0173

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 3.2 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Supporting templates are published on the internal documentation portal.

Entry 0441 — 2025-07-29 — Unit AX7200-BC-0809

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 4.7 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Feedback on this document is welcome and should be sent to the owning department. Where a form is prescribed, the current version of that form must be used.

Entry 0442 — 2025-07-29 — Unit AX7200-BC-0441

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 1.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Calibration certificates are held by the metrology team and are available on request. The procedure assumes the operator has completed the standard competency assessment.

Entry 0443 — 2025-07-30 — Unit AX7200-BC-0299

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 3.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0444 — 2025-07-30 — Unit AX7200-BC-0293

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 1.9 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Managers are responsible for ensuring their teams understand the requirements set out here. Nothing in this section overrides an applicable statutory obligation.

Entry 0445 — 2025-07-31 — Unit AX7300-BC-0996

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 1.9 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Photographic evidence should accompany any report of physical damage. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0446 — 2025-07-31 — Unit AX7300-BC-0211

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 4.3 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Questions about the interpretation of this section should be directed to your manager in the first instance. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0447 — 2025-08-01 — Unit AX7300-BC-0629

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 2.9 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

The depot maintains a rolling stock of common spares to reduce turnaround time. Deviation from the documented procedure must be noted in the deployment record.

Entry 0448 — 2025-08-01 — Unit AX7300-BC-0915

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 2.3 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Questions about the interpretation of this section should be directed to your manager in the first instance. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0449 — 2025-08-02 — Unit AX7300-BC-0508

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 2.6 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

The company reviews these arrangements periodically and may revise them with reasonable notice. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0450 — 2025-08-02 — Unit AX7300-BC-0950

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 1.4 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0451 — 2025-08-03 — Unit AX7200-BC-0843

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 5.2 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Managers are responsible for ensuring their teams understand the requirements set out here. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0452 — 2025-08-03 — Unit AX7300-BC-0455

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 3.3 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Field teams should record ambient conditions at the start and end of every deployment. Supporting templates are published on the internal documentation portal.

Entry 0453 — 2025-08-04 — Unit AX7300-BC-0923

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 2.6 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Where a form is prescribed, the current version of that form must be used. Nothing in this section overrides an applicable statutory obligation.

Entry 0454 — 2025-08-04 — Unit AX7300-BC-0112

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 4.3 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Photographic evidence should accompany any report of physical damage. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0455 — 2025-08-05 — Unit AX7300-BC-0128

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 3.2 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

The depot maintains a rolling stock of common spares to reduce turnaround time. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0456 — 2025-08-05 — Unit AX7300-BC-0845

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 5.3 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Feedback on this document is welcome and should be sent to the owning department. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0457 — 2025-08-06 — Unit AX7200-BC-0791

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 3.1 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The company reviews these arrangements periodically and may revise them with reasonable notice. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0458 — 2025-08-06 — Unit AX7200-BC-0878

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 3.3 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Training on this section forms part of the standard onboarding programme.

Entry 0459 — 2025-08-06 — Unit AX7200-BC-0141

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 0.5 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The depot maintains a rolling stock of common spares to reduce turnaround time. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0460 — 2025-08-07 — Unit AX7300-BC-0200

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 1.9 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0461 — 2025-08-07 — Unit AX7200-BC-0411

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 4.4 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

The depot maintains a rolling stock of common spares to reduce turnaround time. Calibration certificates are held by the metrology team and are available on request.

Entry 0462 — 2025-08-08 — Unit AX7300-BC-0048

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 5.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Serial numbers must be transcribed exactly as they appear on the unit label. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0463 — 2025-08-08 — Unit AX7300-BC-0939

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 1.2 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Where a form is prescribed, the current version of that form must be used.

Entry 0464 — 2025-08-09 — Unit AX7300-BC-0639

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 4.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Deviation from the documented procedure must be noted in the deployment record. This section is reviewed each year by the responsible department head.

Entry 0465 — 2025-08-09 — Unit AX7300-BC-0787

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 2.4 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

This section is reviewed each year by the responsible department head. Feedback on this document is welcome and should be sent to the owning department.

Entry 0466 — 2025-08-10 — Unit AX7300-BC-0568

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 1.3 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Managers are responsible for ensuring their teams understand the requirements set out here. Photographic evidence should accompany any report of physical damage.

Entry 0467 — 2025-08-10 — Unit AX7300-BC-0896

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 1.6 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Records created under this section are retained in accordance with the company retention schedule. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0468 — 2025-08-11 — Unit AX7200-BC-0310

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 3.1 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The company reviews these arrangements periodically and may revise them with reasonable notice. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0469 — 2025-08-11 — Unit AX7200-BC-0600

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 4.9 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. This section is reviewed each year by the responsible department head.

Entry 0470 — 2025-08-12 — Unit AX7200-BC-0221

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 2.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Deviation from the documented procedure must be noted in the deployment record. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0471 — 2025-08-12 — Unit AX7200-BC-0455

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 5.6 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Any conflict between this document and a signed customer agreement should be escalated promptly. Calibration certificates are held by the metrology team and are available on request.

Entry 0472 — 2025-08-13 — Unit AX7200-BC-0168

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 2.8 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Training on this section forms part of the standard onboarding programme. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0473 — 2025-08-13 — Unit AX7300-BC-0670

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 1.3 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Shipping arrangements are confirmed in writing before any unit leaves the depot. The procedure assumes the operator has completed the standard competency assessment.

Entry 0474 — 2025-08-14 — Unit AX7200-BC-0260

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 3.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Records created under this section are retained in accordance with the company retention schedule.

Entry 0475 — 2025-08-14 — Unit AX7200-BC-0149

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 2.1 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Records created under this section are retained in accordance with the company retention schedule.

Entry 0476 — 2025-08-15 — Unit AX7300-BC-0498

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 4.8 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Field teams should record ambient conditions at the start and end of every deployment. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0477 — 2025-08-15 — Unit AX7300-BC-0956

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 5.2 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Questions about the interpretation of this section should be directed to your manager in the first instance. Photographic evidence should accompany any report of physical damage.

Entry 0478 — 2025-08-15 — Unit AX7300-BC-0959

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 3.3 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Managers are responsible for ensuring their teams understand the requirements set out here. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0479 — 2025-08-16 — Unit AX7300-BC-0226

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 2.5 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Managers are responsible for ensuring their teams understand the requirements set out here. Feedback on this document is welcome and should be sent to the owning department.

Entry 0480 — 2025-08-16 — Unit AX7200-BC-0550

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 2.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The procedure assumes the operator has completed the standard competency assessment. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0481 — 2025-08-17 — Unit AX7300-BC-0507

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 5.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Where a form is prescribed, the current version of that form must be used. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0482 — 2025-08-17 — Unit AX7200-BC-0418

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 5.5 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0483 — 2025-08-18 — Unit AX7200-BC-0918

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 1.0 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Nothing in this section overrides an applicable statutory obligation. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0484 — 2025-08-18 — Unit AX7200-BC-0045

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 5.2 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Exceptions require written approval from the relevant department head before the activity begins. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0485 — 2025-08-19 — Unit AX7200-BC-0622

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 3.6 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Supporting templates are published on the internal documentation portal. Photographic evidence should accompany any report of physical damage.

Entry 0486 — 2025-08-19 — Unit AX7200-BC-0512

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 3.2 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Training on this section forms part of the standard onboarding programme. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0487 — 2025-08-20 — Unit AX7300-BC-0304

Technician: S. Duplessis **Reported fault:** E-311 **Labour:** 4.9 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0488 — 2025-08-20 — Unit AX7300-BC-0537

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 1.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Exceptions require written approval from the relevant department head before the activity begins. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0489 — 2025-08-21 — Unit AX7200-BC-0008

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 4.1 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Where a form is prescribed, the current version of that form must be used. Deviation from the documented procedure must be noted in the deployment record.

Entry 0490 — 2025-08-21 — Unit AX7200-BC-0164

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 4.2 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Nothing in this section overrides an applicable statutory obligation. Deviation from the documented procedure must be noted in the deployment record.

Entry 0491 — 2025-08-22 — Unit AX7300-BC-0462

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 0.8 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Consumable parts are excluded from the scope of the standard service agreement. The procedure assumes the operator has completed the standard competency assessment.

Entry 0492 — 2025-08-22 — Unit AX7200-BC-0745

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 2.3 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Where a form is prescribed, the current version of that form must be used. Calibration certificates are held by the metrology team and are available on request.

Entry 0493 — 2025-08-23 — Unit AX7200-BC-0106

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 5.8 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Serial numbers must be transcribed exactly as they appear on the unit label. Supporting templates are published on the internal documentation portal.

Entry 0494 — 2025-08-23 — Unit AX7300-BC-0121

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 3.5 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Calibration certificates are held by the metrology team and are available on request. Supporting templates are published on the internal documentation portal.

Entry 0495 — 2025-08-24 — Unit AX7300-BC-0658

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 4.2 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Exceptions require written approval from the relevant department head before the activity begins. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0496 — 2025-08-24 — Unit AX7200-BC-0968

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 5.8 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Field teams should record ambient conditions at the start and end of every deployment. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0497 — 2025-08-24 — Unit AX7200-BC-0640

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 2.8 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The depot maintains a rolling stock of common spares to reduce turnaround time. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0498 — 2025-08-25 — Unit AX7300-BC-0893

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 0.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The company reviews these arrangements periodically and may revise them with reasonable notice. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0499 — 2025-08-25 — Unit AX7300-BC-0324

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 5.2 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Supporting templates are published on the internal documentation portal.

Entry 0500 — 2025-08-26 — Unit AX7200-BC-0266

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 4.2 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Training on this section forms part of the standard onboarding programme. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0501 — 2025-08-26 — Unit AX7300-BC-0792

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 1.2 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0502 — 2025-08-27 — Unit AX7300-BC-0823

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 2.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Field teams should record ambient conditions at the start and end of every deployment. Photographic evidence should accompany any report of physical damage.

Entry 0503 — 2025-08-27 — Unit AX7200-BC-0289

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 1.5 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Exceptions require written approval from the relevant department head before the activity begins. Deviation from the documented procedure must be noted in the deployment record.

Entry 0504 — 2025-08-28 — Unit AX7200-BC-0611

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 2.9 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0505 — 2025-08-28 — Unit AX7200-BC-0298

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 1.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Records created under this section are retained in accordance with the company retention schedule. Feedback on this document is welcome and should be sent to the owning department.

Entry 0506 — 2025-08-29 — Unit AX7200-BC-0565

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 2.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Consumable parts are excluded from the scope of the standard service agreement. Deviation from the documented procedure must be noted in the deployment record.

Entry 0507 — 2025-08-29 — Unit AX7200-BC-0441

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 3.0 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Nothing in this section overrides an applicable statutory obligation. The procedure assumes the operator has completed the standard competency assessment.

Entry 0508 — 2025-08-30 — Unit AX7200-BC-0972

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 0.8 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Questions about the interpretation of this section should be directed to your manager in the first instance. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0509 — 2025-08-30 — Unit AX7300-BC-0113

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Photographic evidence should accompany any report of physical damage. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0510 — 2025-08-31 — Unit AX7300-BC-0243

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 2.9 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Serial numbers must be transcribed exactly as they appear on the unit label. Training on this section forms part of the standard onboarding programme.

Entry 0511 — 2025-08-31 — Unit AX7200-BC-0217

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 0.6 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Feedback on this document is welcome and should be sent to the owning department. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0512 — 2025-09-01 — Unit AX7300-BC-0109

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 4.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Any conflict between this document and a signed customer agreement should be escalated promptly. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0513 — 2025-09-01 — Unit AX7200-BC-0663

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 0.7 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Records created under this section are retained in accordance with the company retention schedule. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0514 — 2025-09-02 — Unit AX7200-BC-0430

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 4.1 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Records created under this section are retained in accordance with the company retention schedule. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0515 — 2025-09-02 — Unit AX7200-BC-0267

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 5.8 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0516 — 2025-09-02 — Unit AX7200-BC-0666

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 2.7 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0517 — 2025-09-03 — Unit AX7200-BC-0408

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 1.6 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Exceptions require written approval from the relevant department head before the activity begins. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0518 — 2025-09-03 — Unit AX7200-BC-0295

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 4.2 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Deviation from the documented procedure must be noted in the deployment record. Feedback on this document is welcome and should be sent to the owning department.

Entry 0519 — 2025-09-04 — Unit AX7200-BC-0998

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 2.2 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Exceptions require written approval from the relevant department head before the activity begins. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0520 — 2025-09-04 — Unit AX7300-BC-0393

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 0.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Calibration certificates are held by the metrology team and are available on request.

Entry 0521 — 2025-09-05 — Unit AX7300-BC-0187

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 3.9 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Training on this section forms part of the standard onboarding programme. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0522 — 2025-09-05 — Unit AX7200-BC-0053

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 2.7 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Any conflict between this document and a signed customer agreement should be escalated promptly. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0523 — 2025-09-06 — Unit AX7200-BC-0559

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 5.0 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Managers are responsible for ensuring their teams understand the requirements set out here. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0524 — 2025-09-06 — Unit AX7300-BC-0106

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 1.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

This section is reviewed each year by the responsible department head. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0525 — 2025-09-07 — Unit AX7300-BC-0349

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 4.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Managers are responsible for ensuring their teams understand the requirements set out here. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0526 — 2025-09-07 — Unit AX7200-BC-0774

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 1.0 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Calibration certificates are held by the metrology team and are available on request. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0527 — 2025-09-08 — Unit AX7300-BC-0703

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 2.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

The depot maintains a rolling stock of common spares to reduce turnaround time. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0528 — 2025-09-08 — Unit AX7300-BC-0390

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 0.7 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Photographic evidence should accompany any report of physical damage. Records created under this section are retained in accordance with the company retention schedule.

Entry 0529 — 2025-09-09 — Unit AX7300-BC-0922

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 4.9 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

This section is reviewed each year by the responsible department head. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0530 — 2025-09-09 — Unit AX7300-BC-0510

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 2.0 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Supporting templates are published on the internal documentation portal. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0531 — 2025-09-10 — Unit AX7200-BC-0207

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 1.8 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Serial numbers must be transcribed exactly as they appear on the unit label. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0532 — 2025-09-10 — Unit AX7200-BC-0110

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 4.1 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Photographic evidence should accompany any report of physical damage.

Entry 0533 — 2025-09-10 — Unit AX7300-BC-0784

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 2.2 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Feedback on this document is welcome and should be sent to the owning department. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0534 — 2025-09-11 — Unit AX7200-BC-0309

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 0.6 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Serial numbers must be transcribed exactly as they appear on the unit label. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0535 — 2025-09-11 — Unit AX7300-BC-0903

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 1.8 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Supporting templates are published on the internal documentation portal. Photographic evidence should accompany any report of physical damage.

Entry 0536 — 2025-09-12 — Unit AX7200-BC-0774

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 4.2 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Feedback on this document is welcome and should be sent to the owning department.

Entry 0537 — 2025-09-12 — Unit AX7300-BC-0052

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 4.9 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Managers are responsible for ensuring their teams understand the requirements set out here. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0538 — 2025-09-13 — Unit AX7200-BC-0468

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 4.0 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Managers are responsible for ensuring their teams understand the requirements set out here. Photographic evidence should accompany any report of physical damage.

Entry 0539 — 2025-09-13 — Unit AX7200-BC-0022

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 1.0 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Field teams should record ambient conditions at the start and end of every deployment. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0540 — 2025-09-14 — Unit AX7200-BC-0171

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 2.7 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Records created under this section are retained in accordance with the company retention schedule. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0541 — 2025-09-14 — Unit AX7200-BC-0129

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 1.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

This section is reviewed each year by the responsible department head. Deviation from the documented procedure must be noted in the deployment record.

Entry 0542 — 2025-09-15 — Unit AX7200-BC-0828

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 2.8 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Records created under this section are retained in accordance with the company retention schedule.

Entry 0543 — 2025-09-15 — Unit AX7300-BC-0438

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 3.9 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Deviation from the documented procedure must be noted in the deployment record.

Entry 0544 — 2025-09-16 — Unit AX7200-BC-0461

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 5.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Consumable parts are excluded from the scope of the standard service agreement. Feedback on this document is welcome and should be sent to the owning department.

Entry 0545 — 2025-09-16 — Unit AX7200-BC-0949

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 2.3 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0546 — 2025-09-17 — Unit AX7200-BC-0107

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 0.8 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Field teams should record ambient conditions at the start and end of every deployment. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0547 — 2025-09-17 — Unit AX7300-BC-0367

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 3.6 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Deviation from the documented procedure must be noted in the deployment record. Supporting templates are published on the internal documentation portal.

Entry 0548 — 2025-09-18 — Unit AX7300-BC-0467

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 1.5 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Managers are responsible for ensuring their teams understand the requirements set out here. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0549 — 2025-09-18 — Unit AX7300-BC-0788

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 3.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Consumable parts are excluded from the scope of the standard service agreement. The procedure assumes the operator has completed the standard competency assessment.

Entry 0550 — 2025-09-19 — Unit AX7200-BC-0944

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 3.2 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Consumable parts are excluded from the scope of the standard service agreement. Supporting templates are published on the internal documentation portal.

Entry 0551 — 2025-09-19 — Unit AX7300-BC-0907

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 1.6 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Consumable parts are excluded from the scope of the standard service agreement. Supporting templates are published on the internal documentation portal.

Entry 0552 — 2025-09-20 — Unit AX7300-BC-0034

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 4.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0553 — 2025-09-20 — Unit AX7300-BC-0208

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 5.1 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Records created under this section are retained in accordance with the company retention schedule. Training on this section forms part of the standard onboarding programme.

Entry 0554 — 2025-09-20 — Unit AX7200-BC-0620

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 4.0 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Questions about the interpretation of this section should be directed to your manager in the first instance. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0555 — 2025-09-21 — Unit AX7200-BC-0966

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 4.0 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Field teams should record ambient conditions at the start and end of every deployment. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0556 — 2025-09-21 — Unit AX7300-BC-0579

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 3.0 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Deviation from the documented procedure must be noted in the deployment record. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0557 — 2025-09-22 — Unit AX7200-BC-0412

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 4.8 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Managers are responsible for ensuring their teams understand the requirements set out here. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0558 — 2025-09-22 — Unit AX7300-BC-0613

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 2.9 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Calibration certificates are held by the metrology team and are available on request. Training on this section forms part of the standard onboarding programme.

Entry 0559 — 2025-09-23 — Unit AX7300-BC-0093

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 5.2 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Photographic evidence should accompany any report of physical damage. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0560 — 2025-09-23 — Unit AX7300-BC-0062

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 5.5 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Where a form is prescribed, the current version of that form must be used. Records created under this section are retained in accordance with the company retention schedule.

Entry 0561 — 2025-09-24 — Unit AX7200-BC-0811

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 5.8 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0562 — 2025-09-24 — Unit AX7200-BC-0187

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 5.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Calibration certificates are held by the metrology team and are available on request. Nothing in this section overrides an applicable statutory obligation.

Entry 0563 — 2025-09-25 — Unit AX7300-BC-0552

Technician: S. Duplessis **Reported fault:** E-311 **Labour:** 4.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Calibration certificates are held by the metrology team and are available on request. Deviation from the documented procedure must be noted in the deployment record.

Entry 0564 — 2025-09-25 — Unit AX7200-BC-0303

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 4.0 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Any conflict between this document and a signed customer agreement should be escalated promptly. Records created under this section are retained in accordance with the company retention schedule.

Entry 0565 — 2025-09-26 — Unit AX7300-BC-0866

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 5.6 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0566 — 2025-09-26 — Unit AX7300-BC-0412

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 0.5 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0567 — 2025-09-27 — Unit AX7200-BC-0132

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 4.2 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Questions about the interpretation of this section should be directed to your manager in the first instance. Feedback on this document is welcome and should be sent to the owning department.

Entry 0568 — 2025-09-27 — Unit AX7300-BC-0351

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 2.2 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Calibration certificates are held by the metrology team and are available on request.

Entry 0569 — 2025-09-28 — Unit AX7200-BC-0412

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 3.7 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Questions about the interpretation of this section should be directed to your manager in the first instance. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0570 — 2025-09-28 — Unit AX7300-BC-0176

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 5.4 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Records created under this section are retained in accordance with the company retention schedule.

Entry 0571 — 2025-09-29 — Unit AX7300-BC-0904

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 4.8 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Serial numbers must be transcribed exactly as they appear on the unit label. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0572 — 2025-09-29 — Unit AX7200-BC-0265

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 4.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Where a form is prescribed, the current version of that form must be used. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0573 — 2025-09-29 — Unit AX7200-BC-0122

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 4.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Exceptions require written approval from the relevant department head before the activity begins. Deviation from the documented procedure must be noted in the deployment record.

Entry 0574 — 2025-09-30 — Unit AX7300-BC-0267

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 4.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

The procedure assumes the operator has completed the standard competency assessment. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0575 — 2025-09-30 — Unit AX7200-BC-0665

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 5.8 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The procedure assumes the operator has completed the standard competency assessment. Supporting templates are published on the internal documentation portal.

Entry 0576 — 2025-10-01 — Unit AX7200-BC-0305

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 4.5 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Managers are responsible for ensuring their teams understand the requirements set out here. Deviation from the documented procedure must be noted in the deployment record.

Entry 0577 — 2025-10-01 — Unit AX7300-BC-0842

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 0.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Nothing in this section overrides an applicable statutory obligation. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0578 — 2025-10-02 — Unit AX7300-BC-0354

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 0.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Calibration certificates are held by the metrology team and are available on request. This section is reviewed each year by the responsible department head.

Entry 0579 — 2025-10-02 — Unit AX7300-BC-0872

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 3.1 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The depot maintains a rolling stock of common spares to reduce turnaround time. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0580 — 2025-10-03 — Unit AX7200-BC-0478

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 4.9 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

The procedure assumes the operator has completed the standard competency assessment. Feedback on this document is welcome and should be sent to the owning department.

Entry 0581 — 2025-10-03 — Unit AX7300-BC-0866

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 1.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Photographic evidence should accompany any report of physical damage. Deviation from the documented procedure must be noted in the deployment record.

Entry 0582 — 2025-10-04 — Unit AX7300-BC-0946

Technician: A. Whitcombe **Reported fault:** E-311 **Labour:** 4.8 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Nothing in this section overrides an applicable statutory obligation.

Entry 0583 — 2025-10-04 — Unit AX7300-BC-0303

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 4.5 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Managers are responsible for ensuring their teams understand the requirements set out here. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0584 — 2025-10-05 — Unit AX7200-BC-0963

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 1.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Where a form is prescribed, the current version of that form must be used. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0585 — 2025-10-05 — Unit AX7200-BC-0253

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 1.1 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Exceptions require written approval from the relevant department head before the activity begins. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0586 — 2025-10-06 — Unit AX7300-BC-0277

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 2.0 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Any conflict between this document and a signed customer agreement should be escalated promptly. Supporting templates are published on the internal documentation portal.

Entry 0587 — 2025-10-06 — Unit AX7200-BC-0847

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 0.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Exceptions require written approval from the relevant department head before the activity begins. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0588 — 2025-10-07 — Unit AX7300-BC-0463

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 5.4 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Measurements should be recorded in SI units unless a customer specification requires otherwise. This section is reviewed each year by the responsible department head.

Entry 0589 — 2025-10-07 — Unit AX7300-BC-0906

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 5.1 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0590 — 2025-10-08 — Unit AX7200-BC-0059

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 2.3 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

The company reviews these arrangements periodically and may revise them with reasonable notice. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0591 — 2025-10-08 — Unit AX7300-BC-0475

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 5.2 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

The depot maintains a rolling stock of common spares to reduce turnaround time. Feedback on this document is welcome and should be sent to the owning department.

Entry 0592 — 2025-10-08 — Unit AX7300-BC-0274

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 2.3 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0593 — 2025-10-09 — Unit AX7200-BC-0078

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 2.1 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

The procedure assumes the operator has completed the standard competency assessment. Deviation from the documented procedure must be noted in the deployment record.

Entry 0594 — 2025-10-09 — Unit AX7200-BC-0861

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 5.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Calibration certificates are held by the metrology team and are available on request. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0595 — 2025-10-10 — Unit AX7300-BC-0414

Technician: S. Duplessis **Reported fault:** E-311 **Labour:** 1.0 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Questions about the interpretation of this section should be directed to your manager in the first instance. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0596 — 2025-10-10 — Unit AX7200-BC-0606

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 3.6 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Feedback on this document is welcome and should be sent to the owning department. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0597 — 2025-10-11 — Unit AX7300-BC-0434

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 5.7 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Field teams should record ambient conditions at the start and end of every deployment. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0598 — 2025-10-11 — Unit AX7300-BC-0396

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 0.9 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Field teams should record ambient conditions at the start and end of every deployment. Photographic evidence should accompany any report of physical damage.

Entry 0599 — 2025-10-12 — Unit AX7300-BC-0527

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 3.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Serial numbers must be transcribed exactly as they appear on the unit label. Supporting templates are published on the internal documentation portal.

Entry 0600 — 2025-10-12 — Unit AX7200-BC-0583

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 3.9 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Questions about the interpretation of this section should be directed to your manager in the first instance. Feedback on this document is welcome and should be sent to the owning department.

Entry 0601 — 2025-10-13 — Unit AX7300-BC-0649

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 5.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Nothing in this section overrides an applicable statutory obligation. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0602 — 2025-10-13 — Unit AX7200-BC-0907

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 2.2 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Supporting templates are published on the internal documentation portal. Nothing in this section overrides an applicable statutory obligation.

Entry 0603 — 2025-10-14 — Unit AX7200-BC-0121

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 1.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The procedure assumes the operator has completed the standard competency assessment. Supporting templates are published on the internal documentation portal.

Entry 0604 — 2025-10-14 — Unit AX7200-BC-0033

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 5.9 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The procedure assumes the operator has completed the standard competency assessment. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0605 — 2025-10-15 — Unit AX7300-BC-0369

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 5.3 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Calibration certificates are held by the metrology team and are available on request. Where a form is prescribed, the current version of that form must be used.

Entry 0606 — 2025-10-15 — Unit AX7300-BC-0265

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 1.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Managers are responsible for ensuring their teams understand the requirements set out here. Where a form is prescribed, the current version of that form must be used.

Entry 0607 — 2025-10-16 — Unit AX7300-BC-0863

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 3.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Managers are responsible for ensuring their teams understand the requirements set out here. Deviation from the documented procedure must be noted in the deployment record.

Entry 0608 — 2025-10-16 — Unit AX7200-BC-0815

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 3.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

This section is reviewed each year by the responsible department head. Records created under this section are retained in accordance with the company retention schedule.

Entry 0609 — 2025-10-17 — Unit AX7300-BC-0206

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 2.0 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Serial numbers must be transcribed exactly as they appear on the unit label. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0610 — 2025-10-17 — Unit AX7300-BC-0007

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 4.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Calibration certificates are held by the metrology team and are available on request.

Entry 0611 — 2025-10-17 — Unit AX7300-BC-0217

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 1.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Nothing in this section overrides an applicable statutory obligation. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0612 — 2025-10-18 — Unit AX7300-BC-0721

Technician: R. Fairweather **Reported fault:** E-311 **Labour:** 3.4 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

This section is reviewed each year by the responsible department head. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0613 — 2025-10-18 — Unit AX7200-BC-0647

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 4.7 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Consumable parts are excluded from the scope of the standard service agreement. Where a form is prescribed, the current version of that form must be used.

Entry 0614 — 2025-10-19 — Unit AX7300-BC-0392

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 5.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Serial numbers must be transcribed exactly as they appear on the unit label. Records created under this section are retained in accordance with the company retention schedule.

Entry 0615 — 2025-10-19 — Unit AX7200-BC-0279

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 5.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Field teams should record ambient conditions at the start and end of every deployment. Calibration certificates are held by the metrology team and are available on request.

Entry 0616 — 2025-10-20 — Unit AX7200-BC-0355

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 5.2 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Photographic evidence should accompany any report of physical damage. Nothing in this section overrides an applicable statutory obligation.

Entry 0617 — 2025-10-20 — Unit AX7200-BC-0718

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 4.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Nothing in this section overrides an applicable statutory obligation. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0618 — 2025-10-21 — Unit AX7300-BC-0789

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 1.7 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Training on this section forms part of the standard onboarding programme. Nothing in this section overrides an applicable statutory obligation.

Entry 0619 — 2025-10-21 — Unit AX7200-BC-0827

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 4.5 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Nothing in this section overrides an applicable statutory obligation. Feedback on this document is welcome and should be sent to the owning department.

Entry 0620 — 2025-10-22 — Unit AX7200-BC-0616

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 4.2 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Supporting templates are published on the internal documentation portal. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0621 — 2025-10-22 — Unit AX7300-BC-0049

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 4.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Exceptions require written approval from the relevant department head before the activity begins. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0622 — 2025-10-23 — Unit AX7200-BC-0526

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 5.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

This section is reviewed each year by the responsible department head. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0623 — 2025-10-23 — Unit AX7300-BC-0509

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 0.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Calibration certificates are held by the metrology team and are available on request. Where a form is prescribed, the current version of that form must be used.

Entry 0624 — 2025-10-24 — Unit AX7200-BC-0404

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 1.7 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Where a form is prescribed, the current version of that form must be used.

Entry 0625 — 2025-10-24 — Unit AX7300-BC-0713

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 5.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Field teams should record ambient conditions at the start and end of every deployment. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0626 — 2025-10-25 — Unit AX7200-BC-0989

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 5.1 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Where a form is prescribed, the current version of that form must be used. Feedback on this document is welcome and should be sent to the owning department.

Entry 0627 — 2025-10-25 — Unit AX7300-BC-0802

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.4 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Training on this section forms part of the standard onboarding programme. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0628 — 2025-10-26 — Unit AX7200-BC-0422

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 4.1 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Where a form is prescribed, the current version of that form must be used. Supporting templates are published on the internal documentation portal.

Entry 0629 — 2025-10-26 — Unit AX7300-BC-0182

Technician: S. Duplessis **Reported fault:** E-311 **Labour:** 0.6 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Training on this section forms part of the standard onboarding programme. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0630 — 2025-10-26 — Unit AX7300-BC-0999

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 5.9 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0631 — 2025-10-27 — Unit AX7300-BC-0996

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 1.0 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Records created under this section are retained in accordance with the company retention schedule. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0632 — 2025-10-27 — Unit AX7200-BC-0311

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 4.7 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0633 — 2025-10-28 — Unit AX7300-BC-0421

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 5.9 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

This section is reviewed each year by the responsible department head. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0634 — 2025-10-28 — Unit AX7300-BC-0175

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 2.3 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Records created under this section are retained in accordance with the company retention schedule. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0635 — 2025-10-29 — Unit AX7300-BC-0119

Technician: R. Fairweather **Reported fault:** E-311 **Labour:** 1.4 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Field teams should record ambient conditions at the start and end of every deployment. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0636 — 2025-10-29 — Unit AX7300-BC-0649

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 4.2 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Where a form is prescribed, the current version of that form must be used. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0637 — 2025-10-30 — Unit AX7200-BC-0787

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 4.0 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Supporting templates are published on the internal documentation portal. Nothing in this section overrides an applicable statutory obligation.

Entry 0638 — 2025-10-30 — Unit AX7300-BC-0063

Technician: M. Castellanos **Reported fault:** E-311 **Labour:** 3.5 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

This section is reviewed each year by the responsible department head. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0639 — 2025-10-31 — Unit AX7200-BC-0149

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 5.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Feedback on this document is welcome and should be sent to the owning department.

Entry 0640 — 2025-10-31 — Unit AX7200-BC-0443

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 2.9 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

This section is reviewed each year by the responsible department head. Where a form is prescribed, the current version of that form must be used.

Entry 0641 — 2025-11-01 — Unit AX7300-BC-0286

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 5.1 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Feedback on this document is welcome and should be sent to the owning department. Nothing in this section overrides an applicable statutory obligation.

Entry 0642 — 2025-11-01 — Unit AX7300-BC-0554

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 5.0 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Training on this section forms part of the standard onboarding programme. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0643 — 2025-11-02 — Unit AX7300-BC-0350

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 3.5 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Supporting templates are published on the internal documentation portal. This section is reviewed each year by the responsible department head.

Entry 0644 — 2025-11-02 — Unit AX7200-BC-0912

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 2.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Records created under this section are retained in accordance with the company retention schedule.

Entry 0645 — 2025-11-03 — Unit AX7300-BC-0385

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 2.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

The procedure assumes the operator has completed the standard competency assessment. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0646 — 2025-11-03 — Unit AX7200-BC-0876

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 3.2 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Field teams should record ambient conditions at the start and end of every deployment. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0647 — 2025-11-04 — Unit AX7200-BC-0941

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 3.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Where a form is prescribed, the current version of that form must be used. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0648 — 2025-11-04 — Unit AX7300-BC-0692

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 0.5 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Training on this section forms part of the standard onboarding programme. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0649 — 2025-11-04 — Unit AX7300-BC-0456

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 2.3 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

The company reviews these arrangements periodically and may revise them with reasonable notice. Photographic evidence should accompany any report of physical damage.

Entry 0650 — 2025-11-05 — Unit AX7200-BC-0115

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 3.6 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Training on this section forms part of the standard onboarding programme. Records created under this section are retained in accordance with the company retention schedule.

Entry 0651 — 2025-11-05 — Unit AX7200-BC-0645

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 5.2 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Training on this section forms part of the standard onboarding programme. Nothing in this section overrides an applicable statutory obligation.

Entry 0652 — 2025-11-06 — Unit AX7200-BC-0419

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 6.0 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Deviation from the documented procedure must be noted in the deployment record.

Entry 0653 — 2025-11-06 — Unit AX7200-BC-0572

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 3.8 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Any conflict between this document and a signed customer agreement should be escalated promptly. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0654 — 2025-11-07 — Unit AX7200-BC-0931

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 3.1 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Serial numbers must be transcribed exactly as they appear on the unit label. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0655 — 2025-11-07 — Unit AX7300-BC-0647

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 2.4 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Supporting templates are published on the internal documentation portal. Nothing in this section overrides an applicable statutory obligation.

Entry 0656 — 2025-11-08 — Unit AX7200-BC-0655

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 2.1 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Feedback on this document is welcome and should be sent to the owning department. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0657 — 2025-11-08 — Unit AX7300-BC-0147

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 3.9 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Nothing in this section overrides an applicable statutory obligation. Training on this section forms part of the standard onboarding programme.

Entry 0658 — 2025-11-09 — Unit AX7300-BC-0693

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 1.1 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

This section is reviewed each year by the responsible department head. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0659 — 2025-11-09 — Unit AX7200-BC-0842

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 0.7 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Training on this section forms part of the standard onboarding programme. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0660 — 2025-11-10 — Unit AX7200-BC-0520

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 4.7 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Questions about the interpretation of this section should be directed to your manager in the first instance. Feedback on this document is welcome and should be sent to the owning department.

Entry 0661 — 2025-11-10 — Unit AX7300-BC-0542

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 2.2 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0662 — 2025-11-11 — Unit AX7300-BC-0445

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 3.2 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Calibration certificates are held by the metrology team and are available on request. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0663 — 2025-11-11 — Unit AX7300-BC-0549

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 5.9 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Deviation from the documented procedure must be noted in the deployment record.

Entry 0664 — 2025-11-12 — Unit AX7300-BC-0166

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 4.4 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Consumable parts are excluded from the scope of the standard service agreement. Calibration certificates are held by the metrology team and are available on request.

Entry 0665 — 2025-11-12 — Unit AX7300-BC-0236

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 4.3 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Questions about the interpretation of this section should be directed to your manager in the first instance. Feedback on this document is welcome and should be sent to the owning department.

Entry 0666 — 2025-11-13 — Unit AX7300-BC-0479

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 1.7 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Calibration certificates are held by the metrology team and are available on request. This section is reviewed each year by the responsible department head.

Entry 0667 — 2025-11-13 — Unit AX7200-BC-0343

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 2.5 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Serial numbers must be transcribed exactly as they appear on the unit label. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0668 — 2025-11-13 — Unit AX7200-BC-0030

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 1.1 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The procedure assumes the operator has completed the standard competency assessment. Calibration certificates are held by the metrology team and are available on request.

Entry 0669 — 2025-11-14 — Unit AX7300-BC-0830

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 6.0 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Calibration certificates are held by the metrology team and are available on request.

Entry 0670 — 2025-11-14 — Unit AX7200-BC-0494

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 1.9 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

The company reviews these arrangements periodically and may revise them with reasonable notice. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0671 — 2025-11-15 — Unit AX7200-BC-0928

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 2.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Questions about the interpretation of this section should be directed to your manager in the first instance. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0672 — 2025-11-15 — Unit AX7200-BC-0299

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 5.2 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Consumable parts are excluded from the scope of the standard service agreement. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0673 — 2025-11-16 — Unit AX7200-BC-0796

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 1.2 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

This section is reviewed each year by the responsible department head. Deviation from the documented procedure must be noted in the deployment record.

Entry 0674 — 2025-11-16 — Unit AX7200-BC-0311

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 1.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Serial numbers must be transcribed exactly as they appear on the unit label. Nothing in this section overrides an applicable statutory obligation.

Entry 0675 — 2025-11-17 — Unit AX7300-BC-0702

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 1.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Training on this section forms part of the standard onboarding programme. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0676 — 2025-11-17 — Unit AX7300-BC-0796

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 5.2 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Nothing in this section overrides an applicable statutory obligation. Feedback on this document is welcome and should be sent to the owning department.

Entry 0677 — 2025-11-18 — Unit AX7300-BC-0138

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 1.4 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

This section is reviewed each year by the responsible department head. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0678 — 2025-11-18 — Unit AX7200-BC-0166

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 5.9 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0679 — 2025-11-19 — Unit AX7300-BC-0398

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 1.2 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The company reviews these arrangements periodically and may revise them with reasonable notice. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0680 — 2025-11-19 — Unit AX7200-BC-0561

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 4.4 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Measurements should be recorded in SI units unless a customer specification requires otherwise. This section is reviewed each year by the responsible department head.

Entry 0681 — 2025-11-20 — Unit AX7300-BC-0305

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 1.1 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Records created under this section are retained in accordance with the company retention schedule. Supporting templates are published on the internal documentation portal.

Entry 0682 — 2025-11-20 — Unit AX7300-BC-0793

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 4.0 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Serial numbers must be transcribed exactly as they appear on the unit label. This section is reviewed each year by the responsible department head.

Entry 0683 — 2025-11-21 — Unit AX7200-BC-0682

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 1.8 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Exceptions require written approval from the relevant department head before the activity begins. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0684 — 2025-11-21 — Unit AX7200-BC-0135

Technician: A. Whitcombe **Reported fault:** E-204 **Labour:** 4.7 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Photographic evidence should accompany any report of physical damage.

Entry 0685 — 2025-11-22 — Unit AX7300-BC-0275

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 2.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Training on this section forms part of the standard onboarding programme. Deviation from the documented procedure must be noted in the deployment record.

Entry 0686 — 2025-11-22 — Unit AX7200-BC-0102

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.8 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The procedure assumes the operator has completed the standard competency assessment. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0687 — 2025-11-22 — Unit AX7300-BC-0801

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 1.2 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The procedure assumes the operator has completed the standard competency assessment.

Entry 0688 — 2025-11-23 — Unit AX7300-BC-0173

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 6.0 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The procedure assumes the operator has completed the standard competency assessment.

Entry 0689 — 2025-11-23 — Unit AX7200-BC-0535

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 1.0 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Managers are responsible for ensuring their teams understand the requirements set out here. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0690 — 2025-11-24 — Unit AX7200-BC-0732

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 3.4 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Field teams should record ambient conditions at the start and end of every deployment.

Entry 0691 — 2025-11-24 — Unit AX7200-BC-0190

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 3.9 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Training on this section forms part of the standard onboarding programme.

Entry 0692 — 2025-11-25 — Unit AX7200-BC-0290

Technician: A. Whitcombe **Reported fault:** E-142 **Labour:** 2.4 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0693 — 2025-11-25 — Unit AX7200-BC-0114

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 5.0 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0694 — 2025-11-26 — Unit AX7200-BC-0562

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 4.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The company reviews these arrangements periodically and may revise them with reasonable notice.

Entry 0695 — 2025-11-26 — Unit AX7200-BC-0192

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 4.7 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Questions about the interpretation of this section should be directed to your manager in the first instance. Deviation from the documented procedure must be noted in the deployment record.

Entry 0696 — 2025-11-27 — Unit AX7200-BC-0229

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 3.1 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

This section is reviewed each year by the responsible department head. The procedure assumes the operator has completed the standard competency assessment.

Entry 0697 — 2025-11-27 — Unit AX7200-BC-0768

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 4.1 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Measurements should be recorded in SI units unless a customer specification requires otherwise. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0698 — 2025-11-28 — Unit AX7200-BC-0954

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 1.3 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Serial numbers must be transcribed exactly as they appear on the unit label. Records created under this section are retained in accordance with the company retention schedule.

Entry 0699 — 2025-11-28 — Unit AX7300-BC-0485

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 4.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The depot maintains a rolling stock of common spares to reduce turnaround time. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0700 — 2025-11-29 — Unit AX7300-BC-0733

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 1.8 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0701 — 2025-11-29 — Unit AX7300-BC-0402

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 5.5 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Feedback on this document is welcome and should be sent to the owning department. Nothing in this section overrides an applicable statutory obligation.

Entry 0702 — 2025-11-30 — Unit AX7300-BC-0613

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 1.3 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Training on this section forms part of the standard onboarding programme. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0703 — 2025-11-30 — Unit AX7200-BC-0564

Technician: J. Oyelaran **Reported fault:** E-204 **Labour:** 2.6 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0704 — 2025-12-01 — Unit AX7300-BC-0482

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 5.3 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Calibration certificates are held by the metrology team and are available on request. This section is reviewed each year by the responsible department head.

Entry 0705 — 2025-12-01 — Unit AX7300-BC-0199

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 5.0 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The depot maintains a rolling stock of common spares to reduce turnaround time. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0706 — 2025-12-01 — Unit AX7300-BC-0233

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 4.2 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Photographic evidence should accompany any report of physical damage. This section is reviewed each year by the responsible department head.

Entry 0707 — 2025-12-02 — Unit AX7300-BC-0881

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 4.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Training on this section forms part of the standard onboarding programme. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0708 — 2025-12-02 — Unit AX7300-BC-0218

Technician: J. Oyelaran **Reported fault:** E-142 **Labour:** 5.6 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Deviation from the documented procedure must be noted in the deployment record.

Entry 0709 — 2025-12-03 — Unit AX7200-BC-0390

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 2.0 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Deviation from the documented procedure must be noted in the deployment record. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0710 — 2025-12-03 — Unit AX7300-BC-0323

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 5.8 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The depot maintains a rolling stock of common spares to reduce turnaround time. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0711 — 2025-12-04 — Unit AX7300-BC-0917

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 5.0 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0712 — 2025-12-04 — Unit AX7200-BC-0343

Technician: J. Oyelaran **Reported fault:** E-119 **Labour:** 0.6 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Questions about the interpretation of this section should be directed to your manager in the first instance. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0713 — 2025-12-05 — Unit AX7200-BC-0330

Technician: R. Fairweather **Reported fault:** None (scheduled service) **Labour:** 4.8 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0714 — 2025-12-05 — Unit AX7200-BC-0288

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 4.5 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Records created under this section are retained in accordance with the company retention schedule. Training on this section forms part of the standard onboarding programme.

Entry 0715 — 2025-12-06 — Unit AX7200-BC-0151

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 1.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Supporting templates are published on the internal documentation portal. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0716 — 2025-12-06 — Unit AX7200-BC-0378

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 4.1 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Any conflict between this document and a signed customer agreement should be escalated promptly. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0717 — 2025-12-07 — Unit AX7200-BC-0960

Technician: K. Nakamura **Reported fault:** E-119 **Labour:** 1.2 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0718 — 2025-12-07 — Unit AX7200-BC-0668

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 3.8 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Nothing in this section overrides an applicable statutory obligation.

Entry 0719 — 2025-12-08 — Unit AX7300-BC-0236

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 2.6 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Consumable parts are excluded from the scope of the standard service agreement. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0720 — 2025-12-08 — Unit AX7200-BC-0997

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 2.9 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

The depot maintains a rolling stock of common spares to reduce turnaround time. Training on this section forms part of the standard onboarding programme.

Entry 0721 — 2025-12-09 — Unit AX7300-BC-0204

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 3.2 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0722 — 2025-12-09 — Unit AX7200-BC-0751

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 2.7 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Supporting templates are published on the internal documentation portal. Feedback on this document is welcome and should be sent to the owning department.

Entry 0723 — 2025-12-10 — Unit AX7300-BC-0048

Technician: M. Castellanos **Reported fault:** None (scheduled service) **Labour:** 3.3 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Photographic evidence should accompany any report of physical damage. Where a form is prescribed, the current version of that form must be used.

Entry 0724 — 2025-12-10 — Unit AX7300-BC-0725

Technician: J. Oyelaran **Reported fault:** E-311 **Labour:** 2.0 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Feedback on this document is welcome and should be sent to the owning department. Any conflict between this document and a signed customer agreement should be escalated promptly.

Entry 0725 — 2025-12-10 — Unit AX7200-BC-0447

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 2.0 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Where local regulation imposes a stricter requirement, the stricter requirement applies. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0726 — 2025-12-11 — Unit AX7300-BC-0350

Technician: S. Duplessis **Reported fault:** E-311 **Labour:** 0.6 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

The depot maintains a rolling stock of common spares to reduce turnaround time. Photographic evidence should accompany any report of physical damage.

Entry 0727 — 2025-12-11 — Unit AX7300-BC-0965

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 0.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Serial numbers must be transcribed exactly as they appear on the unit label. The requirements below apply to permanent staff, fixed-term staff, and contractors alike.

Entry 0728 — 2025-12-12 — Unit AX7200-BC-0699

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 3.5 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Where a form is prescribed, the current version of that form must be used. This section is reviewed each year by the responsible department head.

Entry 0729 — 2025-12-12 — Unit AX7200-BC-0503

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 1.7 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Records created under this section are retained in accordance with the company retention schedule. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0730 — 2025-12-13 — Unit AX7200-BC-0150

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 1.1 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Where a form is prescribed, the current version of that form must be used. This section is reviewed each year by the responsible department head.

Entry 0731 — 2025-12-13 — Unit AX7300-BC-0683

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 3.7 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

The depot maintains a rolling stock of common spares to reduce turnaround time. This section is reviewed each year by the responsible department head.

Entry 0732 — 2025-12-14 — Unit AX7300-BC-0624

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 5.2 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Where local regulation imposes a stricter requirement, the stricter requirement applies. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0733 — 2025-12-14 — Unit AX7200-BC-0120

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 4.5 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Measurements should be recorded in SI units unless a customer specification requires otherwise. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0734 — 2025-12-15 — Unit AX7200-BC-0264

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 5.0 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Feedback on this document is welcome and should be sent to the owning department. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0735 — 2025-12-15 — Unit AX7200-BC-0174

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 1.9 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Training on this section forms part of the standard onboarding programme.

Entry 0736 — 2025-12-16 — Unit AX7200-BC-0394

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 0.9 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

Deviation from the documented procedure must be noted in the deployment record. Where a form is prescribed, the current version of that form must be used.

Entry 0737 — 2025-12-16 — Unit AX7300-BC-0359

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 3.2 h

Action taken: Housing returned from factory recalibration. Certificate filed and unit released to service.

Exceptions require written approval from the relevant department head before the activity begins. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0738 — 2025-12-17 — Unit AX7300-BC-0627

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 2.6 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

This section is reviewed each year by the responsible department head. Deviation from the documented procedure must be noted in the deployment record.

Entry 0739 — 2025-12-17 — Unit AX7200-BC-0457

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 1.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Nothing in this section overrides an applicable statutory obligation. Shipping arrangements are confirmed in writing before any unit leaves the depot.

Entry 0740 — 2025-12-18 — Unit AX7300-BC-0193

Technician: R. Fairweather **Reported fault:** E-119 **Labour:** 3.4 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Turnaround targets are measured from the date the unit is received, not the date it was shipped. Calibration certificates are held by the metrology team and are available on request.

Entry 0741 — 2025-12-18 — Unit AX7300-BC-0943

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 1.0 h

Action taken: Battery pack capacity tested at 84 per cent of nominal. Flagged for replacement at next service.

Shipping arrangements are confirmed in writing before any unit leaves the depot. Managers are responsible for ensuring their teams understand the requirements set out here.

Entry 0742 — 2025-12-19 — Unit AX7200-BC-0534

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 3.3 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Where local regulation imposes a stricter requirement, the stricter requirement applies. The depot maintains a rolling stock of common spares to reduce turnaround time.

Entry 0743 — 2025-12-19 — Unit AX7200-BC-0284

Technician: K. Nakamura **Reported fault:** E-204 **Labour:** 5.7 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

Questions about the interpretation of this section should be directed to your manager in the first instance. Records created under this section are retained in accordance with the company retention schedule.

Entry 0744 — 2025-12-19 — Unit AX7300-BC-0705

Technician: M. Castellanos **Reported fault:** E-204 **Labour:** 3.5 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

This section is reviewed each year by the responsible department head. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0745 — 2025-12-20 — Unit AX7300-BC-0356

Technician: K. Nakamura **Reported fault:** E-311 **Labour:** 2.2 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Nothing in this section overrides an applicable statutory obligation.

Entry 0746 — 2025-12-20 — Unit AX7300-BC-0825

Technician: S. Duplessis **Reported fault:** E-142 **Labour:** 1.5 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Questions about the interpretation of this section should be directed to your manager in the first instance. Exceptions require written approval from the relevant department head before the activity begins.

Entry 0747 — 2025-12-21 — Unit AX7300-BC-0961

Technician: J. Oyelaran **Reported fault:** None (scheduled service) **Labour:** 1.5 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Deviation from the documented procedure must be noted in the deployment record. Calibration certificates are held by the metrology team and are available on request.

Entry 0748 — 2025-12-21 — Unit AX7200-BC-0960

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 3.8 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

Supporting templates are published on the internal documentation portal. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0749 — 2025-12-22 — Unit AX7300-BC-0258

Technician: R. Fairweather **Reported fault:** E-142 **Labour:** 5.7 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Field teams should record ambient conditions at the start and end of every deployment. Consumable parts are excluded from the scope of the standard service agreement.

Entry 0750 — 2025-12-22 — Unit AX7200-BC-0507

Technician: S. Duplessis **Reported fault:** E-204 **Labour:** 3.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Exceptions require written approval from the relevant department head before the activity begins. Where local regulation imposes a stricter requirement, the stricter requirement applies.

Entry 0751 — 2025-12-23 — Unit AX7200-BC-0947

Technician: S. Duplessis **Reported fault:** None (scheduled service) **Labour:** 5.7 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Serial numbers must be transcribed exactly as they appear on the unit label.

Entry 0752 — 2025-12-23 — Unit AX7200-BC-0665

Technician: K. Nakamura **Reported fault:** None (scheduled service) **Labour:** 1.6 h

Action taken: Sacrificial anode replaced at 60 per cent consumption. Housing inspected for pitting.

Training on this section forms part of the standard onboarding programme. Records created under this section are retained in accordance with the company retention schedule.

Entry 0753 — 2025-12-24 — Unit AX7200-BC-0012

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 0.7 h

Action taken: Firmware updated and deployment log downloaded for analysis. Unit returned to stock.

Supporting templates are published on the internal documentation portal. Records created under this section are retained in accordance with the company retention schedule.

Entry 0754 — 2025-12-24 — Unit AX7200-BC-0473

Technician: K. Nakamura **Reported fault:** E-142 **Labour:** 4.6 h

Action taken: Main O-ring replaced and housing pressure tested to rated depth. No leak detected.

Serial numbers must be transcribed exactly as they appear on the unit label. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0755 — 2025-12-25 — Unit AX7200-BC-0754

Technician: S. Duplessis **Reported fault:** E-119 **Labour:** 1.4 h

Action taken: Connector pins cleaned and re-greased. Continuity verified across all conductors.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Questions about the interpretation of this section should be directed to your manager in the first instance.

Entry 0756 — 2025-12-25 — Unit AX7300-BC-0780

Technician: A. Whitcombe **Reported fault:** E-119 **Labour:** 3.1 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Supporting templates are published on the internal documentation portal. Nothing in this section overrides an applicable statutory obligation.

Entry 0757 — 2025-12-26 — Unit AX7200-BC-0204

Technician: R. Fairweather **Reported fault:** E-204 **Labour:** 1.2 h

Action taken: Transducer face cleaned and bench calibration re-run. Within tolerance on retest.

The procedure assumes the operator has completed the standard competency assessment. Measurements should be recorded in SI units unless a customer specification requires otherwise.

Entry 0758 — 2025-12-26 — Unit AX7200-BC-0994

Technician: A. Whitcombe **Reported fault:** None (scheduled service) **Labour:** 4.1 h

Action taken: Pressure port cleared of biofouling. Sensor reading verified against reference.

Field teams should record ambient conditions at the start and end of every deployment. Deviation from the documented procedure must be noted in the deployment record.

Entry 0759 — 2025-12-27 — Unit AX7200-BC-0683

Technician: M. Castellanos **Reported fault:** E-119 **Labour:** 3.6 h

Action taken: Hydrophone array element continuity checked. One element intermittent; head returned to factory.

The requirements below apply to permanent staff, fixed-term staff, and contractors alike. Turnaround targets are measured from the date the unit is received, not the date it was shipped.

Entry 0760 — 2025-12-27 — Unit AX7200-BC-0063

Technician: M. Castellanos **Reported fault:** E-142 **Labour:** 5.8 h

Action taken: Scheduled twelve-month service completed. All checks passed and calibration certificate issued.

Nothing in this section overrides an applicable statutory obligation. Feedback on this document is welcome and should be sent to the owning department.