EO

SolidWorks Shortcuts Cheat Sheet

54 keyboard and mouse shortcuts to model faster

Tip: press **S** for the shortcut bar and **Space** for views. Add your own keys in **Tools › Customize › Keyboard**.

View orientation

Space	View selector / orientation
Ctrl+1	Front
Ctrl+2	Back
Ctrl+3	Left
Ctrl+4	Right
Ctrl+5	Top
Ctrl+6	Bottom
Ctrl+7	Isometric
Ctrl+8	Normal to selected face

Zoom, rotate & pan

F	Zoom to fit
Z	Zoom out
Shift+Z	Zoom in
G	Magnifying glass
← → ↑ ↓	Rotate the view
Shift+arrow	Rotate 90°
Alt+ ← / →	Spin around the screen centre
Ctrl+arrow	Pan
F11	Full screen

Mouse

Scroll	Zoom at the pointer
Middle drag	Rotate
Ctrl+middle	Pan
Shift+middle	Zoom
Middle ×2	Zoom to fit
Right drag	Mouse gestures (quick commands)

Interface

F9	Show / hide the FeatureManager tree
F10	Show / hide toolbars
F5	Selection filter toolbar
F6	Turn selection filters on / off
C	Expand / collapse a tree branch
Shift+C	Collapse the whole tree

File & everyday

Ctrl+N	New document
Ctrl+O	Open
Ctrl+S	Save
Ctrl+P	Print
Ctrl+Z	Undo
Ctrl+Y	Redo
Ctrl+C / V	Copy / paste
Ctrl+B	Rebuild
Ctrl+Q	Force rebuild (everything)
Ctrl+Tab	Next open document
Enter	Repeat the last command
Esc	Cancel / exit the tool
S	Shortcut bar at the pointer
D	Move the OK / cancel corner to the pointer

Sketching tips

A	Switch line ↔ tangent arc while drawing
Hold Ctrl	Sketch without automatic relations
Ctrl+click	Select several entities to add a relation
Shift+click arc	Dimension to the arc's min / max point
Double-click	End a chain of lines

Assemblies

Tab	Hide the component under the pointer
Shift+Tab	Show the hidden component under the pointer
Alt+drag	SmartMate: drag a face onto another
Ctrl+drag	Copy a component
Shift+click	Select a range in the tree

Edison Ochieng · Nexus CAD Studio · SolidWorks, Inventor, AutoCAD & Fusion 360 training

WhatsApp **+254 708 639 473** · edisonengineer.github.io/MY-PAST-PROJECTS