

Harbour Bridge Inspection Report

Prepared by the **structures team** following the winter storm cycle. Severity uses the *national bridge index* conventions.

Findings

- Expansion joints show normal seasonal movement
- Two bearing plates require regreasing within ninety days
- Deck drainage cleared and functioning at all test points

Load Ratings

Span	Rating	Status
Main	94%	Pass
North approach	88%	Pass
South approach	71%	Monitor

The south approach remains **serviceable** but moves to a six-month inspection interval until the bearing work is complete.