

F M S 10 - 49**SUPPLEMENT FOR**
TRANSMISSION/GEARBOX CHIP WARNING**1. GENERAL**

This supplement shall be attached to the BO 105 Flight Manual (Section 10) when the TRANSMISSION/GEARBOX CHIP WARNING has been installed.

System/Equipment Designation	Part No.	Effectivity
Transmission Chip Warning	105-98265	All
Tail-rotor/Intermediate Gearbox Chip Warning	105-982656	All

The information contained herein supplements the information of the basic Flight Manual; for limitations, procedures, and performance data not contained in this supplement, refer to the basic Flight Manual.

NOTE For approving authorities and original issue date of this supplement, refer to the Log of Supplements.