

Note for some reason Freerouter connected
U38 pin 6 to U10 pin 9 and U5A pin 5 to U10 pin 6.
These traces have been removed by hand on the final board
before Gerber files were made.