

Note: The tether hole is wider than it needs to be because the waterjet cut the hole too big so it has been made larger so it will fit a connector well

Note: Both end plates are being viewed from the outside of the vehicle