







 PT. MNA SERANG	WORKING INSTRUCTION Low Output or No Output Temperature Transmitter	WI/MNASRG-E&I-19-103	
		Dept.	ENGINEERING
		Section	E&I
		Revision	0
		Effective Date	
		Page	1 of 1 page

Instruksi / Instruction	
Persiapan Alignment / Prepare of Alignment Process	
	
Siapkan peralatan dan APD (Prepare equipment and APD)	Identification: Keluaran rendah atau tinggi atau tidak ada keluaran (Low Output or No Output)
Pengecekan Elemen Sensor/Sensor Element Checking	
	
Hubungkan field communicator dan masukkan Mode uji pemancar untuk mengisolasi kegagalan sensor.(Connect a Field Communicator and enter the Transmitter test mode to isolate a sensor failure. And Check the process variable to see if it is out of range.)	Cek variabel proses yang sesuai dengan range (Check the process variable to see if it is out of range.)
Loop Wiring Test	
	
Cek tegangan pada transmitter (Check for adequate voltage to the transmitter.)	Cek polaritas sinyal (Check for proper polarity at the signal)
	
Konesikan Field Communicator dan lakukan kalibrasi (Connect a Field Communicator calibration adjustments)	Ganti instrument, apabila sudah tidak bisa digunakan (Replace the instrument if cant not applied)