

Calibration Pressure DWT

First step:
Inform the workshop operation content, inform the operation purpose, and sign the work ticket.



Second step:
Prepare The P3124 Hydraulic Deadweight Tester Tools and straighten the water pass bubble



Third step:
Install Instrument Gauge to fluke 3120



Fourth step:
Do the priming setup before performing the initial calibration, to remove the air in the calibrator



Fifth step:
Open the reservoir valve one turn counterclockwise



Sixth step:
Pump using a hand pump 2 times



Seventh step:
Close the reservoir valve and rotate the capstan until it comes out full




Eighth step:
if there are no air bubbles in the dust cover, the DWT is ready to use



The Ninth step :
Select mass according to calibration requirement (1 bar)



Ten step:
Hand pump to increase pressure




Eleven step:
Rotate to mass produce a stable pressure





Twelve step:
Take mass to increase pressure DWT (5 bar)



Thirteen step:
Hand pump again to increase pressure



Fourteen step: :
Rotate the mass to produce a stable pressure



File: WI-Calibration Pressure Gauge
using DWT

Signer: **Muhammad**
Chorihuddin

Date of issue: **30 Juni 2022**

version: 1.0