


Order: 243030

Dear Customer, thank you for your order. Please refer below technical queries observed during preproduction work on your supplied files. Request you to go through all below exceptions and confirm back your point wise replies in this same file to maintain the proper record.

Problem description 1:

As per gerber data we have found one carbon type pad in top side but in order detail its option is not selected as shown in below screen dump picture.



Solder mask color bottom Red

Legend top White

Legend bottom White

Surface finish HAL (Sn-Pb)

Via-fill No

via-tili No

Peel-off No Peel Off

Carbon contacts

Edge connector

Edge connector gold thickness

Blind & buried via

No Carbon Contacts

0.00

Mo Carbon Contacts

Impedance control No

Implemented solution:

We have continued order as it is as per gerber data without carbon contact.

To continue the order after you have reviewed the issues, you have two options:

- 1. Click on the "Approve" button to accept the proposed solution(s).
- 2. Click on the "Not Approve" button to reject the proposed solution(s).