

Exercise 3 — Source Packet

Everything the assistant was given. Check the outputs against this — and only this.

Fictional. Meridian Technical Services.

S1 — Standards and procedure register (extract)

Reference	Title	Revision	Status	Issued
MTS-PR-112	Examination Planning and Sequencing	Rev D	Current	2024-03
MTS-PR-114	Wall Thickness Findings Below Design Minimum	Rev B	Current	2025-01
MTS-PR-114	Wall Thickness Findings Below Design Minimum	Rev A	Superseded	2019-06
MTS-PR-118	Immediate Notification to Client	Rev C	Current	2024-11
MTS-PR-121	Records Issue and Retention	Rev B	Current	2023-09
MTS-PR-130	Fitness-for-Service Assessment	Rev A	Current	2025-04

No other revisions of any of the above are in issue.

S2 — MTS-PR-114 Rev B, clause 7.4 (verbatim extract)

7.4 — Vessels exhibiting readings below design minimum

Where examination identifies any measured value below the established design minimum, the vessel **shall not be returned to service** on the basis of a shortened re-examination interval, at full or reduced operating pressure.

Return to service shall require, in sequence:

- (a) a fitness-for-service assessment carried out to MTS-PR-130;
- (b) written authorisation by the designated Technical Authority; and
- (c) entry of both (a) and (b) in the vessel record before service resumes.

This clause departs from common industry practice, which permits return to service under a shortened interval in defined circumstances. **The departure is deliberate.** Rev A of this procedure permitted the shortened-interval route; that provision was withdrawn in 2025 following internal review.

S3 — Examination programme figures (as at end of period)

Figure	Value
Vessels in scope	214
Vessels examined to date	61
Planned to date	84
Cleared without remediation	52
Minor remediation required	7
Below allowable limit	2
Examination rate	~11 per week, 2 teams
Additional reconciliation hours beyond tender	340
Value of unrecovered reconciliation effort	~£41,000
Margin at completion if variation refused	~12% (from 18%)
Variation request submitted	2 May — unanswered
Invoices submitted	All paid within terms
Three unaccounted vessels — client query raised	Unanswered, 6 weeks

S4 — Examination findings, HP-A-118 and HP-A-141

	HP-A-118	HP-A-141
Nominal wall thickness	14.2 mm	14.2 mm
Design minimum	11.8 mm	11.8 mm
Grid points measured	46	44
Points below design minimum	7	5
Minimum recorded value	10.4 mm (grid D4)	10.9 mm (grid C4)
Manufacturing batch	1997-K	1997-K

Batch 1997-K: 21 units in the examination population. 2 found below limit. 4 examined and cleared. **15 not yet examined.**

Rate of loss: cannot be established from a single examination. The previous recorded examination of either unit was in 2018 and consists of a scanned handwritten summary **without recorded measurement values.**

Resequencing of the remaining 15 units: requested of the client. **No direction received.**

S5 — Policy statement 4.3 (verbatim, complete)

4.3 — Independence of examination and assessment

Meridian Technical Services maintains a separation between the personnel who carry out examination and those who determine fitness for service. This separation exists to ensure that the determination is not influenced by the commercial or schedule position of the examination activity. It applies to all engagements irrespective of client preference, and is not subject to waiver at engagement level. Where a client requests a combined arrangement, the request is declined and the reason recorded.

This is the complete text of policy statement 4.3. There is no further text and no associated procedure.

S6 — Staff survey (summary of the 40 comments)

The full 40 comments are Document B from Exercise 2. Relevant characteristics:

- **7 comments** are explicitly positive about the process itself
 - Complaints concentrate on **implementation**: the application, duplication with existing paperwork, inadequate training, connectivity
 - Several critics state that the **process is sound and the software is not**
 - **No comment requests that the briefing be withdrawn**
 - Roughly **24** comments are wholly negative in tone; the remainder are positive, mixed, or neutral
-

End of source packet.