

Troubleshooting of Redmi note9 4G automatic 9008

power amplifier MOSFET and eMMC/UFS share 1.8 VCC,
which leads to eMMC/UFS VCC problem, and eMMC/UFS

cannot be identified

Thereby entering the 9008 port Reballing or

