

Multimeter: fluke 115C

Multimeter: fluke 115C

The main power supply, hard disk lamp and other chips can refer to XS and XSMAX

The main power supply, hard disk lamp and other chips can refer to XS and XSMAX

300	300	0L	0L	0L	0	0L
0L	0L	0	0L	0L	0	0L
0L	0L	0	0	300	300	300
0L	0L	0	346	346	346	380
0L	0L	0	345	495	544	291
0L	0L	0	0	0	0	291
0	0	0	347	0	0	0L
0L	0L	299	348	537	291	374

[illegible]