









212_MM_05_0007

Figure 5-7. Inspection of Main Rotor Hub Grip (1200 Hours)