

NOTE: Use maximum of three steel washers under each nut to obtain proper thread engagement.

- 1. Bolt (2 places)
- Steel washer (MS20002C4)
 Forward deck fitting
- 4. Deck fitting shim
- 5. Steel washers (see NOTE)
- 6. Nut (2 places)

- 7. Bolt (2 places)
- 8. Steel washer (MS20002C6)

- 9. Aft deck fitting 10. Deck fitting shim 11. Deck fitting shim
- 12. Steel washer (see NOTE)
- 13. Nut (2 places)

212-M-71-27

Figure 71-27. Aft right mount bipod deck fitting