

Cycle	reset	PC	Instruction	branch	srca	srcb	aluout	zero	pcsrc	writedata	memwrite	read data
1	1	00	addi \$2, \$0, 5 20020005	0	0	5	5	0	0	0	0	x
2	0	04	addi \$3, \$0, 12 2003000c	0	0	c	c	0	0	0	0	x
3	0	08	addi \$7, \$3, -9 20067fff7	0	c	-9	3	0	0	0	0	x
4	0	0C	or \$4, \$7, \$2	0	3	5	7	0	0	5	0	x
5	0	10	and \$5, \$3, \$4	0	c	7	4	0	0	7	0	x
6	0	14	add \$5, \$5, \$4	0	4	7	b	0	0	7	0	x
7	0	18	beq \$5, \$7, end	1	b	3	8	0	0	3	0	x
8	0	1c	slt \$4, \$3, \$4	0	c	7	0	1	0	7	0	x
9	0	20	beq \$4, \$3, around	1	0	0	0	1	1	0	0	x
10	0	28	slt \$4, \$7, \$2	0	3	5	1	0	0	5	0	x
11	0	2c	add \$7, \$4, \$5	0	1	b	c	0	0	b	0	x
12	0	30	sub \$7, \$7, \$2	0	c	5	7	0	0	5	0	x
13	0	34	sw \$7, 68(\$3)	0	c	44	50	0	0	7	1	x
14	0	38	lw \$2, 80(\$0)	0	0	50	50	0	0	5	0	7
15	0	3c	j end	x	x	x	x	x	x	x	x	x
16	0	44	sw \$2, 84(\$0)	0	0	54	54	0	0	7	1	x