

-60

-80

-100

40

20

-80 -60 -40 calibrate actual printed dimension. Check both X and Y

0 -20 ond Y. Measure between tick 0 and last tick

20

40

50

80