intertek
Total Quality. Assured.

TEST REPORT Number : WUXH00099913

Applicant : ZHEJIANG CHAIRMENG TECHNOLOGIES COMPANY COMPANY LIMITED
CHAIRMENG TECHNOLOGIES COMPANY LIMITED (GUOHUA FURNITURE),YANGGUANG INDUSTRIAL PARK,DIPU TOWN,ANJI COUNTY HUZHOU CITY, ZHEJIANG PROVINCE
Attn : WANG ZHIYIN

Date : Apr 17, 2020

Sample Description:
One(1) Group Of Submitted Sample Said To Be :
Item Name : 25# Foam-HR.

Tests Conducted:
As Requested By The Applicant, For Details Refer To Attached Page(s).

Conclusion:
Based Upon The Test Results Reported, The Sample Meets The Requirement Of Schedule 1 Part I Of The Furniture And Furnishings (Fire) (Safety) Regulations 1988 (As Amended).

Prepared And Checked By:
For Intertek Testing Services Wuxi Ltd.

Peter Chen
General Manager

INTERTEK TESTING SERVICES WUXI LTD. 无锡天祥质量技术服务有限公司 检验检测专用章

Intertek Testing Services Wuxi Ltd.
无锡天祥质量技术服务有限公司
No.8 Fubei Road, Xishan Economic Development Zone, Wuxi, Jiangsu, China. 214101
江苏省无锡市锡山经济开发区府北路 8 号 214101
Tel: +86 510 8821 4567
Fax: +86 510 8820 0428
www.intertek.com.cn
www.intertek.com

TEST REPORT Number : WUXH00099913

Tests Conducted (As Requested By The Applicant)

1 Flammability Test (BS 5852 Part 2:1982, Crib Test):

The Test, Specified In Schedule 1 Part I Of The Furniture And Furnishings (Fire) (Safety) Regulations 1988 (As Amended In 1989,1993 And 2010), Is Based On BS 5852 Part 2:1982 Using Ignition Source 5 - Crib Test.

To Assess The Ignitability Of Polyurethane Foam Filling With Standard Cover Fabric When Subjected To A Burning Crib.

The Following Test Results Relate Only To The Ignitability Of The Combination Of Upholstery Composites Under The Particular Conditions Of Test; They Are Not Intended As A Means Of Assessing The Full Potential Fire Hazard Of The Materials In Use.

Criterion Of Ignition: Ignition Source 5 - Crib.
Conditioning : 72 Hours Indoor Ambient And At Least 16 Hours Of 20±5°C, 50±20% Relative Humidity.
Testing Atmosphere : 15-30°C, 20-70% Relative Humidity
Performance Requirement : Clause 4.1-4.2 Of BS 5852 Part 2:1982

Test Result:

Progressive Smoldering Failure		1st Test	Retest
(A)	Any Composite That Produces Externally Detectable Amounts Of Smoke, Heat Or Glowing 60 Minutes After Ignition Of The Crib;	No	No
(B)	Any Composite That Displays Escalating Combustion Behaviour So That It Is Unsafe To Continue The Test And Requires Forcible Extinction;	No	No
(C)	Any Composite That Smoulders Until It Is Essentially Consumed Within The Test Duration;	No	No
(D)	Any Composite That Smoulders To The Extremities Of The Specimen Viz Upper Or Lower Margins, Either Side Or To Its Full Thickness, Within The Duration Of The Test;#	No	No
(E)	Any Composite That, On Final Examination, Shows Evidence Of Charring Other Than Discolouration, More Than 100 Mm In Any Direction Apart From Upwards From The Nearest Part Of The Original Position.#	No	No

Intertek Testing Services Wuxi Ltd.
无锡天祥质量技术服务有限公司
No.8 Fubei Road, Xishan Economic Development Zone, Wuxi, Jiangsu, China. 214101
江苏省无锡市锡山经济开发区府北路 8 号 214101
Tel: +86 510 8821 4567
Fax: +86 510 8820 0428
www.intertek.com.cn
www.intertek.com

TEST REPORT Number : WUXH00099913

Tests Conducted (As Requested By The Applicant)

Flaming Failure		1st Test	Retest
(A)	Any Composite That Continues To Flame For More Than 10 Minutes After The Ignition Of The Crib;	No	No
(B)	Any Composite That Displays Escalation Combustion Behaviour So That It Is Unsafe To Continue The Test And Requires Forcible Extinction;	No	No
(C)	Any Composite That Burns Until It Is Essentially Consumed Within The Test Duration;	No	No
(D)	Any Composite On Which Any Flame Front Reaches The Lower Margin, Either Side Or Passes Through The Full Thickness Of The Specimen Within The Duration Of The Test.#	No	No

Resultant Mass Loss	1st Test	Retest
	29 G	31 G

Foam	Ignition Source	Time To Extinction After Placement Of Ignition Source			
Test No.		Flaming Ceased Time		Smoking Ceased Time	
		Min	Sec	Min	Sec
1	5	4	21	6	51
Retest	5	4	41	7	10
Ignitability Performance Index		P5			

Remark : No = Was not observed
= If failure against the criteria and provided that the resultant mass loss was less than 60 g the foam pass the ignitability test

Date Sample Received: Apr 13, 2020
Testing Period: Apr 13, 2020 To Apr 16, 2020

Intertek Testing Services Wuxi Ltd.
无锡天祥质量技术服务有限公司
No.8 Fubei Road, Xishan Economic Development Zone, Wuxi, Jiangsu, China. 214101
江苏省无锡市锡山经济开发区府北路 8 号 214101
Tel: +86 510 8821 4567
Fax: +86 510 8820 0428
www.intertek.com.cn
www.intertek.com

TEST REPORT Number： WUXH00099913

Tests Conducted (As Requested By The Applicant)

Photo



End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

This report shall not be reproduced except in full, without written approval of the laboratory

Intertek Testing Services Wuxi Ltd.
无锡天祥质量技术服务有限公司

No.8 Fubei Road, Xishan Economic Development Zone, Wuxi, Jiangsu, China. 214101
江苏省无锡市锡山经济开发区府北路 8 号 214101

Tel: +86 510 8821 4567
Fax: +86 510 8820 0428
www.intertek.com.cn
www.intertek.com