COPPER & BRASS

TU1

MATERIAL / REFERENCE CONDITION

Oxygen-free copper

Typical applications Electrical and thermal components requiring low oxygen content

Material type	Oxygen-free copper
Condition / reference grade	Specify annealed, half-hard or hard condition
Manufacturing	Machining · forming
Reference data	Jintian publishes grade and temper-specific data. Strip data must not be used as bar-stock acceptance limits.
Specification notes	Confirm oxygen and purity limits from the actual mill certificate.

Original technical reference | Jintian Copper

Mill strip catalogue (PDF)

jtcopper.com | External publisher; reference only

Selection reference, not a material certificate or guaranteed purchasing specification. Properties apply only to the stated grade, form, condition and test method. Branded examples do not establish Metalcorex stock or supplier identity. Confirm the production specification, supplier sheet and required records with your quotation.