


MATERIAL: 16 GA (0.0598) UNITS: INCHES SCALE: NTS PLASMA PROGRAM: laminated_panel.gm



1. Bend lines are at the sketch dimensions on the flat blank.
2. Confirm whether sketch dims are flat or formed; bend deduction not applied.
3. Angle and direction not on sketch: fill in before forming.
4. End tabs (7/8 x 3/4) sit between BL2 and BL3; check tab/flange clearance.

