

HEARTHSTONE MUTUAL - LOSS CONTROL
PLAYGROUND SAFETY AUDIT

REPORT LC-5538

INSURED LITTLE ACORN EARLY LEARNING

LOCATION RIVERSIDE CENTER

SURVEY DATE 09/10/2026

RECOMMENDATIONS

R-1 Mulch under climber only 4 in deep, 9 in required
PRIORITY 1 COMPLETE WITHIN 30 DAYS

R-2 Toddler yard gate latch does not self-close
PRIORITY 2 COMPLETE WITHIN 14 DAYS

R-3 Swing hanger bolt missing its locking nut
PRIORITY 1 COMPLETE WITHIN 7 DAYS

REPEAT OF LC-5361 R-4 (03/12/2026)

Sand box has no cover

PRIORITY 3 COMPLETE WITHIN 60 DAYS

COMPLETION PERIODS RUN FROM THE SURVEY DATE