

Industrial Equipment Maintenance Manual

Motor Maintenance

Regular inspection of motors includes checking for overheating, unusual noise, vibration, and burnt smell. Overheating motors should be shut down immediately and inspected for insulation damage, bearing failure, or overload conditions.

Belt and Conveyor Maintenance

Conveyor belts should be inspected for wear, cracks, and misalignment. Belt tension must be checked regularly. Worn belts should be replaced immediately to prevent production stoppage.

Bearing Maintenance

Bearings should be lubricated every 500 hours. Signs of bearing failure include grinding noise, excessive heat, and vibration. Failed bearings must be replaced immediately.

Electrical Panel Maintenance

Electrical panels should be inspected for loose connections, burnt components, and overheating. Circuit breakers should be tested monthly.

Pump Maintenance

Pumps should be checked for leaks, cavitation, and abnormal vibration. Seals and impellers should be inspected every 1000 hours of operation.