

1065 Henry Eng. Pl. Langford BC, Canada V9B 6B2

Email: fts-techsupport@aem.eco **USA Phone:** +1 (301) 250-4221 Canada Phone: +1 (778) 715-7050

# Service Report: Temperature and Humidity Sensor (THS)

Serial Number	556677	Date of Service	2023-11-27
RMA#	RMA-TEST	Support Ticket	CST-TEST
Sales Order Number	SO-TEST	Customer Number	FTS TEST

## **Details of Service Preformed**

#### **Sensor Information**

Internal Module Serial	992288	THS Model	THS-3-R
Number	992200	T ITS Model	1113-3-K

This sensor was received for the following operation: **Upgrade/Mod.** 

# Additional Notes on the Incoming Condition of the Sensor:

These are my incoming notes of the sensors condition

## Service Work Checklist

- Initial Checks: Failed Explain in Comments
- Internal Module Firmware Updated to version:
- Full Visual Inspection of the Sensor: Completed by the Tech
- Thorough Cleaning of the Sensor: Completed
- Cable-To-Module Srews: Installed
- Builentins Referenced for repairs: None

### **Calibration Checklist**

- Incoming Humidity Test: Unable to Test
- Incoming Temperature Test: Unable to Test
- Repairs: Repairs Preformed
- Active Current Test: Passed
- Humidity Callibration: Passed, within +/-2%
- Temperature Calibration: Passed, within +/-

0.2C

#### **Component Verification or Replacement Checklist**

• Humidity Wafer: Replaced • Porex Filter: Replaced • **Desiccant Packet:** Replaced

**Warranty Status:** No Warranty

Tech: EVERLY TEST

#### **Service Notes:**

This is a test