

1065 Henry Eng. Pl. Langford BC, Canada V9B 6B2

Email: fts-techsupport@aem.eco **USA Phone:** +1 (301) 250-4221 **Canada Phone:** +1 (778) 715-7050

Service Report: Fuel Stick

Serial Number	112233	Date of Service	2023-11-28
RMA#	RMA-TESTFS	Support Ticket	CST-TESTFS
Sales Order Number	SO-TESTFS	Customer Number	FTS TESTFS

Details of Service Preformed

Sensor Information

Internal Module Serial	009988	THS Model	FS-3-R
Number			

This sensor was received for the following operation: Other (Desc. in Comments)

Additional Notes on the Incoming Condition of the Sensor:

INCOMINGNOTES

Service Work Checklist

- Initial Checks: Failed Explain in Comments
- Internal Module Firmware Updated to version: 15
- Full Visual Inspection of the Sensor: Completed by the Tech
- Thorough Cleaning of the Sensor: Completed
- Cable-To-Module Srews: Installed
- Builentins Referenced for repairs: Yes See Comments

Calibration Checklist

- Incoming Humidity Test: Unable to Test
 Incoming Temperature Test: Unable to Test
- **Repairs:** Repairs Preformed
- Active Current Test: Passed
- Humidity Callibration: Passed, within +/-2%
- Temperature Calibration: Passed, within +/-0.2C

Component Verification or Replacement Checklist

Humidity Wafer: ReplacedPorex Filter: ReplacedDesiccant Packet: Replaced

• Dowel: Replaced

Service Notes:

The techs service comments will go here

Warranty Status: No Warranty

Tech: Everly TESTING

ISO-XXX-XXXX

Rev: 0 1 of 1 Report Generated on: 2023-11-29