Property Inspection Report

Residential Pre-Signing Inspection Summary for TX001

Property	Unit 1801, Building 7, Jinyu Lanwan
Inspection Date	2026-03-17
Inspection Type	Visual non-invasive residential inspection
Inspector	HomeCheck Residential Services
Occupancy Condition	Vacant at time of inspection

This report records visual observations made during a pre-signing inspection. The report is intended to support transaction review and does not replace specialist engineering or waterproofing tests.

2. Scope and Methodology

- Visual inspection only; no destructive opening of walls, ceilings, or pipe shafts.
- Functional spot checks were performed where safe and accessible.
- Findings are based on conditions visible on the inspection date.

Areas reviewed included the living room, bedrooms, bathrooms, kitchen, balcony, and accessible utility interfaces. Hidden defects may exist beyond the visible scope of this report.

3. Living Room Wall Condition

The living room wall surface showed a visible crack near the center-left section of the main wall. The crack was not measured destructively, but it is visually significant enough to merit further clarification before signing.

Observation note: crack pattern appears more than superficial paint crazing and should be checked against seller disclosures or maintenance history.

4. Door, Window, and Surface Review

- Main entry door and internal doors opened and closed normally during spot testing.
- Window locking hardware functioned with minor age-related stiffness.
- Surface wear in bedrooms and corridor is consistent with normal residential use.

No major glazing damage was observed in the accessible rooms during the inspection.

5. Plumbing and Utility Notes

- Drain and supply lines visible under accessible sink cabinets show age-related wear.
- Pipe condition appears older and replacement should be considered in the medium term.
- No pressure test was performed during this visit.

Recommendation: aging plumbing components should be reviewed by a qualified contractor before or shortly after handover if the transaction proceeds.

6. Kitchen and Service Areas

- Kitchen cabinets and worktop show ordinary wear.
- Ventilation fan was not tested under extended load.
- No visible gas modification was identified from the accessible inspection angle.

Utility and appliance functionality should still be confirmed during final handover.

7. Bathroom Fixture and Ventilation Check

- Basin, mirror cabinet, and towel hardware appear fixed in place.
- Exhaust ventilation was not tested under a long continuous cycle.
- Sealant around the wet-area edges shows ordinary age-related wear.

These fixture observations do not replace separate waterproofing or moisture-source confirmation.

8. Bathroom Moisture Review

Moisture-related staining was observed near the bathroom ceiling corner. The affected area suggests prior or intermittent water ingress and should be clarified before closing.

Observation note: staining pattern is visible enough to warrant seller-side explanation or repair history confirmation.

9. Bedroom and Storage Areas

- Bedroom flooring is generally level to the eye within accessible areas.
- Wardrobe interiors show ordinary use and no obvious structural failure.
- Storage corners were partially obstructed and not fully reviewed.

No major odor or severe visible mold was observed in the bedroom areas at the time of inspection.

10. Balcony and Exterior-Facing Elements

- Balcony drainage was visually checked but not water-tested.
- Exterior-facing window seals show ordinary aging and should be monitored seasonally.
- Railing stability appeared acceptable during light manual testing.

Weatherproofing performance cannot be fully confirmed without rainfall history or dedicated testing.

11. Overall Conclusion and Follow-Up

Overall condition is good. The unit appears serviceable for ordinary residential use based on this visual inspection, subject to routine maintenance and follow-up on items noted above.

No destructive testing was undertaken, and no engineering opinion is expressed beyond the visual scope of this report.

This conclusion should be read together with all page-level findings rather than as a substitute for them.

1. Clarify the visible living-room wall crack with seller-side maintenance or repair records.
2. Clarify the source and history of the bathroom ceiling water stain.
3. Consider contractor review of aging plumbing before or after possession transfer.

These observations may affect negotiation, disclosure review, or post-handover repair planning.

12. Inspector Sign-Off

Report prepared for transaction review only.

Inspector Signature: _____ Date: 2026-03-17

Reviewer Signature: _____ Date: 2026-03-17

End of inspection report.