DERATE PARAMETERS		
150.0	TimeDRStart	-Time for turbine to initiate derating
200.0	TimeDREnd	-Time for turbine to start returning to full rated
operation		
0.2	DerateFactor	-Ammount turbine will be derated (fraction of 1)
9999.9	TEmShutdown	-Time to initiate an emergency shutdown of the turbine
15.0	max0verspeed	-The maximum safe overspeed (%). An overspeed larger than
this will initiate an emergency shutdown.		

DEDVEE DVDVNEEDC