


CUSTOMER #: 400985

454864

VLAD KULCHYTSKY

INVOICE

TUCSON SUBARU



Confidence in Motion

4901 N. Oracle Road · Tucson, AZ 85704
(520) 721-2400 · Fax: (520) 620-9824
www.tucsonsubaru.comSERVICE DEPARTMENT HOURS
7:30 A.M. TO 6:00 P.M.
Monday - Friday

8:00 a.m. to 5:00 p.m. Saturday

PAGE 1

-8111

BUS:	CELL:	SERVICE ADVISOR:	1163 BRITTNEY OTTAVIANO			
COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	13	SUBARU Impreza	JF1GR8H6XDL834668		146990/146990	T9942
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
12MAR13	DD28DEC12	12MAR2016	17:00 22SEP26		214.00	CASH
R.O. OPENED	READY	OPTIONS: DLR:404637 ENG:2.5_Liter_Turbo				
16SEP26	22SEP26					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A THANK YOU SO MUCH FOR SERVICING AND TRUSTING US WITH YOUR VEHICLE
TODAY! I HOPE WE HAVE PROVIDED 10/10 RATED SERVICE FOR YOU, IF
WE HAVEN'T OR IF YOU HAVE ANY QUESTIONS/CONCERNS, PLEASE LET ME
KNOW AT 520-620-9859 :)

NOTE NOTE LINE ONLY

PARTS:	1586 ISP	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	(N/C)
								0.00

B PERFORM COMPLIMENTARY MULTI POINT VEHICLE INSPECTION, \$84.50 VALUE AT
NO CHARGE, INCLUDES BATTERY TEST AND COMPLETE VEHICLE VISUAL
INSPECTION

MPI PERFORM COMPLIMENTARY MULTI POINT VEHICLE
INSPECTION, \$84.50 VALUE AT NO CHARGE,
INCLUDES BATTERY TEST AND COMPLETE VEHICLE
VISUAL INSPECTION

PARTS:	1586 IMPI	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	(N/C)
								0.00

C TOW IN // GUEST STATES WHEN DRIVING THE ENGINE WATER TEMP GOES VERY
HIGH TO THE RED, VEHICLE NEVER REALLY OVERHEATS, GUEST JUST
PARKS AND LETS VEHICLE COOL DOWN, SOMETIMES GUEST CAN DRIVE FOR
HUNDREDS OF MILES WITH NO ISSUES, AND SOMETIMES IT RANDOMLY
STARTS OVERHEATING, PLEASE CHECK AND ADVISE

DIAG DIAGNOSIS

1586 CPS	535.00	535.00
1 45122FG003 SHROUD		133.88
1 45119SC090 RADIATOR		577.40
1 45137FE002 CAP AY RADIATOR		21.81
1 45161AG000 RADIATOR HOSE INLET		41.88
1 45161AG010 RADIATOR HOSE OUTLET		41.88
4 909170064 CLAMP HOSE D38.5		16.00
2 SOA906V9272 SUPER COOLANT 50/50 PREDI		65.00
PARTS:	897.85	LABOR: 535.00
		OTHER: 0.00
		TOTAL LINE C:
146990 REPLACED RADIATOR, HOSES, CLAMPS, AND BROKEN FAN SHROUD. DUE		1432.85


TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller, hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. Service provided and accepted satisfactorily.

X

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

TUCSON SUBARU



Confidence in Motion

 4901 N. Oracle Road · Tucson, AZ 85704
 (520) 721-2400 · Fax: (520) 620-9824
 www.tucsonsubaru.com

SERVICE DEPARTMENT HOURS

7:30 A.M. TO 6:00 P.M.

Monday - Friday

8:00 a.m. to 5:00 p.m. Saturday

454864

INVOICE

PAGE 2

COLOR		YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
		13	SUBARU Impreza	JF1GR8H6XDL834668		146990/146990	T9942
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
12MAR13	DD28DEC12	12MAR2016	17:00 22SEP26		214.00	CASH	22SEP26
R.O. OPENED		READY	OPTIONS: DLR:404637 ENG:2.5_Liter_Turbo				
16SEP26		22SEP26					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
TO AFTERMARKET PARTS WITH POOR FITMENT RESULTING IN A LACK OF COOLANT PRESSURE AND COOLING PERFORMANCE. VEHICLE NOW OPERATING AS DESIGNED AT THIS TIME.							

D TKA18 TAKATA AIRBAG RECALL

CAUSE: A182031 1.6

182031 PASSENGER SIDE AIR BAG MODULE INFLATOR

REPLACEMENT

1478 W

1 98279FG07B RC AIR BAG MODULE P KIT

(N/C)

(N/C)

FC: TKA18 PART#: COUNT:

CLAIM TYPE: RC

AUTH CODE:

 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00
 146990 PERFORMED AIRBAG RECALL TKA18 TAKATA AIRBAG. OLD-WJJ5P018558
 NEW-WJJTK01VTP

 E** DURING INSPECTION TECHNICIAN FOUND POWER STEERING PUMP ACTIVELY
 LEAKING POWER STEERING FLUID, REMOVE AND REPLACE
 STR STEERING CONCERN

1586 CPEX	278.20	278.20
1 34430FG040 POWER STEERING PUMP AY		714.45
1 34621AC024 GASKET		3.75
2 SOA635040 ATF HP		10.46
1 34611AG221 HOSE SUCT		50.50
2 909170063 HOSE CLAMP		9.24
PARTS: 788.40 LABOR: 278.20 OTHER: 0.00 TOTAL LINE E:		1066.60

146990

REMOVED AND REPLACED POWER STEERING PUMP, DUE TO LEAKING FLUID.

GOLD STANDARD AUTOMOTIVE COVERAGE AUTH # CL10996906LLB 8019634653

PAYMENTS@GOLDSTANDARDAUTOMOTIVE.COM \$1383.47 GUEST TO PAY DIFFERENCE //

WARRANTY COVERING \$290.39 FOR PUMP (INCLUDES MARK UP), WARRANTY NOT

COVERING REMAINING HOSES OR ATF

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller, hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. Service provided and accepted satisfactorily.

X


DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

TUCSON SUBARU

400985

454864

INVOICE



Confidence in Motion
4901 N. Oracle Road - Tucson, AZ 85704
(520) 721-2400 - Fax: (520) 620-9824
www.tucsonsubaru.com

SERVICE DEPARTMENT HOURS
7:30 A.M. TO 6:00 P.M.
Monday - Friday
8:00 a.m. to 5:00 p.m. Saturday

PAGE 3

SERVICE ADVISOR: 1163 BRITTNEY OTTAVIANO

US:	COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	13		SUBARU Impreza	JF1GR8H6XDL834668		146990/146990	T9942
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
12MAR13	DD28DEC12	12MAR2016	17:00 22SEP26		214.00	CASH	22SEP26
R.O. OPENED	READY	OPTIONS: DLR:404637 ENG:2.5_Liter_Turbo					
16SEP26	22SEP26						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

F** DURING INSPECTION TECHNICIAN FOUND REAR DIFFERENTIAL MOUNT LEAKING,
REMOVE AND REPLACE

DIFF DIFFERENTIAL CONCERN

1586 CPEX

214.00 214.00

1 41310AG040 DIFFERENTIAL MEMBER AY F

173.83

2 902330008 SELF LOCK NUT M12

8.40

PARTS: 182.23 LABOR: 214.00 OTHER: 0.00 TOTAL LINE F: 396.23

146990

REPLACED REAR DIFFERENTIAL FRONT MOUNT, DUE TO LEAKING HYDRAULIC
FLUID.

GOLD STANDARD AUTOMOTIVE COVERAGE AUTH # CL10996906LLB 8019634653

PAYMENTS@GOLDSTANDARDAUTOMOTIVE.COM \$1383.47 GUEST TO PAY DIFFERENCE

G** DURING REPAIRS TECHNICIAN FOUND LOWER CONDENSOR O RING LEAKING AC

REFRIGERANT, REMOVE AND REPLACE AC O RING & RECHARGE

AC AIR CONDITIONING CONCERN

1586 CPEX

363.80 363.80

1 73039TA030 PT211297 O-RING

2.00

1 SOA635015 REFRIGERANT R134A

25.00

PARTS: 27.00 LABOR: 363.80 OTHER: 0.00 TOTAL LINE G: 390.80

146990

REPLACE LOWER CONDENSER O-RING, DUE TO LEAKING REFRIGERANT ACTIVELY

GOLD STANDARD AUTOMOTIVE COVERAGE AUTH # CL10996906LLB 8019634653

PAYMENTS@GOLDSTANDARDAUTOMOTIVE.COM \$1383.47 GUEST TO PAY DIFFERENCE

H** CUSTOMER DECLINED THE FOLLOWING ITEMS AT THIS

TIME CUSTOMER INITIALS

CAUSE: CUSTOMER DECLINED THE FOLLOWING ITEMS AT THIS TIME:

DS CUSTOMER DECLINED THE FOLLOWING ITEMS AT THIS

TIME CUSTOMER INITIALS

1586 ISP

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE H: (N/C) 0.00

146990 LEFT AND RIGHT FRONT FENDER LINERS W/ CLIPS \$845.84

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller, hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. Service provided and accepted satisfactorily.

X

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	


CUSTOMER COPY

TUCSON SUBARU

400985

454864

INVOICE



Confidence in Motion

4901 N. Oracle Road · Tucson, AZ 85704
(520) 721-2400 · Fax: (520) 620-9824
www.tucsonsubaru.com

SERVICE DEPARTMENT HOURS

7:30 A.M. TO 6:00 P.M.

Monday - Friday

8:00 a.m. to 5:00 p.m. Saturday

PAGE 4

SERVICE ADVISOR: 1163 BRITTNEY OTTAVIANO

COLOR			YEAR		MAKE/MODEL		VIN		LICENSE		MILEAGE IN / OUT		TAG		
			13		SUBARU Impreza		JF1GR8H6XDL834668				146990/146990		T9942		
DEL. DATE		PROD. DATE		WARR. EXP.		PROMISED		PO NO.		RATE		PAYMENT		INV. DATE	
12MAR13		DD28DEC12		12MAR2016		17:00		22SEP26		214.00		CASH		22SEP26	
R.O. OPENED			READY			OPTIONS:		DLR:404637 ENG:2.5 Liter Turbo							

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

ESTIMATE: 0.00

18SEP26 09:39 SA: 1163

CONTACT:

Customer portion \$2,067.91

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller, hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. Service provided and accepted satisfactorily.

X

DESCRIPTION	TOTALS
LABOR AMOUNT	1391.00
PARTS AMOUNT	1895.48
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	3286.48
LESS INSURANCE	0.00
SALES TAX	164.90
PLEASE PAY THIS AMOUNT	3451.38

INSPECTION FORM


T9942
 TAG NUMBER
 454864
 R.O. NUMBER
 JF1GR8H6XDL834668
 VIN (LAST 8 DIGITS)
 09/16/2026
 DATE
 CUSTOMER SIGNATURE
 DATE

SUBARU
EXPRESS
SERVICE


- Checked and OK
- Requires further attention
- Requires immediate attention
- Not applicable

*Technician requires access to the glove box to check the cabin air filter (if applicable), and the trunk to check the spare tire.

INTERIOR/EXTERIOR CHECKUP



UNDER-HOOD CHECKUP




- ☐ Oil Change
- ☐ Synthetic
- ☐ Oil Filter
- ☐ Tire Rotation
- ☐ Bulbs
- ☐ Wiper Inserts
- ☐ Wiper Blades
- ☐ Other

SUBARU

- Checked and OK
- Requires further attention
- Requires immediate attention
- Not applicable

UNDER-VEHICLE CHECKUP



Tire Pressure**

Front Tire Pressure set to 35 PSI

Rear Tire Pressure set to 35 PSI

**Factory-recommended specifications.

Tread Depth Key

- 6/32" remaining
- 3/32" to 5/32" remaining
- Under 3/32" remaining

Brake Pad Thickness Key

- Over 5 mm
- 3 mm - 5 mm
- Less than 3 mm

Notes/Comments:

Recall Check:

Next Service Due: