

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

20 PK40318

NAME

Eulogio, Garry Boy Tagalog

FROM

PKIMT Management

SUBJECT

Notice for Suspension

No. of Offense

1st offense

DATE

January 14, 2021

This refers to the alleged offense(s) you have committed at

1/12/2021

to name:

Line/Shift

ACKNOWLEDGE BY

Eulogio, Garry Boy Tagalog

ACKNOWLEDGEMENT FORM

COMMENTS/ ASSESMENT

Violation Offense No.

OFFENSES AGAINST COMPANY INTEREST

Section No.

Absence from work for less than 3 consecutive working days

Description:

No good taping in assy process

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to mplement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

KIMT Management

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 20 PK40318

NAME

Eulogio, Garry Boy Tagalog Cuf-

FROM

: PKIMT Management

SUBJECT

: Notice to explain

No. of Offense

: 1st offense

DATE

14-Jan-21

This refers to the alleged offense(s) you have committed at

12-Jan-21

to name: Eulogio, Garry Boy Tagalog

Violation Offense | V

OFFENSES AGAINST COMPANY INTEREST

Section No.

14

Absence from work for less than 3 consecutive working days

Description

No good taping in Assy process

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

Conforme:

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

To whom it may concern,

Good Day!

This is to request disciplinary action for employee, Garryboy Eulogio, PKIMT employee, for not following Standard Operation Procedure. This resulted to MAJOR QUALITY PROBLEM with outflow already and need to request pullout of FG and conduct special repairing of affected harness

See attached for the detailed investigation report and written explanation of the concern employee

For your immediate action

Thank you

Prepared by:

Hazelyn Dimayuga

Assistant Manager/ PD1-Section 2

Noted by:

Rochelle Odevilas

Section Manager/ PD1-Section 2

Kirdly 1884 DA immediately.

INVESTIGATION RESULT	YA-106-GR								***************************************																			OA Denartment	Confirmed by: Velocities by:	EFF: 08/01/13
FURUKAWA AUTOMOTIVE SYSTEMS LIMA PHILIPPINES, INC.	taping of clamp Y		Affected: 463 sets NG out of 800 sets		705			9N		_ to Z.5 rounds				ed clamp YA-106-GR it shour: be 4-5 rounds taping on	Associate do one under on affected clamp then Zrounds taping on both side of clamp. As per interview to associate he did not used the andon light when he encountered delay on the process.	s on clamp to avoid delaymer knowing that he produce		YA-106-GR to check the presence of fixing on both side	e of clamp	of clamp,one under of clamp,markings for the counter				on quality. the importance of		025 F. W. O		Table free Table		
	Problem: Insuficient to		Details Affected: 463 set:					3000		4 to 5 rounds	Investigation:	Root cause:	 2 clamp YA-106-GR are affected on the harness. No changing point. 	 Associate did not follow the SOP during toping of affected clamp YA-106-GR it shound be 4-5 rounds toping on both side of clamp 	Associate do one under on affected clamp then 2rounds As per interview to associate he did not used the andon	instead associate lessen the number of rounds of taping	worse type of defect.	Leakcause: On Dimension process, put markings on affected clamp YA-106-GR to check the presence of fixing on both side		 On Appearance inspector she only check the presence of clamp, one under of clamp, markings for the counter measure of previous CLAIM missing fixing. 			ACTION TAKEN:	Re-orient associate regarding possible causes and outflow on quality. Penalty will be given to the associate. Remind all member the importance of	t on the process .	Cherrye powers of ass			Verkelation of Elicensiness: (b 8 trantins after operalimments professinistical)	HCC-003B-01
Approved by: Onecked by: Issued by:	TO COUNTY OF THE PROPERTY OF T							Insuficient taping of clamp			Assy Sub- F/S assa/Layout process	X N/A				REMARKS					-	Leakcause				EFF. DATE	EFF. DATE		PRODUCTION DATE:	EFF: 08/01/13
	0	1000	90-200		1	pui					T DIMENSION	×	"X" -defect may occur/ leak			YES NO	0	0		0						IEASURE:	EASURE:			
rstems	ON REPORT Date Prepared: 08-20-2020		Car Model: J72A/K 190-200	Lot No:		Containment Action and Product Disposition	SCRAP	SORT:			CLAMP CHECK ECT	×	"X" -defect			A.										OCCURRENCE COUNTERMEASURE:	LEARCAUSE COUNTERMEASURE:		Ċ	
JTCIMOTIVE SI	INVESTIGATION REPORT Date Prepared: 08-										Option	×	occur/leak	320				권? nension/ ECT/ A				41				חססס	LEAN		PRODUCT NO:	
FURUKAWA AUTCIMOTIVE SYSTEMS LIMA PHILIPPINES, INC.	INVEST		Mazda Merge		usct check:		PITED				Арр	0	-befect will not occur/leak	mvestigation:			ovepair?	4.2 Does it have any mirror defect record? 4.3 Undergo all Inspection process (Dimension/ ECT/ Appearance*		cranger		Occurrence								
W		mation.			al defect prop	essment:	CLAIM NOT ACCEPTED	arks:	stigation:	3.1 Process Mapping	OA Inspection	N/A	0"	3.2 Result of process myestigation			4.1 Did harness undergovepair?	it have any min	e)3	4.4 is there any besign cranger 4.5 Have changing point an 4M?	5. Summary of investigation					asure:			7. Implementation let/ dave	1
1		1 Product Information	Customer:	Part No:	2.Result of actual defect product check:	Defect Assessme		Assessment Remarks:	3. Process Investigation:	3.1 Proc	Process Name:	Investigation	Legend:	3.2 Resu	4. Product History:	L	4.1 Did h	4.2 Does	Assurance)?	4.4 Is th	5. Summary o					6. Countermeasure:			7. Implemer	3.) HCC- 003A-01

MAZDA

WRITTEN EXPLANATION

NAME: Culary, yearny boy EMPLOYEE NO: DAPK 469 YE

DATE: 01-12-21 1110

FAS

AGENCY: PKIN

VIOLATION: Produce Maissive defect (Insufficient Taping on Both Side of clamp)

LINE

parimanhun rup po and hurdi be pagarned sa excensional stapping of claim papageted so mga aroso nayon and aming live ay buyang no bulang Tam so altered ng tao. At linabawangan naming matorget and gos hangarg pag mamadali hindi tuna po pagawang pindatin ang ardon upang and plan namuh ngunus per garren partoan pala hunti le namamatayang nas no good no ong alting quagawa.

card po all uniford managoder and alling paparlinenting maraning payamed ps.

OFFENSE:

Kollowin

DATE: 1/14/2021

WRITTEN EXPLANATION:

Ato po ei Garry by Gulogio. By humbig og paumanhin patrobahilangng pa sawrang pagmamadali ko po ay hirdi kuna na check ong oting quagawa kung kaya nagkaroon ng Na ang alking gurawa, Isa painto ay kunakaulargan naming makatarget sa ganap na Mam 800 Lungkaya ay maominadali ko ang aking gawain. sand no ay myong manapatin and acting pawmantin mananing salamad po.

Countermeasure:

aking paghoubuthin any away trobaho at akin po itong thack upang mauudoan ang pagkakamali

enlogio.

Signature over Printed Name / Line