

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 17 PK18250

NAME

Aclan, Giselle Panganiban

FROM

: PKIMT Management

SUBJECT

: Notice for Suspension

No. of Offense

1st offense

DATE

October 21, 2019

COMMENTS/ASSESMENT

No. Offense: Uf land

Nov. of land

Line STOU/A

ACKNOWLEDGE BY:

MANAGER

Signature Over Printed name/ Date

ACKNOWLEDGEMENT FORM

This refers to the alleged offense(s) you have committed at

9/19/2019

to name:

PKIMT

Aclan, Giselle Panganiban

Violation Offense No.

V

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Conforme:

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 17_PK18250

NAME

Aclan, Giselle Panganiban

FROM

: PKIMT Management

SUBJECT

: Notice to explain

No. of Offense

: 1st offense

DATE

18-Oct-19

This refers to the alleged offense(s) you have committed at

19-Sep-19

to name: Aclan, Giselle Panganiban

Violation Offense | V

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description

Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED DY:

PKIMT Management

17 BV1838

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

I ALERT WRITTEN EXPLANATION

FAS		Control No: FALP-1A -	1909-1342
Please Specify: PKIMT	,	Audited By: Note	agadia ed By:
Name: Aclan, Girelle Position: Associate ID Number: 17-PK/8250 Batch No.: 181 Car Model/Line: Suzuki / Sloy Audit Findings: Non-compliance or failure	Process: Group/Shift: Date/ Time: No. of Offense: Superior Name:	Appearance A IDS D9-19-19 /2:SSPM Int A. AGWIN and operational procedure in	inspecting the
Inspector did not compare actual har Inspector did not conduct inspection Inspector did not follow proper was	ness to master based on veg	Sample uence	
WRITTEN	N EXPLANATION		
Tungkel po sei companing ng Actual po kasi. Pinagtatapat ang Ang actual se at Nag co concluct po ako ng Point to ako na Hindi na ako nag Po-pant, sa parihas kong Hawak ang actual hantes a	naster Sample Point System : A portion pu kasing	na cucompare ku naman p AT May mga Portion na	0.00
	aku sa <u>connector</u> Hindi nga land	ng ayos sa ganun paraai - Jahat naman po ng 3. pp nasisina consistent	Companent,
po sa pag unspect ng pruduct:	aking pag inst	pect: Magiging Standara	1 00
Remark	ks/ Evaluation:		New State of the Control
Print to point is the coop			
Issue 1	Penalty		
Signature of Employee Date: 1-28-19 Date: 9-38-19 Date:	MAV E Su Daff Su 9/28/19 Date:	pervisor Manager 9/28/21	

Final Assembly Assurance/Appearance Inspection Process

Master Sample, Registered Ballpen, Daily Checksheets

ALL

Measuring Tapes; FGI-D07 Master Sample Dally impaction

Н

Quality Assurance Inspection Board; IRCS; Passtape Supplying Machine

Final Assembly Process COACOS Final Assembly Process Internal Defect Medicing CLA-COZ Final Assembly Process Inspection Record;
COACOS Final Assembly Process Internal Defect Medicing CLA-COZ Apparament Assumes Leading Sets Monitoring Form, MEI. To Serve 35 instruction for 50551 July Cheek Record for Dimension, Apparament, Assumance Inspection Process Teach (1998) 2019 July Inspection Records
OLIGINAL Process Internal Process Internation Record Post Clinic Internation I

FALP-OP-012, FALP-GL-QCA-LS-143, FALP-GL-FGI-16003, FALP-WI-QCA-15007 ZZK-025-E

Section Manager Assistant Manager Supervisor FALP-OP-003, FALP-OP-008,

Department Manager

1 OF Feb-23-2019

WORK INSTRUCTION

FALP-WI-QCA-15005



the harness for inspection. 3. Get the co

2. Lay out the wire harness into the Inspection Board and barcode the

Note 1: Must layout one (1) harness at a time.

Note 2: For those products without nam

Note 3: Inspector must update the prod actual product number running on insp

plate, barcoding are not

nt inspection

Note 4: In case of Jacking set, finished

before starting lacking harness to avo

on every nameplate if it is the same as the Note 1: Check the tag code indicate tag code indicate tag code indicated in the polycard.

Note 2: Inspector must get the issued polycard one at a time and only one polycard for the running product must be present on inspection area.

1. For preparation, conduct \$\frac{15}{2}\$ in inspection area and check the condition of inspection board and master sample base on the ME-055F1 Daily Check Record for Dimension, Appearance, Assurance

Inspection Board and FGI-007 straster Sample Daily Inspection Record.

1.1 Check also the condition of tools and materials using forms of MEI-069F1 Daily Inspection Record of Measuring Tapes and QCA-023 Appearance/ Assurance Dally Checksheet of Tools and Materials. 1.2 After filling-out all daily inspection records, perform checking of lacking harness left by the previous shift, if there are lacking sets never to FALP-GL-QCA-LS-143 Proper Treatment on Lacking Farness and if there is no lacking harness, log in to IRCS using own QR code.

1.3 Get the harness from the langer/polytainer and fill out the product information into the QCA-007 Final Assembly Process Inspection Record (if applicable). NOTE 1: In case line has no remeter sample or the master sample was in no good condition, inspector will use Daily Sample provided by OA/PD Jr. Staff, Staff. Daily Sample Card must be attached on the daily sample harness. Refer to FALP-GL-FGI-16003 Control of Master Sample NOTE 2: Product number of deligg sample to be used must always be the same of the product number of the actual harness for inspection. 4.1 Inspection flow/procedure for product which are required to barcode the polycard in polybox.

4.1.1

4.1.2



4.1.3 Push the button for pass tape and attach to the harness

4.1.4 Mark the pass tape using register ballpen as

ndication that the harness pass the Assurance

/Appearance Inspection.



4.1.4

A Assurance Inspection (MAZDA) Characteristics:

the operation/inspection, CALL the actention of Staff/Jr. Staff and WAIT for further instruction. Refer to FALP-WI-QCA-15007 Final Note: In case inspector found NG or abnormality, STOP

and Preventive Action for encountered problem/ abnormality during

of inspection. Rever to FALP-OP-008 Quality Assurance Preparation Product and FALP-OP-003 Control of Nonconformities, Corrective

for New Product, FALP-OP-012 Mon/toring and Measurement of

NO SOLD

1 36550-1980 D

there is no dirt or marking on it. (refer in Good and No good polycard holder. Ensure that Note 3: Check the plastic Ol nO: ZZZK-025-E

ENG-001-03

Note 1. Write also all the required masking [ex. marking for extromer blam audit claim] in polycard before setting to polycard holder (finipplicable).

Note 2. For harness that will undergo first Good inspection refer to

4.1.1 Sign the polycard as indication of person who part set/put the polycard in polycard holder of the polybox

	WORK INSTRUCTION FAGENOS 1 OF 1 REVISIONINGS 3 May-08-2019	PROVAL Verified by: Approved by:	B. Famirez A. Nachor / T. Maruoka Asst. Manager Sec. Manager	into or u er M to	MO GOOD candition on proper way of checking connector. 1. WARNING In case of Abnormalities, please 1. Stop the Production or Process 2. Call the attention of Jr. Staff / staff 3. Wait for further advise Staff / staff Wear proper PPE, (Refer to FALP-GL-ESH-18006 Personal Protective Equipment (PPE) for the applicable PPE Be careful not to cause injury during inspection of Wireharmess
	DOCUMENTTYPE: WORK! DOCUMENTING! REVI	Checked by: Verified E	S, Morfe Supervisor	The state of the s	(4) (5) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4
		Prepared by:	CA-17074 (CA-15015 SH-18006 L, Mindanao Stoff	Check to dolde of connector 1. No den age part (all edges must check) 2. No fore ar mateur attended 3. No excess burn 4. No hell cocked retement	74 Inspection Criteria for Damaged he accentable damage condition). O). Sen (applicable for water proof sing the insertion part of connector it of connector.
	IG CONNECT	ONBERGEN	FALP-CP-QCA-17074 FALP-WI-QCA-15015 FALP-GL-ESH-18006	S S S	- Check the Insertion part of connector 1. No timisped cavity (refer to FALP-OP-OCA-17074. Inspection Criteria for Damaged on Insertion Part of all Common Connectors, for the accentable damage condition) 3. Condition of Inserted wire in pulling out on TBO). 4. Presence and condition of gomusen and tsumesen (applicable for water proof connector). 8. Bending portion must be <u>50min</u> away from neck of connector b. Avoid too much banding of branch. Datails of connector.
	NAY OF CHECKII	Alignment jig		Check front side of connector based on connector lock position (unless otherwise specified) Mowong part all edges must chec. Mod of manage part all edges must chec. Mo oscess burn Mo oscess burn	
	PROPER WAY OF		PURPOSE To set instruction on how to check the condition of connector properly	al posiconi CAUTION: Do not insert your finger inside the consector matting part during inspection! and forzoneal position. Therety gi	C-leck left side of connector Codomage part (all edges must cheek Codomage part (all edges must cheek Codomage part (all edges must cheek Codomage part of connector A bo deform part of connector
	VESYSTEMS	N/A	To set instruction on of connector properly	Check the mating part of certactor No forminal backing out (in "-check in vertical and horizontal position) No foreign matter affached No excess burn Presence of red mark (forma is connectors that has alignment, g) Presence of red mark (forma is connectors that has alignment, g) Presence and condition of packet in tubbles seal (applicable for water	STEGGRAVITY DETE
and the second s	FURUKAWA AUTOL-OTIVE SYSTEMS UMA PHIUPPINES, INC. CAR MODEI	All	FORMS N/A	Check the mating part of cornector 3. No cames pearfeld edges - rat check, in vertical and horizontal position 3. No cames pearfeld edges - rat check). 3. No cames burrt 4. No excess burrt 6. No cames burrt 7. No excess burrt 8. No excess burrt 8. No excess burrt 8. No excess burrt 9. Presence of red mark (for - rate connectors that has alignment it is proposition). 7. No excess planting of termina sold/fur) 8. Presence of red mark (for - rate connectors that has alignment it is). 9. Presence and condition of rate of the rate of the proof connectors.	Otheck right side of connector 1. No damage part (all edges must check) 2. No foreign matter attached 3. No excess burr 4. No deform part of connector Payou No. Payou No.

3

Align sequence of checking to current process (sequence no. 2,34,82); changes of picture Item no. 6; additional instruction and note on sequence no. 13,4,5,86); Remove check item for (color/size/type of wire) already checked item of sub assy operator using Sub PC, Remove checkin of deform insulation barrel and bend-up/down terminal (checked item of initial process) (sequence no. 6); Additional check item [Presence and condition of gomusen and trumesen) and additional note if prope bending of branch during checking of connector (sequence no. 6); additional reference

Upcate the sequence number of Pacess, additional comment for sequence No. 1 First Issue per ISO 9001:2008 Quality Management System

Oct-21-2016 Jul-25-2015

A3a-1610-007

Jul-24-2017

QA-QCA-L3a-1707-001