

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

## MEMORANDUM NO. HRADM

TO

: 19 PK30719

NAME

Bufi, Juliet Laylo / Youp

**FROM** 

PKIMT Management

SUBJECT

: Notice for Suspension

No. of Offense

: 1st Offense

DATE

November 10, 2020

This refers to the alleged offense(s) you have committed at

10/9/2020

to name:

Line/Shift

ACKNOWLEDGE BY:

Bufi, Juliet Laylo

ACKNOWLEDGEMENT FORM

COMMENTS/ ASSESMENT

Violation Offense No.

10

OFFENSES AGAINST COMPANY INTEREST

Section No.

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

## **Description:**

## Not following SOP in Lay-out - Non compliance on insert pull method

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

10 PK2071

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

## I-ALERT WRITTEN EXPLANATION

FAS				Control No: FALP-14-2010-4185		
AGENCY	IF. PKIMT		J. Maracayon	K. Hernandez	J.Reyes	
Please Specify: PKINT		Audited By:	Checked by:	Noted By:		
Name:	Butit, Juliet	Process:	Layout			
	tasociate	Group/Shift:	DC/B	Non-compl	iance Reference/Document	
	9PK30719	Date/ Time:	oct 09,2020 / 09:20		Control Number:	
	954	No. of Offense:	1et		was Hon Compliana	
Car Model/Line: 2	aihatapozL / 2111	Superior Name:		QA -2010-	0)	
Details of Audit Findings: Non compliance on Invert-Pull Method  Associate did not conduct pulling of win after invertion on layout process. Connector: 456   TKN2-14F						
Acrociate did not conduct pulling of wire after invertion on layout process. Connector: 456/76N2-14F						
WRITTEN EXPLANATION wire colors GI WI, VII, GRI and WIG.						
Good Day! Grefy First						
the po i lillet Buti ay ha-audit sou conn. YCK-TONY 4-267-19 soa kadah laran peng hindi ple						
ato natagog pulling dalad po ako po ayo modalayout at requirert ng ct.5 at ct. 4 kari po axy nata porton as						
isa Ct. 5 ay nasa Ct. 2 sa pagmamadali lio po hindi lo na po nasuno d ura segvence kari po madede kuy						
10 ale						
COUNTER MEAGURE: Andi na po mavulit at cucundin ko na po ang incert Push PvI) ca lahat ng						
Trure ha aking itincect at mag-aandon na lamang po also pag also						
94 nadedelay upany majurasan ha din po any T.B.O o Terminal						
Bayling Out.						
REMARKS/ EVALUATION						
i-Alert written only Agency/FALP Written Only(based on handbook)						
Need day/s suspension(based from handbook & Memo for Major Non-compliance).						
., , , ,		non my	(a)		IAA	
jeuh		H-HMJUELLES	UNERES	Of A		
Employee Date:	13-90 Date:	TStaff 13 - 20	Staff Date: 613/2010	Supervisor Date: 9 4	Manager Date:	
/ /						