

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

### MEMORANDUM NO. HRADM

TO

: 18 PK27257

NAME

Velasquez, Roselyn Asi hartlesque by

FROM

SUBJECT

: PKIMT Management

: Notice for Suspension

No. of Offense

2nd Offense

DATE

October 22, 2019

ACKNOWLEDGE BY:

MANAGER

ACKNOWLEDGE BY:

ACKNOWLEDGEMENT FORM
COMMENTS/ ASSESMENT

2rd - 2 days Supersion Nov. 8+9> 9211 Curemus CC7 7101 - 121 A

This refers to the alleged offense(s) you have committed at

9/25/2019

to name:

PKIMT

No. Offense:

Velasquez, Roselyn Asi

Violation Offense No.

V

## OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

#### Description:

Not Follow SOP - Failure to follow the standard operational procedure in Inspecting the Product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

**PKIMT Management** 

Conforme:

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

# I ALERT WRITTEN EXPLANATION

Process: Group/Shift: Date/ Time: No. of Offense: Superior Name: to follow the vian	idard operational p	
Group/Shift: Date/Time: No. of Offense: Superior Name: to follow the vian	Appearance A   NS 09-25-19   07:25 124 Old  J. Afienza  Idard operational p	Noted By:
Group/Shift: Date/Time: No. of Offense: Superior Name: to follow the vian	Appearance A   NS 09-25-19   07:25 124 Old  J. Afienza  Idard operational p	AM
Group/Shift: Date/Time: No. of Offense: Superior Name: to follow the vian	A   NS 09-25-19   107: 25 124	
Date/Time: No. of Offense: Superior Name: to follow the vian	1.4 old V. Afrienza Idard operational p	
No. of Offense: Superior Name: to follow the vitan y of Checking	1.4 old V. Afrienza Idard operational p	
to follow the vian	J. Afienza adard operational p	recodure in inspecting
to follow the vian	idard operational p	rocodure in inspecting
y of checking		
	Collector	
EVDI ANATION		
LAI LAIVATIO	V	
na fula	Ina labe MDI	ay namanata
o≠ checkina	connector. Hindi	na oo man-
ya na po	kayo .	,
	Company of the Compan	
	of checking.	ng Subaru line 7/01  of checking connector thad you no po kayo.

Signature of Employee
Date:

Juin Itims
Jr Staff
Date: 9-27-1

Staff of Ya

Supervisok Date:

Manager Date: 9/31



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines

Tel No.: (043) 405 6388-89 / (043) 405 6407-08

### MEMORANDUM NO. HRADM

TO

: 18 PK27257

NAME

Velasquez, Roselyn Asi pravlaugmen

**FROM** 

**PKIMT Management** 

**SUBJECT** 

: Notice to explain

No. of Offense

: 2nd Offense

DATE

22-Oct-19

This refers to the alleged offense(s) you have committed at

25-Sep-19

to name: Velasquez, Roselyn Asi

Violation Offense I V

## OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description

Not Follow SOP - Failure to follow the standard operational procedure in Inspecting the Product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

navelaconely 18\_PK27257

NOTED BY:

**PKIMT Management** 

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

				A CONTRACTOR OF THE PARTY OF TH	Calveryor Constitution of the		f
FURUKAWA AUTOMCTIVE SYSTEMS			1	DOCUM	DOCUMENT INFE	WORK INSTRUCTION	PAGENO: 1 OF 1
LIMA PHILIPPINES, INC.	アドロアドド シタ	VAY OF CHECKING CONNECTOR	¥5	DOCUR	DOCUMENT NO.:	REVISION NO.	EFFECTIVITY DATE:
The second second second				FALP-WI-	FALP-WI-QCA-15008	3	May-08-2019
CARMODEL	MALERIALS MAN CONTROL OF THE PARTY OF THE PA	DEVICES / EQUIPMENT USED: FILE OF	REFERENCE			APPROVAL	THE RESIDENCE OF THE PARTY OF T
II A	N. Y.			Prepared by:	Checked by:	Verified by:	Approved by:
		Alignment Jig	2000 000				
FORMS	PURPOSETR	SCOPE	FALP-WI-QCA-15015				
N/A	To set instruction on how to check the condition	Firs Accord Vibraces	FALP-GL-ESH-18006	L. Mindanao	S. Morfe	B. Ramirez	A, Nachor / T. Maruoka
	of connector properly	TITE OF THE PROPERTY AND A SECOND SEC		Staff	Supervisor	Asst. Manager	Sec. Manager / Dept. Manager



· Check frontside of connector based on connector lock position (unless otherw

> 2. No damage part (all edges must check). 3. No foreign matter attached · Check the mating part of connector

4



NQTE 1: Slightly touch the retainer using thumb finger from left to right, and right to left to be checked if the FALP-WI-QCA-15015 Proper Method on Pressing and Checking of Retainer lock retainer is already locked or unlocked refer to

NOTE 2: TBO can be detected if encountered half

locked/imperfect locked of retainer,

NOTE 3: These applies to all connectors except special connectors where in retainer and connector lock are situated on different location,



NO GOOD condition on proper way of checking


WARNING

2. Call the attention of Jr. Staff / staff 1. Stop the Production or Process 1) In case of Abnormalities, Please

3. Wait for further advise (2) Wear proper PPE. (Refer to FALP-GL-ESH-18006 Personal Protective Equipment (PPE) for the applicable PPE

(3) Be careful not to cause injury during inspection of

Align sequence of checking to current process (sequence no. 2,3,4,8.5); changes on parture item no. 6, additional instruction and note on sequence no. 1,3,4,5,6,6); Remove checking of deform insulation barrel and bend-up/down terminal (checked item of initial process) (sequence no. 6); Additional check item (Presence and condition of gomusen and tsumasen) and additional note for prope by noting of branch during checking of connector (sequence no. 6); additional reference -GL-ESH-18006), Be careful not to cause injury during inspection and packing of wire al Protective Equipment (Refer to EAL) te n No. 8 Update the sequence number of Process, additional comment for sequence No. 1 Additional warning information regarding safety purposes (Wear Proper PPE Perso First Issue per ISO 9001:2008 Quality Management System Oct-21-2016 Jul-25-2015 May-08-2019 Jul-24-2017 QA-QCA-L3a-1905-015 QA-QCA-L3a-1707-001 A3a-1610-007 A3a-1507-022









Vo damage part (all edges mi No foreign matter attached

1. No damage part (all edges must che

· Check right side of connector 2. No foreign matter attached



No damaged cavity (refer to FALP-CP-QCA-17074 Inspect on Orienta for Damaged in Insection Part of all Common Connectors, for the acceptable damage condition). Presence and condition of gomusen and tsumesen (app. Condition of inserted wire (no pulling out or TBO). No damaged insulation/exposed core wire

NOTE: Proper way of bending branch when checking the inscription part of connector.

Bending portion must be 50mm away from neck of cornector.

Avoid too much bending of branch:

