SERVICE REPORT PREVENTIVE MAINTENANCE

FORM NO.

		PREC	ISION A		NDITIO	NING (P	PAC)			
		P	T. HM SA LANT			,	110)		Tipe Form PM04	
Lok	asi : LT3	Model Unit:	Team Engineer List: tes			es	Date :			
								2024- 08-03		
Coc	le unit : 12	No. Seri }: 12			1			Start PM : 0	06:10	
Nor	nor Unit : 83						Close PM: 08:10			
CH	ECKLIST TEAM BRIE	FING			-					
INTENSIVE SAFETY BRIE						?	OK	?	NOT OK	
	AM Filter Section									
Λ	Item Checked	Spec. Range / Cond. Std.	Actual	Checked	Item (Checked	Spec. Range	Ac	tual Checked	
	1. Check/Replace filters	Clean or Dirty	Clean	,	5. Clean co		Clean or Dirty	Clean		
	2. Grille area unrestricted	OK / Not OK	Ok		· · ·		Clean or Dirty	r Clean		
	3. Wipe section clean	Clean or Dirty			7. Check/Test filter-		Ok or No	Ok		
D	4. Coil clean Blower Section	Clean or Dirty	Clean		clog switcl	n operation				
Б		Spec. Range /	Blov	wer 1	Blo	wer 2	Blo	ower 3		
	Item Checked	Cond. Std.	Before	After	Before	After	Before	After	Keterangan	
	1. Mounting bolts tight	Ok or No	OK	OK	OK	OK	OK	OK	OK OK	
	2. Fan-guard bolts tight 3. Impeller spins freely	Ok or No Ok or No	OK OK	OK OK	OK OK	OK OK	OK OK	OK OK	OK OK	
l	4. Check/Test air sail		OK	OK	OK	OK	OK	OK	OK	
	switch	Ok or No								
	5. Motor amp draw	FLA L1 =···· A	L1	L1	L1	L1	L1	L1	1	
	Compare to nameplate amps	FLA L2 =···· A	L2	L2	L2	L2	L2	L2	1	
		FLA L3 =···· A	L3	L3	L3	L3	L3	L3	1	
	6. Check belt tension and condition	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
C	7. Check sheave/pulley	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
	Reheat	Spec. Range /	Heater 1		Heater 2		Hea	ater 3		
	Item Checked	Cond. Std.	Before	After	Before	After	Before	After	Keterangan	
	1. Reheat amp draw	FLA =····· A	1	1	1	1	1	1	1	
	2. Check Heater Resistance	18-22 ohm	1	1	1	1	1	1	1	
	3. Inspect elements	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
	4. Check wire connections	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
D	Steam Generating Hum	idifier								
	Item Checked	Spec. Range	Actual Checked		Item Checked			Spec. Range	Actual Checked	
	1. Humidifier amp draw 2. Check drain valve/drain lines/trap fordamage/clogs/leaks 3. Check water fill valve and all supply lines/connection for leaks		1		4. Check of hose	condition of	steam	Ok or No	Clean	
			Ok		5. Clean st	rainer		Ok or No	Clean	
			Clean	lean		6. Check humidifier bottle (Boiler tank)			Clean	
L					7. Check o	peration of	humidifier	Ok or No	Ok	
E	Electrical Panel		Actual Checked							
	Item Checked	Spec. Range / Cond. Std.		Before	Actual	Спескей	After		Keterangan	
	1. Check fuses	Ok or No	Ok			Ok			Ok	

2. Check contactors for

pitting (Replace if pitted)

Ok

Ok or No

Ok

Ok

2. Check Ok or No	Ok	Ok	Ok
Check Contactors			
for			
pitting (Replace			
(Replace			
pitted)			

Electrical Panel								
Item Checked	Spec. Range / Cond. Std.	Actual Checked						Keterangan
	Conu. Stu.		Before	CHC	l	After		
4. Voltage Line to Neutral Ground	220 + 10%	L1/L2/L3 =1		V	L1/L2/L3 =1		V	1
5. Voltage Line to Line	380 + 10%	L1L2/L2L3/L V	1L3 = 1		L1L2/L2L3/L V	1L3 =1		1
6. Frequency	50 + 10%	F =1		Hz	F=1		Hz	1
Controls Item Checked	Spec. Range / Cond. Std.	Actual	Checked	3. Check/Test water-detectiondevice 4. Check/Test CAN connection between indoor and outdoor units			Spec. Range	Actual Checked
1. Check/Verify control operation	Ok or No	Ok					Ok or No	Ok
2. Check/Test changeover device	Ok or No	Ok					Ok or No	Ok
Refrigeration Piping							q	
Item Checked	Spec. Range	Actual	Checked	Item Checked			Spec. Range	Actual Checked
1. Check refrigerant lines (clamps secure/no rubbing/no leaks)	Ok or No	Ok		3. Check for restriction temperature drop across filter drier			Ok or No	Clean
2. Check for moisture (sight glass)	Ok or No	Ok						
Compressor Section								
Item Checked	Spec. Range /						np. 3	Keterangan
1. Ampere draw	OA··· A	Before	After 1	Before	After 1	Before	After	1
2. Check oil level	55 - 90 PsiG	1	1	1	1	1	1	1
3. Check for oil leaks	200 - 300 PsiG	1	1	1	1	1	1	1
4. Check compressormounts (springs/bushings)	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok
5. Cap tubes (not rubbing)	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok
6. Check/Re-torque wireconnections (inside compressor box)	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok
7. Compressor operation (vibration/noise)	Hz dB	1	1	1	1	1	1	1
8. Check crank-case heater fuses/operation	Ok or No	Ok	Ok	Ok	Ok			Ok
9. Check for refrigerantleaks	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok
10. Suction pressure Circuit	55 - 90 PsiG	1	1	1	1	1	1	1
11. Discharge PressureCircuit	200 - 300 PsiG	1	1	1	11	1	1	1
12. Superheat Circuit	?C		1	1	1	1	1	1
13. Low-pressure switchcut out Circuit	Ok or No	Ok	Ok	Ok	Ok			Ok
14. Low pressure cut in Circuit	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok

	Circuit	Ok or No									
	16. Sight Glass	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok		
			O.K	lon.	o.c	- Jose	- Car	<u> </u>	jon –		
	~ - ~ -										
П	Condensor Section		a	-		D 0		0.			
	Item Charles I		Spo	ec. Range		Before A		fter	Keterangan		
	Checked				Class	CI					
	1. Coil clean of debris (Cle ifrequired)	Clea	an or Dirty	Clean		Clean					
_	2. Fans free of debris		Clean or Dirty		Clean		Clean				
	3. Fans securely mounted		1	an or Dirty	1		1				
	4. Motor bearings in good	condition	1		1		1				
	5. Check all refrigerant lin		1		Ok	Ok		Ok			
	vibration	101	Ok or No		OK	OK .					
	isolation. Support as nece	ssary									
	6. Check for refrigerant le		С	k or No	Ok		Ok				
	7. Check surge-protection		Ok			Ok					
L	(ifinstalled) status-indicat	tor lights	Ok or No								
	8. Check/Re-torque wire o	connections	C	k or No	Ok		Ok				
	9. Check contactors for pi	tting (replace		N. a., N	Ok	Ok Ok					
	ifpitted)		C	k or No							
	10. Verify operation seque	ence/set points	1		1		1				
	11. Charge verification:		1		1		1				
	a. Outdoor Ambient Tem	perature	1		1	1 1					
	b. Subcooling		1		1						
	c. Indoor-unit Return-air		1		1						
	d. Sight-glass level (if Lee-Temp		1				1				
_	orpumped refrigerant)			L1/L2/L3 = L1/L			.2/L3 =				
	12. Motor amp draw		FL	A = 1 A	L.			Amp			
	General Function					TTIMP		Шр			
J								Spec.			
	Item Checked	Spec. Range		Actual		Item Checked		Range	Actual		
	1 G 11 m :		-	hecked	4.5.				Checked		
_	1. Cooling Test	Ok or No	Ok			4. Dehumidification Test		Ok or No			
	2. Heating Test	Ok or No	Ok		5. Alar	m Test		Ok or No	Ok		
172	3. Humidification Test	Ok or No	Ok								
K	Room Condition							Spec.			
	Item Checked	Spec. Range		Actual		Item Check	ked	Range	Actual		
			C	Checked				Ŭ	Checked		
	1. Temperature	1 C	1			2. Humidity		1 %	1		
T	,			NO	TES						
Ter	nuan : tes										
Rekomendasi : tes RESUME											
				RES	UME						
	JOB COMPLETED	Yes	NO, plea	ase check on	NOTES		RUNNING	G HOURS:			
	?										
				APPR	OVAL						
	SIGNING										
	Approved by		Verified By Service By					Service By			
	ISS,			Supervisor, Team Leader/Staf,				m Leader/Staf,			

Ok

Ok

Ok

Ok or No

15. High pressure cut out

Ok

Ok

Ok

Ok

(No. HP.

Keterangan : Lembar 1 untuk Teknisi; Lembar 2 untuk User; Lembar 3 Arsip Kantor

(No. HP.

)