

Corrective and Preventive Action (CAPA) Report

CAPA Reference: CAPA-2026-002 | Related Defect: DEF-003 | Owner: Anjali Thomas

Problem Statement

Incoming high-brightness LED chips from KeralaLED Components (SUP-01) batch received under GRN-4012 showed luminous output readings below the rated 100-110 lm specification, affecting 320 units.

Root Cause

Investigation identified a binning inconsistency at the supplier's chip-sorting stage following a recent production-lot changeover.

Corrective Action

Affected batch quarantined and returned to supplier via Return Note RN-014. Replacement batch requested with an additional pre-shipment luminous-output test certificate.

Preventive Action

Supplier required to submit a pre-shipment Certificate of Conformance including luminous-output test results for all future shipments. Incoming Inspection SOP updated to include a luminous-output spot-check for LED chip receipts.

Status

Closed - verified effective over next 3 shipments with zero luminous-output deviations.