

AutoClarity

Comprehensive Multi-Point Pre-Purchase Inspection

Report #: SAMPLE-0000 (demo) | Inspector: Faheb Brown, Founder & Lead Technician

6.5

Overall condition score (out of 10)

Recommendation: Negotiate / Repair First

Inspection overview

A sound, well-optioned example that presents well and shows no evidence of prior collision repair. Two items should factor into your offer: rear tires near their wear limit and a minor valve-cover oil seepage. Nothing observed indicates an immediate safety hazard. Addressing the noted items and negotiating accordingly is reasonable.

Vehicle details

Year/Make/Model	2019 Chevrolet Corvette	Trim	Stingray (demo)
VIN	1G1YY..00000 (fictional)	Odometer	28,450 mi (demo)
Location type	Private seller	Inspection date	Demonstration

Immediate safety concerns

None observed at the time of inspection.

Major findings

PRIORITY	Rear tires near wear limit [\$500-\$900] Both rear tires measured ~3/32". Serviceable now but replacement should be budgeted soon; date codes indicate ~5-year-old tires.
-----------------	---

Moderate findings

MODERATE	Valve-cover oil seepage (driver side) [\$250-\$600] Light seepage observed; no active dripping or low-oil condition. Monitor; reseal if it progresses.
MODERATE	Front bumper stone chips & light curb rash on one wheel [\$150-\$400] Cosmetic only; noted for negotiation. No structural concern.

Maintenance observations

- NOTE** **Brake fluid slightly dark** [\$100-\$180]
Due for a flush based on appearance; inexpensive routine service.
- NOTE** **Cabin air filter dirty** [\$20-\$60]
Minor; owner-serviceable item.

Tire & brake measurements

Front tires	6/32" & 6/32"	Rear tires	3/32" & 3/32"
Front brake pad	~7 mm	Rear brake pad	~6 mm
Rotors	Within limits	Tire age (approx.)	~5 years

Visible leaks & fluids

Minor valve-cover seepage as noted above. Coolant, transmission and power-steering: no visible leaks; fluid levels and condition acceptable.

Body & paint observations

Paint-depth spot checks were consistent across panels; no evidence of prior collision repair or repaint observed. Panel gaps uniform. Glass free of cracks; minor rock chip on windshield outside the driver's line of sight.

Road-test observations

Cold start normal. Idle steady. Transmission shifted cleanly through the range under light and moderate load. No abnormal noises, vibration, or pulling. Brakes firm and straight. Climate control functioned in all modes. (Road test performed with seller permission in this demonstration.)

Underbody review & limitations

Underbody inspected to the extent safely and physically possible at the location. A full lift inspection was not performed. Visible undercarriage areas showed no structural damage, active leaks, or crash residue. If deeper access is needed and appropriate, a suitable facility may need to be arranged in advance and confirmed in the quote.

Photographic findings

Your real report includes clear photographs of every meaningful finding (rear tire tread, valve-cover seepage, bumper chips, wheel curb rash, odometer, and the VIN plate).

Estimated repair-cost ranges & negotiation considerations

Priority + moderate items total roughly \$900-\$1,900 in the near term (rear tires being the main driver). These are reasonable, documented points to raise with the seller. None are deal-breakers on their own for a vehicle that otherwise presents well.

Inspection limitations

This inspection is a professional opinion of the vehicle's observable condition at the time of inspection. It is visual and non-invasive unless expressly stated; components are not disassembled. Hidden, intermittent, or future failures may not be detectable. Seller access and location can limit what is possible. A pre-purchase inspection is not a warranty or guarantee, and the buyer retains the final purchasing decision.

Inspector

Faheb Brown - Founder & Lead Technician, AutoClarity. 11+ years of hands-on automotive experience. Every Las Vegas inspection currently performed personally by the founder.