



Report No.: FR532814

Appendix A. Test Photos

Conducted Test



Conducted Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A5

Report Version

: Rev. 01



Conducted Test

Report No.: FR532814

SPORTON INTERNATIONAL INC. Page No. : A2 of A5 TEL: 886-3-3273456 Report Version : Rev. 01


FAX: 886-3-3270973






Report No.: FR532814

Radiated below 1GHz Test



Radiated below 1GHz Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A5

Report Version


: Rev. 01






Report No. : FR532814

Radiated above 1GHz Test



Radiated above 1GHz Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A4 of A5

Report Version

: Rev. 01





SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A5 of A5

Report No.: FR532814

Report Version : Rev. 01