


Appendix A. Test Photos

Conducted Test



Conducted Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A5

Report No. : FR493017

Report Version : Rev. 01



Conducted Test

SPORTON INTERNATIONAL INC.
TEL: 886-3-3273456

FAX: 886-3-3270973

Page No. : A2 of A5
Report Version : Rev. 01


Report No. : FR493017






Report No.: FR493017

Radiated below 1GHz Test



Radiated below 1GHz Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A5

Report Version


: Rev. 01






Report No. : FR493017

Radiated above 1GHz Test



Radiated above 1GHz Test



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A4 of A5

Report Version

: Rev. 01



FCC Test Report No.: FR493017



SPORTON INTERNATIONAL INC.
TEL: 886-3-3273456

FAX: 886-3-3270973

Page No. : A5 of A5
Report Version : Rev. 01