

ITC Engineering Services

Over 20 years experience in Compliance Testing and Engineering Consulting Services

April 4, 2014

To: TIMCO

Re: Submission for RondoMotion, Ref: TIMCO Job #414UC14

Please find attached the following responses to TIMCO response communication dated 04/02/2014: SUBJECT: TIMCO-TCB/Request for additional info - DYSONICS, INC. – FCC ID: 2AA7UDYSRM001 - JOB #: 414UC14:

- 1) This Transmittal Letter
- 2) **Question #1**: **TEST REPORT**: Pages 9, 11, 12: As per KDB 460108, the use of a monopole (rod) antenna for radiated emission measurements below 30 MHz is not allowed. For radiated emission measurements below 30 MHz, the FCC requires the use of a loop antenna. Please use a loop antenna for these measurements.

Response: Loop antenna was used for re-test; data and results are in updated test report, pages 9 through 11, attached as exhibit.

3) 731 Form is attached, with updates on Items 10 and 13, per recent test report updates.

We look forward to your response.

Sincerely,

ITC ENGINEERING SERVICES, INC.